

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

99
 $\frac{1}{4}$ Corner to Section 1 only, T30-2W.
 Found - 14" W.Oak S.70°W. 4.0 ft., found old axe work. - No trace N.W. BT.
 12x10x8 Basalt Stone, firmly in ground, " $\frac{1}{4}$ " on W. face.
 Set - Brass Cap at $\frac{1}{4}$ Cor.Mkd: County Surveyor's R T 30 S R
 Office 2 S 1 | $\frac{1}{4}$ 1
 1968 W S 1 | $\frac{1}{4}$ W
 New BT's: 5" D.Fir N.71 $\frac{1}{2}$ ° W. 9.6 ft. mkd. $\frac{1}{4}$ S1 CS BT.
 10" W.Oak S.46 $\frac{1}{2}$ °W. 20.0 ft. mkd. $\frac{1}{4}$ S1 CS BT.
 Note - This corner lies 81.2 ft. south of $\frac{1}{4}$ Cor. Sec. 6 only, T30-1W.

FD. 7/73 HAINES
SEE GIS FILE

100
 Sec. Cor. to Sections 1 and 12 only, T30-2W.
 Found - Stone at Section Corner.
 15", now 25" D.Fir, S.24°W. 19.8 ft., shows good scar.
 16", now 22" Dbl. D.Fir, N.55°W. 25.1 ft., shows good scar.
 Set - Brass Cap at Sec.Cor.Mkd: County Surveyor's R T 30 S R
 Office 2 S 1 | S 7 1
 1968 W S 12 | S 7 W
 Old Bearing Trees O.K., Tagged Same.
 Note - This corner lies 50.8 ft. S. of Sec.c.Cor. Secs. 6 & 7, T30-1W.

FD. 7/73 HAINES
SEE GIS FILE

101
 Sec. Cor. to Sections 6 and 7 only, T30-1W.
 Found - Stone at Section Corner. - N.E. BT. down & rotten.
 30", now 39" D.Fir, S.80°E. 66.0 ft., bark scribe visible.
 Set - Brass Cap at Sec.Cor.Mkd: County Surveyor's R T 30 S R
 Office 2 S 1 | S 6 1
 1968 W S 1 | S 7 W
 New BT's: 9" D.Fir S.71°E. 30.4 ft. mkd. T30S RLW S7 CS BT.
 14" Cedar N.66°E. 35.1 ft. mkd. T30S RLW S6 CS BT.
 Note - This corner lies 50.8 ft. N. of Sec. Cor. 1 & 12, T30-2W.

John M. Powell
 Frank Jones & W. Penley
 January and February, 1968
 C. S. File No. 54/59

102
 Sec. Cor. to Secs. 30 & 31, T30-1W. & Secs. 25 & 36, T30-2W.
 Found - 36", now 40" D.Fir, S.45°E. 5.3 ft., bark scribe visible,
 good scar for BT.
 18" D.Fir, now blow down, N.25°W. 12.2 ft.
 No trace of N.E. or S.W. BT's.
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office 2 S 25 | S 30 1
 1968 W S 36 | S 31 W
 New BT's: 11" W.Fir N. 4° W. 47.5 ft. mkd. T30S R2W S25 CS BT.
 15" Yew N. 37° E. 61.0 ft. mkd. T30S RLW S 30 CS BT.
 12" Yew S. 50° E. 49.0 ft. mkd. T30S RLW S31 CS BT.
 No trees available in S.W. Quad.

RE-RENEWED, SEE CORNER NO. #234

103
 $\frac{1}{4}$ Corner to Sec. 13, T30-2W. & Sec. 18, T30-1W.
 Found - 38" D.Fir S.10°E. (Rec.S10W) 5.3 ft., faint bark scribe " $\frac{1}{4}$ ".
 Tree opened before, "BT" visible. See ~~Ren. #19~~
 48" D.Fir, now stump, S.50°W. (Rec.S50E) 7.9 ft.
 Find no other trees in area close to matching. Calls on S. Umpqua
 fit good. Renew by using reverse bear. & Orig. dist.
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office, 1968 2W $\frac{1}{4}$ S 13 | S 18 1W
 Reblzd.&Rescbd: 38" D.Fir S.10°E. 5.3 ft. mkd: $\frac{1}{4}$ S18 CS BT.
 New BT: 12" R.Fir N. 30° W. 10.8 ft. mkd. $\frac{1}{4}$ S13 CS BT.
 June, 1968

104
 Sec. Cor. to Secs. 18 & 19, T30-1W. and Secs. 13 & 24, T30-2W.
 Found - Stone at section corner, 6 x 8 x 18.
 Orig. 8" D.Fir, now stob, S.14°E. 7.9 ft., old axe work, "B" visible.
 Orig. 9" D.Fir, now rotten stump & hole, N.75°W. 8.6 ft.
 20" D.Fir S.53 $\frac{1}{2}$ °E. 14.8 ft., bark scribe visible "T30S RLW S19 CS BT". #209
 18" D.Fir S.79 $\frac{1}{2}$ °W. 19.4 ft., bark scribe visible, See Ren. #19.
 24" D.Fir N.56°E. 20.0 ft., bark scribe visible, possible O.B.T.
 24" D.Fir N.62 $\frac{1}{2}$ °W. 48.2 ft., bark scribe visible.
 Set - Brass Cap at Cor.Mkd: County Surveyor's R T 30 S R
 Office 2 S 13 | S 18 1
 1968 W S 24 | S 19 W
 Note - Bearing Trees all in good condition, O.K. and Tagged.

RE-RENEWED, SEE CORNER NO. #209