

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 8 and 9 only. #241 111
 Found - No trace of Corner Stone or N.W. Bearing Tree.
 7" Fir, down & burnt, N.24°E. 13.2 ft., opened for scribe, "T"
 and other marks.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
 Office S 8 | S 9
 1968 S 16
 New BT's: 10" D. Fir N.56°W. 65.0 ft. mkd: T30S R2W S8 CS BT.
 8" D. Fir S.25°W. 17.0 ft. mkd: T30S R2WS16 CS BT.
 No other trees available.
 This corner lies 115.5 ft. East of cor. to Sections 17 & 16, see below.

South $\frac{1}{4}$ Corner to Section 9 only. 113 ~~112~~
 Found - No trace of corner stone called for.
 Orig. 15", now 29" R. Fir, alive, N.32°E. 22.4 ft., open & find scribe.
 Rescribe: " $\frac{1}{4}$ S 9 CS BT."
 N. W. Orig. BT. turned out & lying face down.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
 Office, 1968 $\frac{1}{4}$ S 9
 New BT: 14" Cedar N.83°W. 18.4 ft. mkd: " $\frac{1}{4}$ S9 CS BT".
 This corner lies on moderate northerly slope.
 Note - Chaining from the S. $\frac{1}{4}$ 9, we find no trace of N. $\frac{1}{4}$ Sec. 16, due
 to cat logging. 10/11/68

$\frac{1}{4}$ Corner to Section 15 only. 113A
 Found - 15x12x8 Stone, mkd: " $\frac{1}{4}$ ".
 18", now 24" D. Fir, S.40°W. 14.5 ft., shows good scar.
 8", now down, Laurel, S.15 $\frac{1}{2}$ °E. 29.7 ft., scribe visible.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R2W
 Office $\frac{1}{4}$ S 15
 1968
 New BT: 9" D. Fir S. 10° W. 50.5 ft. mkd: $\frac{1}{4}$ S15 CS BT.
 This corner lies 8.0 ft. south of E. - W. fence line.

$\frac{1}{4}$ Corner to Section 10 only. 114
 Found - 14x12x6" Stone, mkd: " $\frac{1}{4}$ ".
 9" Cedar, now stob, N.40°W. 36.3 ft., tree opened "BT" visible.
 7" Laurel, now burnt stump, N.69°E. 22.4 ft., shows burnt face.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R2W
 Office $\frac{1}{4}$ S 10
 1968
 New BT's: 6" D. Fir N.27°E. 3.2 ft. scribed $\frac{1}{4}$ S10 CS BT.
 8" D. Fir N.27°W. 45.8 ft. mkd: $\frac{1}{4}$ S10 CS BT.
 This corner lies 15.0 ft. south of E-W Fence Line.

$\frac{1}{4}$ Corner to Section 35 and 36. 115
 Found - 24" D. Fir, now stump, N. 26° E. 11.2 ft.
 24" D. Fir, now down, N.14°W. 11.9 ft., tree badly splintered
 and torn apart to find scribe of "BT".
 Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R2W
 Office, 1968 $\frac{1}{4}$ S 35 | S 36
 New BT's: 11" R. Fir S.51°E. 13.0 ft. mkd: $\frac{1}{4}$ S36 CS BT.
 10" R. Fir N.62°W. 15.2 ft. mkd: $\frac{1}{4}$ S35 CS BT.

Section Corner to Sections 25 - 26 - 35 - 36. 116
 Found - 30", now 38" D. Fir, N.60°E. 8.6 ft., shows good scar.
 18" D. Fir, now stump, S.30°E. 43.6 ft., opened for scribe "BT".
 No trace of N.W. or S.W. BT's., skid road.
 Unrecorded D. Fir, now stump 5' high, 1.0 ft. N. of corner,
 faint bark scribe on S.E. side, T30S R2W S36, possible start of
 corner tree, then not used.
 Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R2W
 Office S 26 | S 25
 1968 S 35 | S 36
 New BT's: 6" Y. Pine S.24°E. 33.4 ft. mkd: T30S R2W S36 CS BT.
 13" D. Fir S. 3° E. 20.9 ft. mkd: T30S R2W S36 CS BT.
 13" D. Fir N. 59° W. 73.5 ft. mkd: T30S R2W S26 CS BT.
 Note - No good trees close in Southwest. 10/25/68

John M. Powell
 Frank Jones & W. Penley
 October, 1968
 C. S. File No. 54/73

SEE INSERT
 FOR #112

RE-RENEWED, SEE CORNER NO. #241

RE-RENEWED, SEE CORNER NO. #231

RE-RENEWED, SEE CORNER NO. #256

74 - Per Field Notes -
 compare
 1/18/68 R.