

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

123

$\frac{1}{4}$  Corner to Sections 18 and 19.  
Found - 40", now 54" Cedar, Corner Tree, shows good scars.  
24" D. Fir, now snag, S. 62° E. 22.4 ft., opened for scribe.  
No trace of N. E. BT.  
Set - Brass Cap on N. side of Cor. Tree Mkd: County Surveyor's T30S R2W  
Office 1968  $\frac{1}{4}$   $\frac{S 18}{S 19}$   
New BT's: 13" Maple S. 24° W. 31.4 ft. mkd:  $\frac{1}{4}$  S19 CS BT.  
9" D. Fir N. 20° W. 18.7 ft. mkd:  $\frac{1}{4}$  S18 CS BT.

**RE-RENEWED, SEE CORNER NO. #266**

124

$\frac{1}{4}$  Corner to Section 30 only.  
Found - 18" D. Fir, now down, S. 25° E. 19.8 ft., opened for scribe, "T".  
12" Laurel, now 14" & broken, S. 22° W. 21.1 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W  
Office 1968  $\frac{1}{4}$   $\frac{S 30}{S 30}$   
New BT's: 6" Y. Pine S. 4° W. 8.1 ft., mkd: S30  $\frac{1}{4}$  CS BT.  
5" D. Fir S. 35° E. 6.4 ft., mkd:  $\frac{1}{4}$  S30 CS BT.  
This corner lies 68.0 ft. west of  $\frac{1}{4}$  corner to Section 19, see cor. below.

*Fd ok  
2/18/68 Howard Johnson  
M 100-21*

125

$\frac{1}{4}$  Corner to Section 19.  
Found - 12" D. Fir Corner Tree, now rotten stump.  
24" D. Fir, now snag, N. 6 $\frac{1}{2}$ ° E. 5.3 ft., scribe visible.  
10" D. Fir, now 8' Stob, N. 30° W. 6.9 ft. (Rec. 9.9), scribe visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W  
Office, 1968  $\frac{1}{4}$   $\frac{S 19}{S 19}$   
New BT's: 15" D. Fir N. 47° W. 7.8 ft. mkd:  $\frac{1}{4}$  S19 CS BT.  
29" D. Fir N. 43° E. 46.8 ft. mkd:  $\frac{1}{4}$  S19 CS BT.  
This corner lies 68.0 ft. East of  $\frac{1}{4}$  Corner Sec. 30, see above.

*Fd ok  
12/15-2/16  
H. Johnson  
M 100-21*

10/30/68

126

$\frac{1}{4}$  Corner to Section 31 only, T29-2W.  
Found - GLO Brass Cap at  $\frac{1}{4}$  Cor. properly marked in 1917.  
30", now 38" D. Fir, N. 32 $\frac{1}{2}$ ° W. 19.8 ft., shows good scar.  
20" D. Fir, now down, N. 8 $\frac{1}{2}$ ° E. 12.5 ft.  
New BT: 20" D. Fir N. 30° E. 25.1 ft. mkd:  $\frac{1}{4}$  S31 CS BT.  
This corner lies 100 ft. west of  $\frac{1}{4}$  cor. Sec. 6, T30-2W., see below.

**RE-RENEWED, SEE CORNER NO. #257**

11/13/68

127

$\frac{1}{4}$  Corner to Section 6 only, T30-2W.  
Found - 12" D. Fir, now rotten stump, S. 2° E. 13.2 ft., found scribe.  
6", now 8" Laurel, S. 40° W. (Rec. S40E) 2.3 ft., rotten face.  
Stone at  $\frac{1}{4}$  corner approx. size marked + on top.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W  $\frac{1}{4}$   $\frac{S 6}{S 6}$   
Office, 1968 T30S  
New BT's: 5" D. Fir S. 41° E. 17.4 ft. mkd:  $\frac{1}{4}$  S6 CS BT.  
30" D. Fir S. 35° W. 18.9 ft. mkd;  $\frac{1}{4}$  S6 CS BT.  
This corner lies 100 ft. east of  $\frac{1}{4}$  corner sec. 31, T29-2W, see above.

*Fd. ok  
11/11/68  
H. Johnson  
M 97-65*

128

Section Corner to Sections 31 and 32, T29-2W.  
Found - No trace of Corner Stone.  
10", now 15" D. Fir, N. 6 $\frac{1}{2}$ ° E. 13.9 ft., shows good scar.  
20", now 25" D. Fir, N. 38° W. 35.6 ft. scribe visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W  $\frac{S 31}{S 6}$   $\frac{S 32}{S 6}$   
Office, 1968 T30S  
New BT: 11" D. Fir S. 2° E. 18.8 ft. mkd: T30S R2WS6 CS BT.  
This corner lies 73.9 ft. west of Cor. Secs. 6 and 5, T302W, see below.

129

Section Corner to Sections 5 and 6, T30-2W.  
Found - Stone at Sec. Cor., approx. size, no marks found.  
24", now 26" D. Fir, S. 27° E. 11.9 ft., shows good scar.  
30", now 34" D. Fir S. 16° W. 30.4 ft.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T29S R2W  $\frac{S 32}{S 6}$   $\frac{S 32}{S 5}$   
Office, 1968 T30S  
New BT; 8" Cedar N. 34° E. 16.1 ft. mkd: T29S R2W S32 CS BT.  
This corner lies 73.9 ft. east of Sec. 31 & 32, T29-2W., see above.  
(Record Dist. Chained)

John M. Powell  
Frank Jones & W. Penley  
November & October, 1968  
C. S. File No. 54/73