

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

John M. Powell
Jack Heritage & W. Penley
December, 1968 C. S. File No. 54/73

169

$\frac{1}{4}$ Corner to Sections 16 and 21.
Found - 18", now 30" Fir Corner Tree, shows good scars.
24" Fir, now stump, N.47 $\frac{1}{2}$ °W. 41.6 ft., shows scar.
36" Cedar, now stump, S.66 $\frac{1}{2}$ °W. 49.5 ft., tree opened, scribe visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office 1968 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{16}{21}$
New BT: 17" D.Fir N.20°W. 23.3 ft. mkd: $\frac{1}{4}$ S16 CS BT.
16" B.Fir S. 5° E. 33.3 ft. mkd: $\frac{1}{4}$ S21 CS BT.

12/5/68

170

Section Corner to Sections 28 - 29 - 32 - 33. *FD OK 2/94 BY BECKLEY M121-55*
Found - 18"xl8" Stone & 1 $\frac{1}{2}$ " I. Pipe at Corner, See Ren. #73.
Orig. 36" D.Fir, now stump, N.31°E. 53.5 ft.
Orig. 20" D.Fir, now stump, N.65 $\frac{1}{2}$ °W. 47.5 ft., opened for scribing.
Orig. 24" D.Fir, now snag, S.50°W. 4.6 ft., shows good scar.
Orig. 30" D.Fir, now down, S.72°E. 10.6 ft., shows good scar.
No trees available for Bearing Trees in burnt area.
Set - 2, 6' steel fence posts. East 8.0 ft. and 16.5 ft.
This corner lies on top of small ridge about 15.0' East of old down fence line, running N. & S.

171

$\frac{1}{4}$ Corner to Sections 28 and 29.
Found - Orig. 10", now 21" W.Oak, N.3°E. 75.9 ft., opened for scribe.
Orig. 15", now 24" W.Oak, N.18°W. 69.3 ft., shows good scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office, 1968 $\frac{1}{4}$ S 29 | S 28
New BT's: 24" D.Fir S.88°W. 19.2 ft. mkd: $\frac{1}{4}$ S29 CS BT.
10" W.Oak N.25°E. 36.7 ft. mkd: $\frac{1}{4}$ S28 CS BT.

172

Section Corner to Sections 20 - 21 - 28 - 29.
Found - Orig. 10", now 17" D.Fir, N.76°W. 23.8 ft., shows good scar.
Orig. 12" Laurel, now down, S.60°W. 17.2 ft., found reverse scribing not enough to call letters & rotted.
Orig. 24" D.Fir, now down, S.4°E. 20.5 ft., rotted.
Orig. 15" Laurel, now snag, N.45°E. 33.0 ft., shows faint scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office 1968 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{20}{29}$ | $\frac{S}{S}$ $\frac{21}{28}$
New BT's: 6" D.Fir S.58°W. 35.6 ft. mkd: T30S R2W S29 CS BT.
9" Cedar S.70°E. 32.6 ft. mkd: T30S R2W S28 CS BT.
19" D.Fir N.64°E. 36.0 ft. mkd: T30S R2W S21 CS BT.
Note - Corner Stone not found.

RE-RENEWED, SEE CORNER NO. #277

173

$\frac{1}{4}$ Corner to Sections 17 and 20.
Found - Quartz Stone, approx. size, out of ground, no marks.
15", now 20" Hemlock, N.64 $\frac{1}{2}$ °W. 8.6 ft., shows good scar.
6" Hemlock, now down, S.80°E. 38.9 ft., opened for scribe $\frac{1}{4}$ S20 BT"
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office 1970 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{17}{20}$
New BT: 18" Hemlock S.59°W. 48.7 ft. mkd: $\frac{1}{4}$ S20 CS BT".
Rebzd. & Resbd: 20" Hemlock N.64 $\frac{1}{2}$ °W. 8.6 ft. mkd: $\frac{1}{4}$ S17 CS BT.

4/15/70

174

Section Corner for Sections 30 & 29.
Found - Corner stone, approx. size, firmly in ground, 38.3 ft. west of Quartz Stone for Sections 19/20.
No Bearing Trees found.
This & another stone I found a year ago. This year Rsbgr. Lumber chained to them from the N. & E. Everyting points to these stones as the corners.
Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office 1970 $\frac{1}{4}$ $\frac{S}{S}$ $\frac{19}{30}$ | $\frac{S}{S}$ $\frac{19}{29}$
New BT's: 10" Yew S. 35° W. 20.8 ft. mkd: "T30S R2W S30 CS BT".
14" Hemlock South 10.8 ft. mkd: "T30S R2W S29 CS BT".

FD OK 12/177-2/86 H-Johnstone M100-21 6/29/70