

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

175

Closing Corner to Sections 19 and 20 only.
Found - Broken Quartz Stone at Closing Corner. No trace of BT's.
I found these stones approx. a year ago, & since then Rsbgr. Lumber
has chained from the N. & E. to these points. Everything points to
this being the correct position for corners.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office CC S 19 | S 20
1970 S 29

New BT's: 7" D. Fir N. 65 W. 24.0 ft. mkd: "T30S R2W S19 CC CS BT".
6" D. Fir S. 15 E. 18.7 ft. mkd: "S29 CS BT".

No other trees available to the N.E.

This corner lies 38.3 ft. E. of Cor. S 30/S29, See Ren. #174.

*Fd OK 12/185-2/84
H. Johnstone
6/29/70 M100-21*

North $\frac{1}{4}$ Corner to Sections 29 only.

Found - Stone at $\frac{1}{4}$ Corner, no marks visible.

24" Laurel, now snag, S.40°W. 5.9 ft., opened for scribe.

5" Laurel, now stump, S.10°E. 5.3 ft.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office $\frac{1}{4}$ S 29
1970

New BT's: 16" D. Fir S. 65°W. 27.0 ft. mkd: " $\frac{1}{4}$ S29 CS BT".

8" Laurel S.12°W. 34.2 ft. mkd: " $\frac{1}{4}$ S29 CS BT".

This corner lies 15.1 ft. West of $\frac{1}{4}$ Corner Sec. 20 only. (Rec. 27.7)

6/29/70

176

$\frac{1}{4}$ Corner to Section 20 only. (South Boundary)

Found - 8", now 14" Cedar, N. 17° W. 7.3 ft., tree opened, reverse
scribe found, "B".

14", now 26" Laurel, N. 6° E. 26.4 ft., shows scar but rotted out.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office $\frac{1}{4}$ S 20
1970

New BT's: 36" D. Fir N. 10° W. 10.1 ft. mkd: " $\frac{1}{4}$ S20 CS BT".

36" D. Fir N. 76° E. 41.9 ft. mkd: " $\frac{1}{4}$ S20 CS BT".

This corner lies 15.1 ft. East of $\frac{1}{4}$ Corner Section 29 only, (Rec. 27.7)

6/29/70

177

East $\frac{1}{4}$ Corner to Section 20 only.

Found - No trace of Corner Stone nor S. W. Bearing Tree.

72", now 76" D. Fir, N. 62° W. 47.5 ft., opened for scribe "B".

Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office, 1970 $\frac{1}{4}$ S 20

New BT: 6" D. Fir N. 14° W. 51.1 ft. mkd: " $\frac{1}{4}$ S20 CS BT".

6/30/70

178

$\frac{1}{4}$ Corner West Side Section 21 only.

Found - 15x12x6" Stone, firmly in ground at $\frac{1}{4}$ corner, with chisel
marks on east face.

48", now 58" D. Fir, N. 50°E. 15.2 ft., shows good scar.

16", now 20" D. Fir, S. 78°E. 9.9 ft., shows good scar.

Set - Brass Cap at Cor. Mkd: County Surveyor's T 30 S R 2 W
Office, 1970 $\frac{1}{4}$ S 21

All Bearing Trees O. K. and Tagged.

6/30/70

179

$\frac{1}{4}$ Corner to Sections 23 and 24.

Found - 1963 Cadastral Brass Cap, in place & properly marked.

At this time we remove the Co. Surveyor Brass Cap set for

Witness Corner, See Ren. #45.

From this corner, B.B.I. 1940 BT, 10" W. Oak bears N. 49°W. 68.4 ft.,
this tree alive, and shows scar.

Cadastral BT's. alive & in good condition, as follows:

16" Y. Pine N. 71 $\frac{1}{2}$ °E. 86.5 ft., alive, scribe visible, This BT to
be removed in land clear.

13" Cedar S. 6 3/4° W. 19.8 ft., alive, blaze healed, tagged.

New BT: 12" D. Fir S. 44° E. 30.8 ft. mkd: " $\frac{1}{4}$ S24 CS BT".

The Pine BT. for W.C., Ren. #45, bears N. 59 3/4°E. 46.9 ft. and
will also be removed in land clear. The Cadastral $\frac{1}{4}$ corner lies about
1200' S. of S. Umpqua Rd., See C.S. File 55/52.

8/10/70

180

John M. Powell
W. Penley & J. Heritage
June, 1970 C. S. File No. 54/73

RE-RENEWED, SEE CORNER NO. #249

*CORNER LOST
DUE TO SLIDE
Visited 7/21/83
Doug. Co. Surveyor Office
L. Mansueti, Deputy
C.S. 62/19
Landed For, Noted.
2/22/91 C.S. 64/13*

MARCH 71