

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

2

R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

190

Vic. Cangie
Clell E Goodwin
M. Lenora Ladig
CS 57/39
12/17/75

1/4 Corner to Sec. 16 & 15 REN #61
Found- 1" x 1" angle iron set by Markham (Ren # 61) in place at the corner
From Which- we find the remains of the only existing orig. BT , a rotten
stump with scribing "BT" visible on rotting face bears S 20°E.,3.3 ft.
The Original NW bearing tree is gone. We find Markhams bearing trees as
follows: A 24" Incense cedar (Rec.30" Dia.) alive with scribing partially
visible on unhealed blaze bears S 35°W.,40.7ft.(Rec.S 32°W.,40.7 ft.)
A 17" D.Fir (rec.18" Dia.),alive with scribing visible on partially healed
blaze bears N 81 1/2°E.,31.5 ft.(Rec. N80°E.,33.0 ft.)
A 45" D.fir (rec.50"dia.) with bark scribing visible, bears S 35°E.,20.1 ft.
(Rec.S 35°E.,21.7 ft.) At the corner point, we
Set- 1" x 30" iron pipe, with Brass cap attached marked:

DOUGLAS CO. SURVEYOR
1975

T	30	S	R	2	W
		S	16	S	15
			1/4		

We place angle iron alongside brass cap.
Note: This corner is located in a N-S fence line approx. 150 ft. west of
BLM Rd #30-2-14.0. Com pass Dec. 20° E. 12/17/75

L.E. Monrean
M.L. Ladig
C.S. 57/39
12/31/75

Sec. Corner to Sec. 28,27,33 and 34 REN. #3
Found- 3x3x20" granite stone marked as recorded in Ren. #3. Stone is dislodged
with top (x) facing westerly. Stone dislodged by falled tree.(also found
3/4 " bolt beside stone, loose)

BT's-Orig. fir 12" now 30" dia.bears S20°E.,18.5 ft. Tree has old blaze, I
open and find orig. scribing "BT"
A fir 20" now 23" dia. bears N42°E.,30.0 ft. to center 29.1 ft.to face
(rec. N43 1/2°E) Tree is bark scribed "T30S R2W S27 BT"
A fir 30" now 31" dia. bears N 30°W.,22.5 ft. to center, 21.0 ft. to face
(Rec. N37°W.,20.0 ft. tree is bark scribed "T30S R2W S28 C"
A fir, 30" dia. bears approx. S53°W.,47.0 ft. tree is uprooted, has old
blaze. (ren #85)
A fir stump 30" dia. bears S 10°W.,38.6 ft.(Rec. S5°W). Stump is scribed
"S 33 T30S R2W BT".(Not of Record)A rotted fir stump approx. 15" Dia.
bears S54 1/2°W.,16.7 ft. Stump scribed "BT" Note. No other bearing trees
found.

Set- Brass cap at sec. corner stamped

COUNTY SURVEYORS OFFICE
1975

T	30	S	R	2	W
		S28	S27		
		S33	S34		

Stone marked And bolt alongside cap. Note no new BT's scribed.Mag.Dec.20°E.
12/31/75

Clell Goodwin
Gary Langlitz
Vic Cangie
Lenora Ladig.
C.S. 57/39
12/17/75

South Sec. corner commom to Sec. 9&10 Ren#49
Found- 3/4" x 30" IP and a 15"x10"x6" stone with 3 notches on the east side
buried alongside.
Orig.30" cedar now a 36" I Cedar bears N 70°W.,21.0ft.
Orig.48" fir now a 53" D.Fir stump bears N 60°E.,18.5 ft. and Markham's trees
scribed in 1960 as follows:

11" G. fir with visible scribe marks bears S38°E.,15.0 ft.

14" G Gir well healed bears S 64°W.,21.6 ft.

9" I cedar with visible scribed marks bears N 7°W.,23.0 ft.

Set- 1"x30" IP with brass cap stamped:

DOUGLAS CO. SURVEYOR
1975

T	30	S	R	2	W
		S	9	S	10
			S15		

Set- the found pipe to the South and the stone to the north of the corner.
This corner lies 400+ west of Dompier Cr. Rd. in a fence running E-W
Compass declination 20° East 12/17/75

FO. OK 4-25 BY
NYGREN M121-76

12/18/75

Sec. Corner to Sec. 12 & 13 T30-2 and Sec. 7 & 18 T30-1 193 REN#35
Found-A stone, firmly set 18"x10"x5" mkd. with 4 notches on the south side,
and at least 1 notch on the north. Markham's 1958 3/4x24" I pipe is set
alongside the stone, from which two remaining orig. BT's are located
Orig. 15" now 22" D fir alive and well-healed bears S44°W.,23.8 ft.,
(Rec. S 48°W.,23.8 ft.)
Orig. 6" now 17" D fir, alive and well-healed, bears N34°W.,20.5 ft.(Rec.N30°
W.,20.5 ft)
15" now 35" sugar pine marked during a subsequent Gov. resurvey, alive and in
good condition, bears N 18°E.,25.7 ft. BT's mkd. by Markham in 1958 are
A 5" now 7" chinguapin, alive scribing visible on rotting face bears S88°W.,
17.0 ft.(Rec. N87°W.,17.0 ft.

CONTINUED ON NEXT PAGE