

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30 T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21001

Glenn S. Baughman
OLS #536
For: U.S. Forest
Service
May 1978
M 70 - 15

211

Section Corner for Secs. 24 and 25; and 19 and 30 of T30-1
Found - 1968 Brass cap set by Baughman and Ackaret. Ren. #107
8" Chinquapin bears S.36°W., 23.5 ft.
6" W. Fir bears S.23°E., 46.0 ft. (down)
26" D. Fir bears N.56°E., 22.4 ft.
9" Maple bears N.20°W., 6.2 ft.
New BT - 10" D. Fir bears S.52°E., 69.4 ft. scribed T30S R1W S30 BT.

212

1/4 Corner for Secs. 25 and 36.
Set - 2" x 30" I.P. with brass cap marked T30S R2W WM 1/4 S25 S36
1978 OLS 536.
BT's - 8" D. Fir bears S.70°W., 9.0 ft. scribed 1/4 S36 BT.
8" D. Fir bears N.29°W., 5.8 ft. scribed 1/4 S25 BT.

213

1/4 Corner for Secs. 25 and 26.
Set - 2" x 30" I.P. with brass cap stamped T30S R2W WM 1/4 S26 S25
1978 OLS 536.
BT's - 8" D. Fir bears N.78°E., 30.1 ft. scribed 1/4 S25 BT.
10" W. Fir bears S.50°W., 17.3 ft. scribed 1/4 S26 BT.

Lloyd R. Moffit
For: U.S. Forest
Service
August, 1978
C.S. 58/176

214

Section corner for Secs. 31 and 32 only. South boundary.
Found - A stone 18 x 10 x 9 inches marking the south section corners.
From which: A 36" Fir bears N.23°E., 124.7 ft. scar visible.
Set - A 2" Pipe with 3" brass cap stamped: T30S R2W S31 S32 T31S R2W S6
PLS 944 1978.
New BT- A 8" Fir bears N.20°W., 15.4 ft. scribed T30S R2W S31 BT.
Note: The orig. stone is buried along side the 2" pipe. the new BT has a
brass tag #944 nailed at BT scribe.

215

Closing Corner for Secs. 6 and 5 only of T31-2.
Found - A granite stone 15" x 15" x 6" marking the closing corner.
From which:
A 36" Fir bears S.14°W., 13.2 ft. scar healed over.
A 24" Madrone (now dead) bears S.14°E., 49.5 ft. scar visible.
Set - A 2" pipe with 3" brass cap stamped: T30S R2W S32 S6 S5 CC
T31S R2W PLS 944 1978.
New BT - A 8" Fir bears S.53°E., 21.8 ft. scribed T31S R2W S5 BT.
Note - The orig. stone is buried along side the 2" pipe. The new BT
has a brass tag #944 nailed at BT scribe.

216

1/4 Corner for Section 12 only. South
Found - 1" O.D. x 34" Iron pipe set solidly in ground. Ren. #53
Orig. BT to the NE is blown down, stump hole bears N.40°E., 5.9 ft
A 14" Cedar bears S.21°W., 36.1 ft. scribing visible, "BT 1/4
S12" on a single blaze. Ren. #53.
A 20" Cedar, bears N.47°W., 40.4 ft. scribed "1/4 S12 BT" on a
double blaze.
Brass cap for S13 only (which I renewed this A.M.) bears N.89°45'W
57.5 ft.
Set - Referencing the iron pipe, I move it aside and set in its place
a 1 1/2" I.P. with a 2 1/2" brass cap stamped "County Surveyor's
Office T30S R2W 1/4 S12 1978". I bury the 1" iron pipe along-
side the brass cap.

No new Accessories.
I placed County BT signs on both BTs. Local attraction caused by a metal
fence post setting 1.2 ft. east of the brass cap.

Dennis Gaylord, USFS
Deputy, Douglas County Surveyor
Witness: James Davis
August 30, 1978
C.S. 60/11

FD. OK 4-75 BY NYGREN M 121-76

8/30/78