

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 2 R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21661

William Ruppert, LS #866  
For: U. S. Forest Service  
April, 1979  
M 70 - 61

Glenn Baughman  
For: U.S. Forest  
Service  
July 1979  
C.S. 58/176

Bruce Shaner,  
For: U.S. Forest Serv.  
and Roseburg Lumber  
July 1980  
RM 3 - 33

1/4 Corner, Secs. 33 and 34. *FND. OK 11-92 BY H CENTER M 116-33* **223**  
*FD OK 7-94 BY G Lang M120-69*  
No monument found at corner. Corner relocated from bearing trees per  
C.S. 55/51 of County Surveyor's records, Trees now bear:  
18" D. Fir, N.18°44'E., 98.5 ft. well healed Ren. #91  
20" Cedar, N.65°11'E., 86.9 ft. scribing visible  
18" D. Fir, N.51°51'W., 111.9 ft. well healed.  
Corner relocated by intersection of distances from bearing trees per C.S.  
55/51. Corner falls in Elk Creek.

Witness corner for 1/4 Cor. for Secs. 33 and 34. *FD OK BY G Lang* **224**  
*7/94 M120-69*  
Set - Witness corner, a 2" x 30" Galv. iron pipe with 2 1/2" brass cap in  
mound of stones. Stamped "T30S R2W W.C. 1/4 S33 S34 94.77  
PLS 866 1979."  
BT's- 9" D. Fir, N.64°15'W., 58.0 ft. "W.C. 1/4 S33 BT"  
6" W. Fir S.13°39'E., 11.4 ft. "W.C. 1/4 S34 BT".

Section corner for 32 and 33 only. See Ren. #197 **225**  
Found - 5/8" Iron rod, per M56-49 Douglas County Surveyor's records, at  
uproot of large fir. (no cap).  
22" D. Fir, good scar, N.25°57'W., 33.9 ft.  
8" D. Fir scribing partly vis. N.85°44'E., 71.8 ft.

Witness corner for Section corner of Secs. 32 and 33. See Ren. #197 **226**  
Set - Witness corner, a 2" x 30" galv. iron pipe with 2 1/2" brass cap  
marked T30S R2W W.C. S32 S33 T31S 85.00 PLS 866 1979"  
BT's - 15" D. Fir, N.57°08'W., 12.5 ft. "W.C. T30S R2W S32 BT".  
6" D. Fir, S.10°21'E., 8.7 ft. "WC T30S R2W S33 BT".

Section corner for Secs. 33 and 34 and Sec. 3 and 4 of T.31-2 **227**  
Found 20" Cedar corner tree. 1" pipe with 2 1/2" brass cap bears S.45°W.  
1.3 ft. marked County Surveyors Office S33 S34 S4 S3 1966.  
24" stump very rotten S.35°52'E., 8.0 ft. See  
24" D. Fir good face S.6°22'E., 14.7 ft. Ren. #205  
20" D. Fir good face S.68°32'W. 7.3 ft.  
40" D. Fir good face N.66°35'W., 10.4 ft.  
10" D. Fir good face N.9°09'W., 32.6 ft.  
8" Cedar windfall N.36°09'W., 13.8 ft.  
Scribed new BT:  
18" D. Fir, N.62°00'E., 43.3 ft. "T30S R2W S34 BT".

Township Corner for Sec. 1; and Sec. 6 of T30-1; and Sec. 36 of T.29-2; **228**  
Sec. 31 of T.29-1  
Found - 1" iron pipe, 10" above the ground with a 2 1/2" brass cap mkd.  
"T29S R2W R1 W S36 S31 S6 S1 T30-S 1917"  
From which:  
A 22" Oak bears N.70°W., 37.0 ft. Ren. # 95  
An 18" Oak stob bears N.8°E., 47.5 ft.  
An 18" Oak stump bears S.89°E., 118.8 ft. *FD. BC 9/93*  
An 18" D. Fir bears N.44°W., 26.8 ft. *PIESKE M 117-62*  
A 16" D. Fir bears N.73°E., 17.5 ft.  
An 18" D. Fir bears S.9°E., 13.0 ft.  
A 12" D. Fir bears S.41°W., 33.0 ft.  
New BT - 10" D. Fir bears S.25°E., 38.4 ft., I marked "T30S R1W S6 BT" on  
a double blaze and nailed a brass washer stamped "LS 536" into  
lower blaze.

Center 1/4 Corner for Section 23 *FD. OK BY BROWN. APR. 1996 - M 125-2* **229**  
Set - Brass cap mkd. T30S R2W W.M. C 1/4 S23 RLS 430 1980.  
New BT's- 26" Fir, I scribed "C 1/4 S23 BT" bears N.23°W., 30.4 ft.  
10" Fir, I scribed "C 1/4 S23 BT" bears S.23°E., 30.5 ft.  
7/80