

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30 T. S. R 2 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 91881

267

South 1/4 Corner for Sec. 36 only, T.29-2
 Found - 1917 GLO 2½" brass cap on a 1" iron pipe.
 A Fir stump bears N.37°W., 31.7 ft. (to center of tree)
 Scars visible. (1917)
 A 17" Fir bears N.45°E., 11.9 ft. Scars visible. (1917)
 A rotted Fir stump bears N.51°E., 23.1 ft. Old face visible.
 Ren. No. 136.
 New BT - I marked A 12" Fir which bears N.38°E., 31.9 ft. Scribed 1/4 S36
 with L.S. Washer No. 944 nailed to BT scribe.

10/86

268

1/4 Corner for Sections 23 and 26
 Found - 1963 BLM 2" gal. iron pipe with a 3" brass cap.
 32" Fir stump, N.06°E., 16.5 ft. scribe visible. (orig)
 16" Fir bears S.44¼°E., 99.6 ft. scar visible.
 New BT - I scribed a 8" Fir BT which bears N.17°W., 30.8 ft. marked
 1/4 S23 BT, with LS 944 brass washer nailed to BT scribe.

10/86

269

South 1/4 Corner for Section 33 only.
 Found - 1966 County Surveyor's 2½" brass cap on a 1" iron pipe in a
 mound of rock. Ren. No. 198 and 80
 A 8" Hemlock (snag) which bears N.29 3/4°E., 26.2 ft.
 scribe visible.
 A 28" Fir stump which bears S.01 3/4°W., 6.6 ft. scar visible.
 A 22" Cedar (dead) which bears N.21½°W., 12.4 ft. scribe visible.
 New BTs - I marked a 28" Fir which bears N.31°E., 96.4 ft. scribed 1/4
 S33 BT.
 I marked a 24" Fir which bears N.43°W., 60.6 ft. scribed 1/4
 S33 BT.

Both new BTs have LS 944 brass washer nailed to BT scribe.

10/86

270

Section corner for Sections 5 and 4 only of T.31-2.
 Found - 1966 County 2½" brass cap on a 1" iron pipe is on south side
 of corner tree. Ren. No. 81
 Found a 42" Fir corner tree with scribe visible.
 Found remains of Fir BT, S.70 3/4°E., 17.8 ft. (steel fence post
 with signs stand where tree was.) Ren. No. 218
 Found 24" madrone which bears S.05½°W., 18.7 ft. scribe visible.
 New BT - 8" Fir which bears S.25°E., 20.1 ft. mkd. T31S R2W S4 BT with a
 LS 944 brass washer nailed to BT scribe.

10/86

271

North 1/4 Corner for Section 2 only.
 Found - 1968 County 2" brass cap on a 1" iron pipe in a rock mound.
 Ren. No. 138
 A 16" Hemlock which bears S.22°E., 15.8 ft. scar visible.
 A Fir stump which bears S.84°E., 34.4 ft. scribe visible.
 New BT - I scribed a 6" Fir which bears S.41¼°E., 35.2 ft. marked 1/4
 S2 BT with LS 944 brass washer nailed to BT scribe.

10/86

272

1/4 Corner Sections 28 and 33.
 Found - A 2½" diameter brass cap marked "T30S R2W, ¼ S28 S33
 PLS 866, 1979, Reset 1981" on a 2½" outside dia.
 iron pipe 30" long. Monument is set in a fire trail and was
 apparently disturbed by a tractor; monument leans approximately
 14" southwest from its plumb position, flush with the ground.
 Original post not found. #25
 Stone first noted in Ren. #74 not found.
 3" pipe per Ren. #74 not found. See Ren #235
 BT's - Bearings and distances taken to plumb position of brass cap.
 A 48" fir now a stump hole with remnants near original record
 bearing and distance (orig. record N36°E, 29.7 ft.) Original
 BT.
 Original southwest BT gone.
 24" now a 2 ft. high broken and burnt douglas fir stump. no blazes
 or scribing found, bears S 76°W, 101.0 ft. (rec. S 77 3/4°W, 99.5'
 per ren.#25; S 78°W, 99.5 ft. per ren.#86; S 76½°W, 101.0 ft. per
 ren.#220; S 76°W, 101.0 ft. per ren.#235) Ren. #25 BT.

CONTINUED NEXT PAGE....

Loyd R. Moffit L.S. 944
 For: U.S. Forest Service
 October 1986
 C.S. 62/30

Douglas County Surveyors
 R.W. Smith - S.J. Flause
 September 26, 1987