

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 3 R. W. W. M.

✓ SECTION CORNER 5, 6, 31 and 32. ON TOWNSHIP LINE
Set 4" x 4" x 36" Oak Post from the old B.T. Marked
New B.T.s
A Fir 30" dia. bears S.66°W., 24.5 ft.
A Fir 15" dia. bears S.30°E., 32.0 ft.

9
H.L. Eppstein
Wit.
Henry Raehor
Bill Raehor
B.A. Lane
John Busenberck
May 4, 1927.

✓ SECTION CORNER BETWEEN 30 and 31.
Location identified from three original B.T.s which I
replaced and scribe in the bark. Set a 6" x 6" x 24" white
painted rock for corner and Yew Wood post along side 3" x 6" x 24"
scribed S.30 C.S. on N.E. face and T.30S. R.3W. S.31 on
S.E. face.

10
Ben B. Irving D.C.S.
Wit.
John A. Irving
V. N. Poole
Joe Wright
Walter Poole
Feb. 18-19, 1939.

✓ 1/4 SECTION CORNER W. SIDE OF SECTION 30.
Location identified to Original B.T.s as recorded. One
only a stump the other dying. Set 4" x 4" x 36" Post for
corner. Blazed and scribed
A Fir 22" dia. N.65°E., 63 lks.
A Fir 30" dia. S.80°E., 80 lks. 1/4 S.30 C.S.B.T.

11
Ben B. Irving
Dep. Co. Surveyor
Witnesses
J. A. Irving
V. N. Poole
Walter Poole
Roy Matthews
March 7-8, 1930
C.S. 37/18

✓ 1/4 CORNER BETWEEN SECTIONS 29 and 30.
Location identified from original B.T.s. Set 6" x 6" x 48"
Yew Wood Post for corner. Remark both B.T.s.

✓ N.E. CORNER OF JACOB AMSLER D.L.C. 39.
1 1/2" x 1 1/2" Iron Bar in mound of rock. Check original
B.T.s. One standing and one down, both rotting.
New B.T.s.
A 18" Fir S.20°E., 228 lks. marked N.E. Cor. Cl. 39
C.S.B.T.
A 18" Fir S.73°W., 43 lks. marked N.E. Cor. Cl. 39
C.S.B.T.

✓ INTERIOR "L" CORNER OF CLIAM 39.
Rock on upper side of road. Checks one original B.T.
down and rotting 6" x 8" boulder X on top.
A 14" Fir N.30°W., 26 lks. marked Int. Cor. Cl. 39
C.S.B.T.
A 12" Fir N.60°E., 46 lks. marked Int. Cor. Cl. 39
C.S.B.T.

✓ S.E. CORNER OF CLIAM 39.
Location identified from stamp hole of old Oak said by
V. N. Poole to have been location of old B.T. and stump line
tree on South Line of cliam. Set a 16W drive gear from
old mower 14" under ground with 1/2" x 1" x 36" Iron Bar
driven through center.
A 12" Cedar N.80°E., 187 lks. marked S.E. Cor. Cl. 39
A 12" White Oak N.55°E., 447 lks. marked S.E. cor. Cl. 39
C.S.B.T.

✓ 1/4 SECTION CORNER ON SOUTH SIDE OF SECTION 6.
Set proportional measurement between Section Corner
A Flint Rock 4" x 6" x 20" set 18" in ground bisected T on top
and 1/2 on North face.
A 6" White Oak N.45°E., 8 lks.
A 12" White Oak N.65°W., 11 lks.

✓ C.C. 1/4 SECTION CORNER NORTH SIDE OF SECTION 7.
Set by proportional measurement by section corners. Drove
1" x 30" Pipe 29" in ground.
A 14" White Oak S117°22'E., 329 lks.
A 15" White Oak S.40°47'W., 339 lks.

16
Ben B. Irving D.C.S.
Witnesses
Lew Smith
Louis Gilboa
May 24, 1938.
C.S. 11/29

1/4 COR. 17-18
Set 300 ft. South of Witness Corner on line to Cor 17-18-19-20
No B.T.s or sign of corner.
Drive 1" I. Pipe.
Mark 18" Fir S 14° 40' W 87.0 ft.
All other trees dead.

18
D.C.S-Geo. J. Wenderoth
June, 1950
F. Sincumb - Witness
895-714

RE-RENEWED, SEE CORNER NO. 99
RE-RENEWED, SEE CORNER NO. #163
RE-RENEWED, SEE CORNER NO. 32
RE-RENEWED, SEE CORNER NO. #34
RE-RENEWED, SEE CORNER NO. 154
RE-RENEWED, SEE CORNER NO. 57a 151-152

END B.L.M. B.C. 1972 R Brown M112-63

QUESTIONED BY B.L.M. Oct. 1968