

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 3 R. W. W. M.

Ben B. Irving
Wit.
John A. Irving
V.N. Poole
Joe Wright
Walter Poole
Feb. 18-19, 1937

✓ 1/2 CORNER BETWEEN 19 and 30. **SEE CORNER NO. 31** 19
Location identified from both original B.T.s as recorded.
N.E. tree down. Set a Fir Post 4" square X 36" long for
corner. Remarked Original B.T. standing and (C.S. 30/1)
A Fir 14" dia. N.53°E., 65 lks. $\frac{1}{4}$ S.19 C.3.B.T.

Ben B. Irving D.C.S.
Wit.
Lew Smick
Louis Gilboa
Mar 24, 1928.

✓ SECTION CORNER BETWEEN SECTIONS 5 and 6. **SEE CORNER NO. 39** 20
Location identified from three original B.T.s and stamp
of fourth which conforms to original field notes as recorded.
Drove a Yewwood post 3" x 3" x 36" for corner scribed
S.6/S.5 T.30S., R.3W., C.S.

Germond
Aug. 1916
Wit.
Goltzor
Gorus

✓ CLOSING SECTION CORNER BETWEEN SECTIONS 7 and 8. **SEE CORNER NO. 38** 21
Location identified from original B.T.s as described
in the original field notes. Set a 1" x 30" drill steel
for corner with a 4" x 4" x 28" Maple post along side
scribed S. 7 S. 8
T.30S. R.3W.
C.S. C.C.

H. L. Eppstein
Witnesses
C. W. Crocker
J. H. Howell
Nov. 7, 1933.

✓ CORNER OF SECTIONS 24 and 15. **SEE CORNER NO. 76** 22
Set 4" x 4" Post. Witness-Trees
Fir 30" dia. N. 2°E., 8 lks.
Fir 12" dia. S. 5°E., 65 lks.
Cedar 10" dia. S.60°W., 25 lks.
Fir 12" dia. N.55°W., 58 lks.

Arthur Boyer D.C.S.
Wit.
N.E. Richardson
Wm. Vlam
July 21, 1937

✓ CORNER SECTION 19 and 30 **SEE CORNER NO. 29** 23
Set 1 1/2" Iron Bar in ground. Old Oak Witness trees
all in fair condition, did not mark new trees.

Arthur Boyer D.C.S.
Wit.
N.E. Richardson
Wm. Vlam
July 21, 1937

✓ 1/2 CORNER BETWEEN 24 and 25. 24
Found old Pine witness tree N.48°W., 14 lks, and
place where other witness tree stood, tree slid down hill.
Marks plain. Set 1 1/2" x 30" Iron Pipe for corner marked
new Witnesses trees
A 10" Pine S.49°30'E., 25.7 ft.
A 12" Fir N.10°30'E., 22.4 Ft. marked C.S. $\frac{1}{4}$ S. B.T.

Ben B. Irving
Wit.
N.E. Richardson
Loren Weber
Oct. 9, 1940
V.16-E.55

✓ SECTION CORNER BETWEEN 23, 24, 25 and 26. 25
Set part of auto bumper from original tree to N.W.
which is only original tree left. Remarked original
tree
A 30" Fir (Bark blazed new) N.70°W., 43.7 ft. **153**
A 30" Fir S.43 1/2°W., 81.0 ft.
A 24" Fir (Bark Blaze) N.0°30'E., 70 ft.
Stump of original B.T. which was sawed flush, in old
trail, is N.5°E., 24 ft.

✓ S.E. CORNER OF SECTION 25. **SEE CORNER NO. 70** 26
Found rock loose and out of place and Fir tree to
the N.W. cone. Reset rock as well as could be done
and drove steel auto axle from three B.T.s which are
standing. Marked new B.T.
A 16" Fir N.52°45'W., 23.0 ft. marked S.25 T.30 R.3
C.S.B.T.

✓ SECTION CORNER BETWEEN 27, 28, 33 and 34. 27
All bearing trees have been destroyed a stump checks
S.W. for a possible B.T. Mr. W. T. Wright state that a
rock, chisle marked, was alongside a Yew Wood gate post
for many years after he acquired the property around this
corner. The location checked with distances to road and
river as recorded. In accordance with this evidence, drove
a truck axle 1 1/2" diam. flush with ground for corner, No
trees convenient so scribed Yew Wood gate post along side
corner Cor. 27-28-33-34. C.S. **149**