

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 3 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

95
 1/4 Section Corner to Sections 27 and 26.
 Found - 15" B. O. (now hollow shell) N.10°W. 66 ft., per gov't. notes.
 A depression in ground for 15" B.O., S.50°E. 36.3 ft.
 I find two New BT's. faced, no scribing:
 32" Fir N.44°E. 64.2 ft. (I scribe)
 26" Y.P. S.74°W. 62.6 ft. (I scribe)

R. M. Thompson
 For:
 George Meyers
 March 1960
 C.S. File
 No. 51/172

96
 East 1/4 Corner to Section 13.
 Found - Both Orig. BT's. Orig. 30", now 36" Rotted Cedar Stump
 N.46 3/4°E. 94.7 ft. Orig. 12", now 18", Fir N.71°W. 17.8 ft.,
 shows good scribing.
 36" Fir S.70°W. 14.5, not 18.5 ft., shows scribing. (This BT.
 scribed 1908)
 Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1962
 E 1/4 S13 | T30S R3W

No. New Bearing Trees needed.
 Note - I find both BT's., now stumps, each shows good scribing,
 for West 1/4 Corner S18, T.30S R2W. I also find 1 1/4" I.P. set for corner
 with 6" x 2" Painted White Yewwood Post alongside. The Brass Cap at
 S13 bears South 86.0 ft., not 92.4 ft.
 From the 1 1/4" I.P., now 30" Fir Stump bears N.66°E. 31.7 ft., not N.40°E.
 Now 30" S. Pine stump bears S.27°E. 17.2 ft., not S.60°E.
 Bearing trees face to 1 1/4" I.P.

James W. Byron, Deputy County Surveyor
 Dale McFarland and John Powell
 March 22 - 26, 1962
 C. S. File No. 49/47

97
 Section Corner to Sections 13 - 14 - 23 - 24.
 Found - All Orig. BT's. Orig. 24", now 32" Fir Stump S.16°W. 13.2 ft.,
 shows scar.
 Orig. 15", now 16" Fir Snag S.5°E. 23.1 ft., shows good scribng.
 Orig. 36", now 40" Fir Stump N.80°W. 27.7 ft., shows scar.
 Orig. 24", now 30" Fir Stump N.85°E. 19.8 ft., shows scar.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 S14 | S13 T30S R3W
 S23 | S24 T30S R3W
 New BT's: 8" Cedar bears N.24°W. 29.0 ft. scribed S14 T30S R3W.
 24" Cedar bears S.59 1/2°W. 35.3 ft. scribed S23 T30S R3W CS BT.
 8" Fir bears S.38°E. 8.4 ft. scribed S24 CS BT.
 26" R.Fir bears N.85°E. 58.3 ft. scribed S13 T30S R3W CS BT.

98
 1/4 Corner to Sections 14 and 13.
 Found - No Original Bearing Trees. Corner is 15 ft. East of Log. Road
 and in fill area. We do find Orig. 20", now 27" Cedar
 Stump with butt log section laying North & South with 2 old
 notches on North face. This is line tree 2.05 ch. S. of Cor.
 Find 2" x 2" Fir Stake bears N.25°E. 5.0 ft. Mkd: 1/4 S13-S14.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 1/4 S14/S13 T30S R3W
 New BT's: 14" Hemlock bears N.25°E. 35.0 ft. scribed 1/4 S13 CS BT.
 6" W.Fir bears S.72 1/2°W. 51.2 ft. scribed 1/4 S14 CS BT.

James W. Byron, Deputy
 Mike Darby and Wm. Stoffel
 November 1, 1962
 C.S. File No. 52/126

99
 Section Corner to Secs. 5 & 6, T30-3W. & Secs. 31 & 32, T29-3W.
 Found - Both BT's. as recorded by Eppstein, 1927. Each shows good scars.
 Also find 1/2" I.R. at Corner. - REN #9
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 S31 | S32 T29S R3W
 S 6 | S 5 T30S
 New BT's: 10" Cedar bears N.60°E. 21.0 ft. scribed T29S R3W S32 CS BT.
 15" R.Fir bears N.42°W. 55.0 ft. scribed T29S R3W S31 CS BT.

100
 Section Corner as diagramed below:
 Found - 4" x 4" x 6' scribed Cedar Post. 14" B.Oak S.84°W. 40.3 ft.,
 shows rotted. face. 12", now 16" R.Fir N.53°E. 19.7 ft.,
 shows good scar. Other Bearing Trees Not found. (See Ren #42-T30-4W)
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 R4W S36 | S31 R3W T29S
 S 1 | S 6 T30S
 New BT's: 10" R.Fir bears N.71°W. 38.0 ft. scribed S36 T29S R4W CS BT.
 7" Cedar bears S.55°W. 31.9 ft. scribed S1 CS BT.
 No-trace-nea No Trees near to S. E.

Fence Thus:



E 1/4
 6/26
 J.R.

FD OK
 10-9-62
 By L.A.M.
 Mill 7-2

Township
 corner

RENEWED CORNER NO. 132

RENEWED CORNER NO. #232

RENEWED CORNER NO. 198