

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 30 S. T. S. R. 3 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

181

Sec. Cor. to Sections 32 & 33 only, T30-3W.

Found - I. Pipe at Sec. Cor., See Ren. #78.

20" Cedar, now 22", N. 7° E. 6.0 ft., scribing visible

20" Cedar, now 21", N. 5° W. 22.0 ft., scribing visible

20" Cedar, now 22", S. 35° W. 34.0 ft., "

16" Cedar, now 18", S. 1° W. 24.7 ft., "

Set - Brass Cap alongside I. Pipe Mkd: County

	T 30 S	
Surveyor's	S 32 / S 33	
Office	S 5	R3W

All BT's. in very good condition.

1966 T 31 S

Note - This corner is now in cutting corner & lies on the west slope of ridge close to small ravine.

RE-RENEWED, SEE CORNER NO. #235

182

North $\frac{1}{4}$ Corner Section 6 only, T31-3W.

Found - I. Pipe at $\frac{1}{4}$ Corner, (See Ren. #78, T31-3W)

8" Chinq., now 9", N. 18° E. 20.0 ft. scribed $\frac{1}{4}$ S6 BT.

6" Chinq., now 7", S. 24° E. 25.0 ft. " " " "

4" D. Fir, now 5", S. 43° E. 23.8 ft. " " " "

Set - Brass Cap alongside I. Pipe Mkd: County

	$\frac{1}{4}$ T30S	R3W
Surveyor's Office, 1966	S 6	T31S

All BT's. in good condition. Corner is at cutting corner.

183

Corner to Sections 5 & 6 only, T31-3W.

Found - I. Pipe at Corner, (See Ren. #43, T31-3W)

Orig. 30" Fir S. 64° E. 18.5 ft., shows good scar.

Orig. 10" Maple S. 33° W. 18.5 ft., partly rotted but still standing.

7" Live Oak, now 14", S. 19° W. 70.0 ft. scribed S 6 BT.

18" Fir N. 54° E. 23.0 ft., scribed "BT S32".

16" Fir, now 18", S. 78° W. 15.0 ft., shows good scar & "BT".

Set - Brass Cap alongside I.P. & Mkd: S 32 T30S

County Surveyor's Office, 1966	S 6 / S 5	T31S R3W
--------------------------------	-----------	----------

All trees in good condition. Best way to corner, walk up ravine until you come to East-West line, then East uphill.

John M. Powell
Frank Jones & Joe Brady
Dec. 1965 and Jan. 1966
C. S. File No. 52/63

184

Corner to Sections 4 & 3 only, T31-3W.

Found - I. Pipe at Corner, (See Ren. #40, T31-3W)

Orig. 16" Fir Snag S. 44° W. 4.6 ft., gone.

Orig. 16" Fir N. 57° E. 27.4 ft., stump.

10" Fir, now 12", S. 59° W. 21.0 ft., good scars, part of scribing.

6" Fir, now 8", N. 45° E. 16.0 ft., good scars.

6" Fir, now 8", S. 81° E. 26.6 ft., good scars.

Set - Brass Cap alongside I.P. & Mkd: S 34 T30

Co. Surveyor's Office, 1966	S 4 / S 3	T31S R3W
-----------------------------	-----------	----------

FD. OK 8/83
H. Johnson
M 95-6

185

Corner to Sections 5 and 4, only, T31-3W.

Found - I. Pipe at Sec. Cor., (See Ren. #24, T31-3W)

8" Laurel, now 13", S. 23° W. 12.0 ft., bark scribed.

Orig. 15" D. Fir, now 20", N. 11° W. 24.4 ft. Opened, parts of scribing visible.

Set - Brass Cap at Cor. alongside I.P. Mkd: S 33 T30

Co. Surveyor's Office, 1966	S 5 / S 4	T31 R3W
-----------------------------	-----------	---------

New BT's: 19" D. Fir North 31.8 ft. scribed T30S R3W S33 CS BT.

13" Laurel S. 23° W. 12.0 ft. scribed T31S R3W S5 CS BT.

186

Sec. Cor. to Sections 31 & 32 only, T30-3W.

Found - I. Pipe at Sec. Cor., See Ren. #82.

Orig. 24" D. Fir. S. 72° E. 29.9 ft. Tree had been opened, showing faint scribing.

14" Laurel N. 88° E. 49.0 ft., bark scribed.

9" Laurel N. 58° W. 19.0 ft., " " "

14" Laurel S. 17° W. 26.0 ft., " " T31S R3W S6 BT.

Set - Brass Cap alongside I. Pipe Mkd: S 31 / S 32 T30SR3W

County Surveyor's Office, 1966	S 6	T31SR3W
--------------------------------	-----	---------

FD OK 11/88
H. Johnson
M 107-9

New BT's: 14" Laurel S. 16° W. 27.2 ft. rescribed T30S R3W S31 CS BT.
9" Laurel N. 58 $\frac{1}{2}$ ° W. 19.0 ft. " " T31S R3W S 6 CS BT.