

Douglas County Surveyor's Record of  
Government Corners Renewed

T30 T.S. 3R. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

204

Gary Langletz  
Peter L Earle  
4/28/75  
C.S.57/21

1/4 Corner to Secs.4 and 5.  
Found - 3/4 Iron pipe, firmly set.  
From which;

See Ren.#141

- A 16" D Fir stump, rotten, bears N.1 1/2°W., 26.2 ft., 25.8 to face, (rec. S.4 3/4°W., 25.8 ft.) scribing "BT" visible on unhealed blaze.
- A 16" D Fir, now an 18" snag approx. 15 ft. tall and rotten bears S.53°E., 13.8 ft., 13.3 to face, (rec.N.53°E1, 13.3 ft.) showing a well healed double blaze.

We open the upper blaze and find scribing "1/4S" Note! We deface the erroneous bearing shown on an old location poster attached to this BT. We could not determine the reason for the discrepancy shown in the bearings. Note! The blazes on the found BT's do face the location of the iron pipe, the area immediately around the corner has not been severely disturbed.

At the corner point as determined by the location of the found 3/4" iron pipe, we set a 1" x 30" iron pipe with brass cap attached, marked County Surveyors's Office T30S

S4  
S9 1/4  
R3W  
1975

We place the iron pipe alongside the brass cap and mark the following bearing trees;

BT's;

- A 6" Madrone bears N.80 1/2E., 16.5 ft., scribed "1/4 S4 CS BT"
- A 5" D Fir bears S.41°E., 24.5 ft., scribed "1/4 S9 CS BT"

This corner lies in a dense growth of small fir and Madrone.

FD OK 6/93 LANG M123-14

4/28/75

205

L.E. Monrean  
P.L.E.  
J.H.C.  
CS 57/39

Sec. corner to Sec.11,12,14 and 13

Found-Brass cap set in 1963 properly stamped by County Surveyor office.

Cap is out of ground and downhill from sec. corner position. #125

A fir 28" now 44" dia. bears S 66 3/4°W., 17.2 feet. Tree has good blaze

A fir 13" now 29" dia. bears N 38 1/4°W., 8.6 ft. tree has good blaze, I open partially and find scribing "T30S"

Set-reset brass cap at sec. corner cap is marked as noted. As NE and SE bearing trees are gone I scribe two new BT's.

A red cedar 8" dia. bears N 3 1/2°E, 79.6 ft. Tree is double blazed and scribed " T 30 S, R 3 W, S12 CS BT"

A Hemlock 22" dia. bears S 7 1/2°E., 21.9 ft. Tree is double blazed and scribed " T 30 S, R3W., S13 CS BT" Mag. Dec. 20°E. 12/23/75

206

Sec. Corner to 17,18,19, and 20

REN # 36,57, & 160

Found-1" dia. pipe set in 1950. (see renewal # 36) Iron pipe is firmly in place an approx 36" dia. log lying over monument.

Orig. BT's A stump (fir) 18 now 36" dia. bears S78°W, 44.9 ft. Blaze has been opened, scribing "BT" legable.

A fir, uprooted and badly rotted, approx. standing position bears S 18°E., 9.2 ft. Tree has scar which has been opened. No scribing visible.

A maple, 6 now 20" dia. bears N19 1/2°E., 43.6 ft. (rec. N18°E) Tree blazed original blaze badly rotted, scribing "CS" legible from rescribe per renewal #36.

Orig. NW BT not found. (BT's per renewal #36)

A 12 now 13" fir stump, badly rotted, bears N28°W., 56.7 ft. (rec.58.8 ft) scribing visable "18 CS BT"

A 16 now 26" dia. red cedar bears S29°E., 42.0 ft. (rec.S31°20'E) Tree has good glaze. (BT per Renewal # 160)

A 24" dia. red fir, bears S44°W., 80.8 ft. (rec.81.7 ft) Tree has good blaze pitched over.

SET- Brass cap at section corner stamped

COUNTY SURVEYORS OFFICE

1976

T30S R3W

S18 | S17  
S19 | S20