

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S.

R 3

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

220 A

Section corner for Secs. 25 and 36 only, T.30-4.

Found - A 2 1/2" brass cap on a 1" I.P. firmly set and protruding 15" from ground. Cap is properly marked. Ren. #169 (1963)

An orig. red fir 12" now a 24" DBH D. Fir snag approx. 45 ft. tall bears S.48°W., 21.8 ft. distant. tree has blaze scars, an "X" blaze in the bark on the northeast side, and is bark scribed T30 R4W S36 BT.

An orig. Red fir 8" now a 10" diam. 30" tall rotted fir stump bears N.46 1/2°W., 22.4 ft. stump has old axe work, no scribing f

A 14" R. fir now a 14" DBH D. fir snag approx 12 ft. tall bear N.01°W., 40.8 ft. tree has unhealed double blaze marked T30S R4W S25 CS BT (Rec. S25 T30S R4W CS BT)

Monument position is accepted.

New BT's- A 6" DBH D. Fir bears S.51 1/2°W., 31.0 ft. and is scribed T30S R4W S36 CS BT on a double blaze.

A 7" DBH D. Fir bears S.65°W., 61.2 ft. and is scribed T30S R4W S36 CS BT on a double blaze.

The tree from Ren. #169 and the new bearing trees are tagged with DCSO BT tag 3/26/81

1/4 Corner for sections 7 and 18

221

REFERENCED NOTES ONLY

Found - Orig. 8 x 11 x 4 stone (Rec. 14x12x4) marked "1/4" on top of ground along northerly side of iron pipe and brass cap monument a 1965 GLO brass cap marked "1/4 S7 S18 1965".

1" I.P. along northerly edge of I.P. Mon. Ren. #66

Orig. 7" now 8" fir snag scribed "1/4 S" on previously opened blaze bears N.41 1/2°E., 9.9 ft. (Rec. N.36 1/2°E., 9.2 ft.)

Orig. 30" now a 46" fir with healed blaze bears S.75°E., 22.2 ft. (Rec. 23.1 ft.)

A fir, 12" now 14" bears N.38 1/2°W., 23.8 ft. (Rec. N.41 1/2°W. OK at top of blaze.) Blaze is well healed. Ren. #66

This area soon to be logged, we reference as follows:

We reference position of BLM brass cap and dig up cap. #239  
Set at 1/4 cor. position a 5/8" x 30" I.R. 18" below surface.

Set 1" x 18" I.P. (from Ren. #66) 12" below surface directly over I.R.

Set orig. stone along north edge of I.P. 12" below surface. Reset BLM brass cap at referenced position with cap 2" above surface.

Set 4 PK nails in notched roots as follows:

A 48" fir, PK bears S.71 1/2°W., 49.2 ft. (Tree has large opening in east face)

14" fir (BT found) PK bears N.40°W., 22.5 ft.

24" fir PK bears N.22 1/2°E., 40.1 ft.

46" fir (BT found) PK bears S.76°., 19.8 ft.

3/5/81

222

North 1/4 Corner of Sec. 4 only, of T.31-3.

Set - 5/8" x 36" I.R. & alum. cap mkd. LS 498.

New BTs- 25" fir bears N.8°W., 5.4-ft.

7" fir bears S.64°W., 9.5-ft.

6/10/82

1/4 Corner for Sections 27 and 34

223

Recent slide activity had destroyed previous monument. Ren. #201

Found - Orig. 20" fir now 39" stump with scribed "S BT" visible in previously opened blaze.

20" now 24" madrone per Ren. #201 with scribed "1/4 S27 CS BT" visible in partially healed blaze.

55" fir per Ren. #201 now 55" stump with scribed "S27" visible in partially healed blaze.

On March 3, 1983, my crew set a 1" x 30" I.P. with brass cap using record bearings and distances from the found bearing trees. Cap mkd. "Douglas Co Surveyors Office T 30 S R 3 W 1/4 S27 S34 1983."

Bearing Trees are as follows:

39" fir stump bears N.70°E., 36.3 ft.

24" madrone bears N.60°E., 80.6 ft.

55" fir stump bears N.82°E., 46.0 ft.

Since the brass cap falls in the center of the slide area and will probably be washed out again, I returned March 23, 1983 and set two 5/8" Iron rods with aluminum caps as reference marks.

CONT. NEXT PAGE - -

S.J. Flause, Deputy  
Doug. Co. Surveyors  
Office

Witness: T. Plouff  
March 26, 1981  
C.S. 61/19

Larry E. Monrean  
Deputy, Doug. Co.  
Surveyors Office  
G. E. Quibell  
D. L. Stewart  
March 5, 1981  
C.S. 59/30

Howard Johnstone  
LS 498  
For: Rsbg. Lmbr. Co.  
June 10, 1982  
M 92 - 44

Gregory Quibell,  
Deputy, Doug. Co.  
Surveyors Office  
John Powell  
Randy Smith  
March 3-23, 1983  
C.S. 62/7