

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S.

R 3

R.W.W.M.

KOBE-CHAPMAN CO., EUGENE, ORE. 21881

Howard Johnstone,  
L.S #498  
For: Roseburg Lumber  
Company  
August 26, 1983  
M 95 - 6

Section corner for Secs. 27, 28, 33 and 34. 227  
Found - 1" axle in corner of barn yard. Ren. #149  
11" oak, N.9°E., 40.0 ft. partially healed.  
New BT - 20" fir, bears S.10°E., 30.0 ft.

1/4 Corner for Sections 33 and 34. 228  
Set - 1" x 36" iron pipe and brass cap, marked LS 498.  
New BTs - 10" fir, S.63°E., 25.5 ft.  
19" fir, N.42°W., 24.0 ft.

Center 1/4 corner for Sec. 34. 229  
Set - 5/8" x 36" iron rod and alum. cap marked LS 498.  
New BTs - 4" fir, N.70°E., 3.6 ft.  
4" fir, S.64°W., 8.8 ft.

Sec. Corner for Secs. 6, & 7 only. 8/26/83  
Found - 1" I.P. w/B.C. per Ren.#61, protruding 10" above ground properly  
marked.  
Partially buried corner stone alongside I.P. w/four (4) notches  
visible on stone. per W.M. Theil 1889 Resurvey.  
BTs - NO orig. BTs found.  
36" fir, now 30" diam. stump, 4-ft. high & rotted bears  
S.88°E., 21.8-ft. (Rec. N.88°E., 19.8-ft.). B.L.M. 1965 Resurvey  
calls this stump an orig. BT, but this BT came from W.M. Theil  
1889 Resurvey.  
10" maple, now a downed tree, root hole bears S.19°E., 25.6-ft.  
BT has partially healed blaze & illegible scribing visible.  
B.L.M. 1965 Resurvey calls this tree an orig. BT, but this  
BT came from W.M. Theil 1889 Resurvey.  
NO other BTs by W.M. Theil 1889 Resurvey found for this corner.  
18", now 28" fir w/a single healed blaze bears S.50°W., 31.7-ft.  
Ren.#61.  
NO other BTs per Ren.#61 were found.  
12", now 20" D.Fir w/well healed dbl.blaze bears N.61°E., 97.7-ft.  
This BT is from B.L.M. 1965 Resurvey.  
New BTs - 6" ash, dbl.blazed & scribed "T30S R3W S7 CS BT", bears  
S.38°E., 12.8-ft.  
8" maple, dbl.blazed on south trunk of dbl.trunked tree, scribed:  
"T30S R3W S6 CS BT", bears N.73°E., 13.2-ft. to center of  
rootcrown.

Note - See file for additional comments & sketch. 2/84  
Section Corner for Sections 24 & 25 (T30-3) and 19 & 30 (T30-2) 231  
Found - 3/4" drill steel REN #29  
18" Madrone snag, bears N.49°50'W., 26.0 ft. dist.  
24" Madrone snag, bears N.2°26'E., 30.9 ft. dist.  
16" Madrone snag, bears S.31°25'E., 9.3 ft. dist.  
16" Madrone stump, bears S.64°32'W., 19.2 ft. dist.,  
(Record, 18.2 ft. dist)  
15" Oak, bears S.54°W., 24.4 ft. dist. (SNAG)  
SET - A 5/8" iron rod and Aluminum cap, marked "LS 498"  
NEW BT's - 5" Fir, bears N.46°W., 24.0 ft. dist. (Scribed)  
Scribed a 6" Madrone, bears N.46°E., 43.8 ft. dist.  
Scribed a 6" Madrone, bears S.58°E., 21.3 ft. dist.  
Scribed a 5" Madrone, bears S.22 1/2°W., 12.7 ft. dist.

W 1/4 Cor. Section 18 Only. T 30 S R 2 W REN #96A 232  
Found - A 1 1/4" Iron Pipe (Found in 1962), alongside of which is a  
painted white 6" x 2" yew wood post marked: 1/4 S18 30S 2W  
BT's - An Orrig. 30" badly decayed sugar pine stump bears S 27° E,  
17.2'. ( rec. - S 60° E.)  
An Orrig. 30" badly decayed fir stump bears N 66° E, 31.7'  
(rec. N 40° E) chop marks visible. Original tree.  
New BT's - 6" Cedar bears N 62° E, 29.6'.  
5" Fir bears S 20° E, 14.0'.  
Both scribed " 1/4 S18 BT".

Randall Smith, Deputy  
Douglas County Surveyors Office  
Stephen Flause  
2/29/84  
C.S. 62/16

Fuo. ok 10/92 R. Brown M 112-62

Howard Johnstone  
"LS 498"  
For: Roseburg Resources Company  
December 30, 1985  
M 100 - 21

Ronald Geisler  
"L.S. # 1988"  
For: Champion Int.  
May 1986  
M 100-78