

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 4 R. W. W. M.

F. C. Trear D.C.S.  
Witnesses  
Ralph Knight  
Opher Perdue  
November 12, 1919.

J. W. Cole  
Witnesses  
I. H. Smick  
P. D. Wolford

Mit.  
J. W. Montgomery  
H. A. Hill  
4/6/22

G. G. Stewart Deputy County Surveyor  
Mit.  
H. A. Hill  
W. S. Crear  
April 6, 1922

G. G. Stewart Deputy County Surveyor  
Mit.  
W. S. Crear  
April 4, 1922  
c.s. 7/6

Mit.  
W. S. Crear  
H. A. Hill  
April 7, 1922

- ✓ S.E. CORNER OF D.L.C. 40. 19  
I reestablish from O.B.T. by setting a 4" x 4" x 36" Yew Stake and Rock Mound from which.  
A 36" Black Oak N.68 $\frac{1}{2}$ °W., 4.90 ch. O.B.T.  
The S.W. Corner of Cl. 41 bears North 2.00 ch. 242
- ✓ S.E. CORNER OF D.L.C. 41. 20  
I re-establish from old B.T. by setting a 1" x 36" Iron Pipe from which  
A 36" White Oak bears N.25°W., 4.72 ch. Old B.T.  
A 12" White Oak bears W.80°E., 31.15 ch. O.B.T.  
The S.W. Corner of Claim 42 bears N.0°45'W., 6.70 ch. 216
- ✓ THE S.W. CORNER OF D.L.C. 42. 21  
I re-established from old B.T. by setting a 1" x 36" Iron Pipe from which  
# 30" Black Oak bears N.66°E., 1.56 ch. O.B.T.  
A 8" Fir Tree bears S.18 $\frac{1}{2}$ °W., 0.10 ch. C.S.B.T.  
The S.E. corner of Claim 41 bears S.0°45'E., 6.70 ch.
- ✓ CORNER TO SECTIONS 14, 15, 22 and 23. Not Found J.W.B. 22  
Set from three Oak B.T.s which are standing. Tree 1963 N.71°E. is dead. Pine down and slid down hill. Set 4" x 4" x 40" Oak stake properly marked. Erected mound of rock around stake. Marked a X on a Triangular face of rock about 4' high N.11°E., 45.1
- ✓ CORNER TO 9, 10, 15, and 16. 23  
Reset witness corner as established by Thiel Survey of Section 16. The two B.T.s had been cut and were rotting. I set 1" Galv. Iron Pipe 12 links due East of the corner as given by B.T.s. Making pipe 290 links East of section corner. Marked  
A 6" Black Oak S.31°W., 18.5 ft. 141
- ✓ SECTION CORNER 3, 4, 9, and 10. 24  
Reset from two O.B.T.s. Set Iron pipe. Marked  
A 18" Black Oak N.33°E., 10.5 ft.  
A 24" Black Oak N.82°W., 55.6 ft.  
A 22" Black Oak S.7 $\frac{1}{2}$ °E., 130.8 ft.  
No other trees suitable. 231
- ✓  $\frac{1}{2}$  CORNER BETWEEN 3 and 4. 25  
I Set an Iron Pipe for corner from O.B.T. which was a 24" Black Oak instead of White Oak as called for. Bearing did not check. Marked  
A 24" Black Oak S.32°W., 30.0 ft. O.B.T.  
A 18" Pine tree S.42°E., 23.5 ft. 153-125
- ✓ S.W. CORNER OF D.L.C. # 47. 26  
I set an Iron Pipe from O.B.T. Marked  
A 24" Black Oak S.32°W., 30.0 ft.  
A 18" White Oak N.86 $\frac{1}{2}$ °E., 91.0 ft. 157
- ✓ INTERIOR "L" CORNER OF D.L.C. # 47. 27  
Set 2" Iron Pipe for corner. No B.T.s present but rails located. Re-marked the O.B.T. and marked  
A 18" White Oak S.73°W., 194.0 ft. # 83
- ✓ N.W. CORNER OF D.L.C. # 47. 28  
Reestablished by running needle line, West, sun bearing, from point 137.3 ft. North of Section Corner 3, 4, 9, and 10, as set, 1559.0 feet as per field notes by Claim Survey. No corner could be found. Set Iron Pipe marker and marked  
A 24" Cedar N.1°W., 24.6 ft. 235

See C.S. 7/6  
F.B. 3/12

RE-RENEWED, SEE CORNER NO. 141

RE-RENEWED, SEE CORNER NO. 153-125

RE-RENEWED, SEE CORNER NO. 157

RE-RENEWED, SEE CORNER NO. # 83

RE-RENEWED, SEE CORNER NO. 235