

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 4 R. W. W. M.

✓ 1/2 CORNER BETWEEN SECTIONS 9 and 16. 44
Set 1 1/4" x 3" Shaft for corner from old B.T.s. Marked
new B.T. **SEE CORNER NO. 144-61**
A 8" Fir S.21°W., 6 lks.
A 30" Fir N.71°E., 25 lks.

✓ 1/2 CORNER BETWEEN SECTIONS 8 and 9. 45
Set corner from old Black Oak B.T. S.86°W., 1910 lks.
Other tree is gone. Marked new B.T.
Black Oak 24" dia. bears N.10°30'W., 741 lks.

✓ 1/2 CORNER BETWEEN 9 and 10. 46
This corner was gone. So I set it proportional distance
and bearing between Section Corners by placing 1" x 18"
Galv. Iron Pipe 10" under ground and marked new witness
trees
A 22" White Oak S.46°E., 916 lks.
A 5" Prune Tree S.15°30'W., 572 lks.

✓ CORNER BETWEEN 1, 2, 11, and 12. 47
Found Conglomerate Rock 6" x 6" x 1 1/2". Marked **108**
A 6" White Fir N.45°E., 7 ft.
A 8" White Fir S.62°W., 25 ft.
A 24" Fir N.89°W., 13 ft. Orig. B.T.
A 6" White Fir S.42°E., 2.5 ft.

SEE OLD
REN. Vol. 1
PG 143

✓ CORNER BETWEEN 21, 22, 27 and 28. 48
Remarked Original B.T.s (and set Post or Stake) as
follows
A 12" Cedar N.71°E., 21.5 ft.
A 12" Laurel S.48°E., 44.2 ft.
A 30" Cedar S.75°E., 29.0 ft.
A 6" Fir N.80°W., 37.0 ft. New tree **203**

✓ 1/2 SECTION CORNER BETWEEN SECTIONS 19 and 20. 49
Location identified from one original B.T. as described
in Government Field notes 12" (now 24") Fir N. 80°E., 17 lks.
A 6" Laurel South 7 lks. down and rotting. Black Rock
knocked out and in creek. Reset B. Rock chisling 1/4 on South
face. Blaze and scribe
A 18" Fir N.45°E., 70 lks. 1/4 S. 19 C.S.B.T.
A 26" Fir S.45°W., 67 lks. 1/4 S. 30 C.S.B.T.

✓ SECTION CORNER BETWEEN 24, 25, 19 and 30 T.30° S., R. 4 50
and 5 W.
Location identified from Pine N.7°E., 475 lks. and
Fir N.34 1/2°W., 10 lks. (recorded S.34 1/2°W.)
Set 4" x 6" x 22" hard sandstone for corner chiseled
19 on N.E. face--30 on S.E. face--24 on N.W. face--and 25
on S.W. face.
Blazed and scribed
A 16" Fir S.30°W., 58 lks. T.30S., R.5W., S.25 C.S.B.T.
A 16" Fir S.35°E., 43 lks. T.30S., R.4W., S.30 C.S.B.T.
as additional B.T.s. **221**

✓ SECTION CORNER CLOSING 25 and 36. 51
Location identified from Original B.T. as recorded.
Original post rotted off but on ground. Set new post
properly marked 3" x 36". **SEE CORNER NO. #175**
March 19, 1930.

✓ CLOSING 1/2 SECTION CORNER OF SECTION 25. 52
Location on Range line midway between N.E. and S.E.
corners of Section 25. Set 7/8" x 60" Iron bar driven
2" underground, 4" x 6" x 36" Cedar Post alongside scribed
3/4 S.25 C.C. C.S. on W. face,
Marked
An 8" Fir N.70°W., 121 lks. marked 1/4 S.25 C.C. C.S. B.T.
An 8" White Oak S.45°W., ? lks. marked 1/4 S.25 C.C.
C.S.B.T.

H. L. Epstein Co. Sur.
Witnesses
William Kaylor
Henry Rechor
I. E. Richardson
Oct. 26, 1928.

Ben B. Irvine
Witnesses
Earnest Brown
Joe Snyder
Nov. 19, 1934.
Sept. 3, 1937.
D.S. 37/19

54/6
50

Ben B. Irving D.C.S.
Witnesses
Herbert Beyers
Ho. Huntington
January 27, 1930.

D.S. file 5/17 2" x 10" Oak Bark
Pg. 201

Ben B. Irvine
Witnesses
J. I. Irvine
V. N. Poole
Mar. 5, 1930