

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 4 R. W. W. M.

KOTE-CHAPMAN CO., EUGENE, ORE. 97196

e.L. 46-m.e.s.

S.E. Corner Cl-48 Set Post Marked Nee B.T.
Black Oak 16" S 2° W 949 lks
Oct. 19, 1887 Briggs Dumonds

71

A N W Cor. D.L.C. 42
Post Marked New B.T.
Maple 16" S 62° E 35 lks.
Sept. 30, 1900 Briggs

72

1/4 COR BETWEEN 29-30

Determined from the remains of the O. B. T.'s.

Burnt Stump, bears N 85° W 31 lks.

Stump Hole bears S 13° E 28 lks.

At corner set 4" Alder post from which

Alder, 8" diam., bears N 28° E 52 ft., scribed 1/4 S 2880 B T.

Fir, 16" Diam., bears N 3° E 141 ft., scribed 1/4 S 2880 B T.

This cor. is 221 ft. South of Beals Creek; there are three old fences running North, East, and West from this corner; the post being 12 ft. South of fence corner.

73

1/4 COR. BETWEEN 28-29

Determined from the remains of O. B. T.

Burnt stump bears N 85° E 16 lks.

Fir tree bears S 84° W 53 lks., this B T in good condition.

Set 3" Fir post for corner, from which

Fir, 18" diam., bears S 10° W, 38 ft. bark scribed 1/4 S 2880 B T.

This 1/4 cor. is 763 ft. South of the Beals Creek road. The sec. line is fenced North. The centerline is fenced East and West from this cor.

74

1/4 COR. BET. SECS. 5-6

Found both B. T. in good shape

36" Laurel N 75° W 15.8 ft.

12" B. Oak N 45° E 64.0 ft.

Drive 1" Iron Pipe for corner.

SEC. COR. 4-5-8-9.

Found 18" B. Oak N 87 1/2° E 114.4 - Rotten

20" B. Oak N 70° W 70.6 ft. - dead

Drive 2" Iron Pipe for corner.

Scribe - 14" B. Oak N 56° 15' E 79.2 ft.

20" B. Oak S 36° 15' E 87.6 ft.

14" Pine N 87° 50' W 19.5 ft.

14" Pine S 37° 45' W 22.0 ft.

75

SEC. COR. 5, 6, 32 (North Twp. line)

At a point 650.0 ft. West of the South 1/4 cor. of Sec. 32 on Twp.

line, I set a 3/4" x 24" iron pipe 14" in the ground, from which

23" Fir bears N 10° W 19 1/2 ft., mkd. S 32, 2880 B T.

4" Laurel bears S 25° W 40.0 ft. mkd. S 6, 2880 B T.

3" Laurel bears S 58° E 34.0 ft. mkd. S 5 2880 B T.

A diligent search was made for original B.T.'s but no evidence was found. In checking the notes I found the 1/4 cor was re-established from 1 B T., I used the intersection of both original B T's and all of the calls checked (including bearings)

77

1/4 COR. BET. SECS. 2-3

At corner point found 1" I.P. and fence post which I marked

1/4 S, from which

A Cedar 14" diam. bears S 81° E, 24.5 ft. dist. marked 1/4 S, 52, 2880, B.T.

78

George J. Wenderoth
Deputy County Surveyor

John H. Markham Jr.
April 5, 1949
C.S. 40/179

Frank Loso
Lawrence Micheals - Witnesses

May 23, 1949

J. H. Markham - Surv.
Wm. Markham - Wit.

12/5/49
C.S. 40/259

J. H. Markham, Eng.
Geo. Vaughn
C. V. Story
Witnesses
C.S. 40/273

SEE CORNER NO. 205

SEE CORNER NO. 208

SEE CORNER NO. 233

SEE CORNER NO. 116

SEE COR. #13