

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

4

R. W. W. M.

S.W. Cor. of D.L.C. #40, T30S, R4W., W.M. as det. by O.B.T. **106**
A 16" W.O. stump bears N8E., 99.0' dist. O.B.T.
At cor. pt. found large square stone and drove 1" X 30" iron pipe
from which
A W.O. 10" diam. bears N3E; 93.0' dist. mkd. D.L.C. 40 B.T.
A 16" B.O. bears S8E., 373.0' dist. mkd. CL 40 B.T.
S.E. cor. CL # 37 bears South, 669.0'.
Fence runs N & S from corner.

John H. Markham Jr.
Witness: B. E. Blomgren
Done for Stomar Lbr. Co.
June 10, 1953 s. f. 41/161

$\frac{1}{4}$ section cor. 19/20, T30S, R4W., W. M., as det. by O. B. T. **107**
At cor. pt. found 3' pile of stones & drove 1" X 30" iron pipe
from which
A 12" la. snag bears S10°W., 28.0' dist. O. B. T. - found scribe.
A 8" pine bears S11W., 17.0' dist. mkd. $\frac{1}{4}$ S B. T.
A 12" la. bears N6W., 64.0' dist. mkd. $\frac{1}{4}$ S B.T.
A 16" la. bears N48E., 68.0' dist., mkd. $\frac{1}{4}$ S 20, T30S, R4W., 2680 B.T. **219**
Fences run E & W from corner.
Corner lies top of spur ridge.

Section corner to secs 1, 2, 11, & 12 **108**
Identified corner from:
24" Fir N.85°W., 20 lks. chopped out old scribe visible. **SEE COR. #47**
36" Fir S.82°W., 52 lks. - stump checks for bearing and distance.
36" Fir S. 6°E., 51 lks. - stump checks for bearing and distance.
Also found lower part of orig. stake when we excavated for mon.
Set 1 inch iron pipe with brass cap marked County surv. off. 1, 2, 11,
12, T 30 R 4 1953. **SEE CORNER NO. 192, 263**
Blazed and scribed 4 new bearing trees:
8 inch R. Fir, N.15°E., 91.2 ft. dist. mkd. T30S, R4W., S 1 CS BT.
16 inch W. Fir, N.58°W., 41.6 ft. dist. mkd. T30S, R4W., S 2 CS BT,
brass plate.
18 inch R. Fir, S.25°W., 116.5 ft. dist. mkd. T30S, R4W., S 11 BT CS.
12 inch R. Fir, S.65°E., 25.3 ft. dist. mkd. T30S, R4W., S 12 CS BT.

Ben B. Irving
J. Byron
Ray Irving
Nov. 16, 1953
Sur. file
no. 45/219

Northwest corner of the Franklin O. Worley Donation Land Claim No. 49.
Found: **109**
 $\frac{1}{2}$ inch iron pipe at corner - checks bearing and distance to
18 inch R. Fir, S.65°W., 6.5 feet dist. - scribing visible - fair
condition. - **SEE COR. #6**
B. O. BT down and rotted.
Blazed and scribed: **SEE CORNER NO. 240**
6 inch R. Fir, S.77°W., 19.2 feet dist. mkd. NW CL. 49, CS BT.
10 inch Cedar, N.44°E., 23.6 feet dist. mkd. NW CL. 49, CS BT.

J. W. Byron
Ray Irving
John Fee

Southwest corner of the Franklin O. Worley Donation Land Claim No. 49.
Bearing tree set by Cole in 1924 removed by road crew and 4 feet of
fill over corner. We chopped out a 4" ~~from W. O.~~ **SEE CORNER NO. 279** Checks for original
BT except bearing should be N 60° W. No scribing visible as center is
rotted. We set temp. corner using said tree. Then made survey as
shown in notes, which checks position of temp. corner.
Set 1 inch Bolt with $\frac{3}{4}$ inch Hex. head flush with surface of oil mat.
Blazed and scribed:
5 inch W. O., S.88°W., 24.3 feet dist. mkd T30S, R4W., SW CL. 49 CS BT.

May 14, 1954
Filed in 46/45.

N. W. corner of the C. Beckwith C. L. C. No. 39. **111**
Det. by O. B. T. - A 40 inch Fir bears S.18°E., 59.4 feet dist. - found
scribe on O. B. T.
At corner point set $\frac{1}{2}$ inch by 20 inch reinforcing rod and pile of
stones - from which
A 12 inch Maple bears S.61°W., 30.0 feet dist. mkd. CL. 39, B. T.
A 11 inch Cedar bears N.25°W., 50.0 feet dist. mkd. D. L. C. No.
39 B. T.
Centerline of County Road bears East 25.0 feet. **SEE CORNER NO. 165**

John H. Markham Jr.
Witnesses:
R. N. Wilson
J. D. Phillips
Done for Stomar Imbr.
Company
Oct. 28, 1954, File 41/308.