

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

Renew Closing Corner to Secs. 31 & 32, T30S R4W, & Sec. 5, T31S R4W.
Found - All Three Orig. BTs. All Check bearings & distances except
the 45" now 48" Fir S.21 $\frac{1}{2}$ °W. Record distance 37.9 ft. should
be 44.9 ft.

The Orig. N.76 $\frac{1}{2}$ °W. now dead. I open & find good scribing. **131**
Also Find 14"X 12"X 5" stone marked as recorded, laying on ~~none~~
ground & 2 ft. North of Corner.

Set $\frac{3}{4}$ " I.R. at Corner & reset Stone at Corner.

Note: C.C. for Sections 5 & 6. bears N.88°W. 111.2 ft.

New BTs.: 12" R. Fir bears N.64°E. 19.4 ft. scribed CC S32 T30S R4W CS BT.
10" R. Fir bears N.54°W. 21.2 ft. scribed CC S31 T30S R4W CS BT.

RE-RENEWED, SEE CORNER NO. 131

James W. Byron
M. Godfrey
S. Blouw
Dec. 11, 1957
C. S. File No. 49/45

$\frac{1}{4}$ Section Corner to Sections 16 & 17. **132**

No Evidence of Original Corners or BTs. found.

We ran a Traverse Line from the S. W. Corner S16 to N.W. Corner S16.
Then corrected to true line. Reset $\frac{1}{4}$ Corner at proportional distance
& on true line.

Set Brass Cap & 1" I.F. marked County Surveyor's Office, 1954 **230**
 $\frac{1}{4}$ S17/S16 T30S, R4W. from which:

12" Fir bears N.67°E. 41.5 ft. blazed & scribed.

10" Fir bears S.40°W. 44.8 ft. blazed & scribed.

Note: Corner is located in center of logging road.

James W. Byron
For G. Neuner, E. Sumner & A. Rowe
January 17, 1955
C.S. File No. 46/83

Section Corner S17/S16
S20/S21 **133**

BTs. O.K. except 20" Fir S.7 $\frac{1}{2}$ °W. has been cut, stump only left.

Gun Barrell in place. **224**

Blazed & Scribed 10" R. Fir N.9°W. 36.0 ft.

RE-RENEWED, SEE CORNER NO. 224
SEE ALSO #138A

$\frac{1}{4}$ Section Corner to Sections 5 & 8., as det. by O.B.T.'s.

Laurel Stump Hole bears S.6 $\frac{1}{2}$ °W. 12.0 ft. dist. - ~~SEE Cor. #90~~ **134E**
(No Scar on N.W. Cor. BT)

12" B.O. Snag (Live) bears N.39°E. 18.0 ft. dist. O.B.T. *(Not On C. BT)*

At Corner Point found 3"x 3" scribed wood post & Set Steel Fence Post.
from which:

9" Fir bears N.35°E. 9.2 ft. mkd. $\frac{1}{4}$ S5 B.T.

16" La. bears S.30°E. 14.8 ft. mkd. $\frac{1}{4}$ S8 B.T.

4" Fir bears S.49°W. 18.0 ft. mkd. $\frac{1}{4}$ S8 B.T.

7" Fir bears S.80°W. 20.0 ft. mkd. $\frac{1}{4}$ S8 B.T.

I DO NOT BELIEVE THIS TO BE THE TRUE COR. July 14-1958

John H. Markham, Jr., Robert M. Thompson
With: R. G. Boyd
For Stomar Lbr. Co. C. S. File No. 42/236
May 1, 1958
C.S. File No. 42/356

Section Corner to Sections 10, 11, 15, & 14. **135**

I find Orig. D. Fir BT. N.49°E., 30 lks; a cut sump W/scribe open.

A renewed BT. 18" D. Fir (must be S.33°E. to agree with others) 54 lks.

A dead, rotted 5" Oak, O.K. on bearing (N.70°E. 80 lks) is actually
4.0 ft. further.

A 4" W. O. N.40°W., 63 lks. - O.R.

Other new & old BT's (5) Rotted out.

I set a 2"x 2"x 4' Scribed Oak Stake & Scribe:

15" D. Fir, N.75°50'E., 14.8 ft. **195**

RE-RENEWED, SEE CORNER NO. 195

$\frac{1}{4}$ Section Corner to Sections 11 & 12. **136**

Found - Rock with $\frac{1}{4}$ " Cut in West Face.

Fir Stump, now 24" (uprooted & down) N.69°W. 7.9 ft. Stump has
been cut open to expose scribing "BT" in perfect condition.

Fir Stump, now 29", S.57°E. 17.8 ft. Bark is nearly all gone
from N. W. Face of Stump & no definite scars were visible.

Set Brass Cap at Corner beside Rock Mkd: "County Surveyor's Office, 1958
T30S R4W $\frac{1}{4}$ S11/S12"

Blaze & Scribe:: 15" Incense Cedar S.82°W. 81.9 ft. $\frac{1}{4}$ S11 CS BT".

All scribed in one blaze. Top of blaze 3' from ground.

16" Incense Cedar S.10°E. 38.8 ft. $\frac{1}{4}$ S12 CS BT".

James W. Byron, Deputy
M. Godfrey
S. Blouw
July 30, 1958
C.S. File No. 49/45