

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 4 W. R.W.W.M.

ROXE-CHAPMAN CO., EUGENE, ORE. 21881

North $\frac{1}{4}$ Corner to Section 2.

Found - 1" Pipe at Corner & Frear's BT's: 8" Fir S.45 $\frac{3}{4}$ °W. 5 lks.,
Tree has been pushed down the hill about 60 feet, fd.scrbng.
New BT: 10" Cedar S.2°W. 14.0 ft. scribed $\frac{1}{4}$ S2 CS BT.
6" Cedar S.23°E. 22.6 ft. scribed $\frac{1}{4}$ S2 CS BT.

187

James W. Byron, Deputy
Mike Darby & Wm. Stoffel
May 1963
C. S. File No. 52/126

Corner to Sections 34 and 35 only, T29-4W.

Found - 1" I. Pipe at Corner - 10" Pine N.50°E. 25.0 ft., shows scrbing.
Fir Bearing Tree to N. W., now stump
New BT: 13" Laurel N.33°W. 62.2 ft. scribed S35 T29S R4W CSBT.

188

Corner to Sections 4 and 3 only.

Found - 1" I. Pipe at Corner and 20" Cedar S.5°E. 31.0 ft., scribing
visible. S. W. Bearing Tree, now stump. - SEE COR. #150
New BT: 8" R. Fir bears S.56°W. 51.3 feet scribed S4 T30S R4W CS BT.

189

$\frac{1}{4}$ Corner to Sections 2 and 11.

Found - Jasper Bounder at Corner & 6" under surface. - SEE COR. #3
26" W.Oak N.75°E. 13.2 ft. shows scribe marks on old face. REN #8
Trunk Section of 8" Prune Tree S.75°W. 14.5 ft. REN #3
Set - Brass Cap alongside Cor. Stone & Mkd: County Surveyor's $\frac{1}{4}$ S 2 T30S
Office, 1963 S11 R4W
Rescribe: 26" W.Oak N.75°E. 132.5 ft. $\frac{1}{4}$ S2 CS BT.
Note - Centerline County Road is South 37.3 ft.


190

$\frac{1}{4}$ Corner to Sections 10 and 15.

Found - Both Orig. BT's.: Orig. 20", now 26" W.Oak N.78 $\frac{1}{2}$ °W. 36.3 ft.,
shows scribe marks.
15", now 30" B.Oak S.19°W. 41.0 ft., shows good scar.
Iron Pipe set by Stewart not found. We do find base of old Stake.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S10 T30S R4W
Office, 1963 S15
Rescribe: Now 30" B.Oak S.19°W. 42.2 ft. Mkd: $\frac{1}{4}$ S15 CS BT.
Fence Corner Thus:

191

James W. Byron, Deputy County Surveyor
Mike Darby and Wm. Stoffel
June 1963
C. S. File No. 53/26



Section Corner to Sections 1 - 2 - 11 - 12.

Found - Brass Cap at Corner and All Bearing Trees. SEE COR. #108
S. W. Bearing Tree now stump
New BT: 12" Maple S.72°W. 57.0 ft. scribed S11 CS BT.

192

$\frac{1}{4}$ Corner to Sections 22 and 23.

Found - Iron Bar at Corner & in. N.-S. Fence Line. Both BT's. to
N.E. are O.K. S. W. BT. now stump. SEE COR. NO. 59
New BT: 12" R. Fir bears S.88°W. 30.0 ft. scribed $\frac{1}{4}$ S22 CS BT.

193

$\frac{1}{4}$ Corner to Sections 11 and 14.

Found - Both Orig. BT's. each shows good scribing.
Set - Brass Cap at Corner Mkd: County Surveyor's $\frac{1}{4}$ S11 T30S R4W
Office, 1963 S14
New BT's: 12" R. Fir bears N.74°W. 23.0 ft. scribed $\frac{1}{4}$ S11 CS BT.
16" R. Fir bears S.8°E. 23.0 ft. scribed $\frac{1}{4}$ S14 CS BT.
Note - Corner is on spur course N.45°W.

194

Section Corner to Sections 10 - 11 - 14 - 15.

Found - Orig. 18", now 20" R. Fir S.32°E. 35.6 ft., shows scars. #272
Orig. 10", now 20" Fir Stump N.49°E. 19.8 ft., shows good reverse scribing.
15" R. Fir N.76°E. 14.8 ft. shows good bark scribing (Thompson's BT.) SEE COR. #135
Set - Brass Cap at Cor. Mkd: County Surveyor's S10 | S11 T30S R4W
Office, 1963 S15 | S14
New BT: 20" R. Fir bears S.88°W. 17.5 ft. scribed S15 T30S R4W CS BT.

195

Fd. Fixed
1190 De Geor
M 109-47

RENEWED, SEE CORNER NO. #263

RENEWED, SEE CORNER NO. #272