

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

261

N. E. Corner D. L. C. No. 47.  
Found - 24" Oak S.48°E. 17.8 ft., scribe visible,  
"C47 CS" on old burnt fact, See. Ren.#30.  
5/8" Iron Rod at DLC Corner (No Record)  
20" D.Fir S.87°W. 22.4 ft. (No Record)  
22" Cedar N.44°E. 34.2 ft. (No Record)

2/17/72

John M. Powell  
J. Heritage  
2/17/72  
C.S. File 53/26

262

N.W. Corner D. L. C. No. 48.  
Found - 1/2" Iron Pipe at DLC Corner.  
Orig. 24" Oak Snag S.80°E. 17.2 ft., faint scribe  
visible(very possible 48)  
6" Laurel S.17°E. 14.2 ft., scribe visible,  
"DLC 47 CS BT"-Rescribed:" DLC 48 CS BT"  
20" D.Fir, now stump, S.75°W. 41.6 feet.  
New BT: 6" Laurel N.39°E. 25.8 ft. scribed"NW DLC 48 CSBT"  
Note-No trace of Ren.#4(1918) DLC #48.  
This corner lies E. of N-S Fence 6.0 ft. & 122.0 ft. South  
of the N.E. Cor. DLC #47.

263

Section Corner for Secs. 2, 1, 11 and 12  
Found - 8" R. Fir, now 16", bears N.15°E., 91.2 ft. Good scar and  
alive & well. Ren. #108 (#192)  
16" W. Fir stump bears N.58°W., 41.6 ft. No scribing visible  
but fit well for bearing and distance. Ren. #108  
12" R. Fir, now 19" bears S.65°E., 25.3 ft. Shows good scar  
and alive and well.  
36" R. Fir stump, bears S.6°E., 36.7 ft. No scribing visible  
but fit for bearing and distance. Stump is decayed & rotten.

No trace of any other monuments.  
Set - At the corner point, set 1" x 30" I.P. with brass cap stamped:  
Douglas County Surveyor 1976

T	30	S	R	4	W
	S	2	S	1	
	S	11	S	12	

New BT's- A 7" White Fir, bears S.45°W., 41.1 ft. marked "T30S R4W  
S11 CS BT" in a double blaze.  
A 16" White Fir, bears N.2 1/2°W., 59.6 ft. marked "T30S  
R4W S2 CS BT" in a double blaze.

Corner is 100 ft off Days Creek Rd. under a north-south fence  
bordering E.R. Halls pasture. Fence borders east side of pasture.

3/11/76

A. Victor Cangie  
Jim H. Cook  
County Surveyors Office  
March 11, 1976  
C.S. 59/8

RE-RENEWED SURVEYED CORNER #287

264

Corner Closing to Secs. 1 and 12 only. See Ren. #57 T 30-4  
and 1965 BLM resurvey  
Found: Original 29" D. Fir which bears N. 29°W., 14 ft. Visible  
scribing on previously opened SE blaze, NE face had been cut  
out. Alive but damaged.

Original 20" now 24" D. Fir which bears S. 80° W., 11 ft.  
Blaze healed over, tree alive and well.  
3/4" X 17 1/2" Iron Pipe set at corner point.

Set: At corner point determined by original BT's I set 1" X 30"  
Iron Pipe with Brass Cap stamped:

Douglas County Surveyor 1976  
T 30 S  
R W 4 | R W 3  
S 1 | S 7  
S 12

Replaced found 3/4" Iron Pipe in ground North side of Brass Cap.  
New BT's: 10" G. Fir bears N. 71° W, 79.3 ft. distance mkd. "T30S R4W  
S1 CC CS BT" in a double blaze.  
Compass Dec. 20° East.

A. Victor Cangie  
Peter L. Earle  
County Surveyor  
March 31, 1976  
C.S. 59/8