

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21801

268

Center 1/4 Corner for Sec. 3

Found - A 3/4" Iron pipe 22" in ground. Ren. #127
31" Madrone bears S.35°E., 34.2 ft. (Rec. S.41°E., 34.7 ft.)
with visible scribing in an almost healed double blaze.
A 33" Madrone bears N.87 1/2°E., 46.6 ft. (Rec. N.83°E., 48.0 ft.)
with visible scribing " /4 S3 T30S R4W" in partially
healed double blaze.

Set - 1" x 30" Iron pipe with brass cap 6" above ground marked
"Douglas County Surveyor" T 30 S R 4 W
S 3
C 1/4
1977

No new accessories.

10/11/77

269

Section corner for Secs. 27, 26, 34 and 35.

Found - A 1/2" x 15" Iron rod bent over and pushed out of position Ren. #145
by excavated material from road construction, buried 3 1/2 ft.
A 34" Fir stump, now 42", bears N.57 3/4°E., 45.5 ft. (OBT).
A 16" Maple now size indeterminate, down and badly rotted, bears
approx. N.44 1/2°W., 49.5 ft. (OBT).
A Yew snag, 18" dia., 20 ft. high, bears N.48°W, 58.0 ft. Found
scribe marks "S27 BT" in double blaze.
A 4" now 5" Chinkapin, uprooted, root hole bears approx.
S.46°E., 48.0 ft. found double blaze and scribing "S35-T".

Set - A 1" x 30" I.P. from fir stump OBT and Yew snag BT with brass
cap set flush with ground, marked: "Douglas County Surveyor"

T 30 S R 4 W
S 27 | S 26
S 34 | S 35
1977

R. B. Kimberling
M. W. Cline
October, 1977
C.S. 59/40
Douglas Co. Surveyors Office

Set 1/2" I.R. at north edge of BC flush with top. Terraced a 10 ft. dia.
area around corner to prevent erosion.

New BT's- A 12" Maple bears N. 2 1/2°E., 23.4 ft. double blazed and scribed
"T30S R4W S26 CS bT"

A 4" Fir bears N.35°W., 26.9 ft. double blazed and scribed
"T30S R4W S27 CS BT"

A 4" Alder bears S.76°W., 24.3 ft. bark scribed "T30S R4W S34 CS BT"

A 22" Maple bears S.11°E., 59.4 ft. double blazed and scribed
"S35 T30S R4W CS BT"

Corner is in old unit 80 ft. NE of Rd. #30-4-26.0 ft. 100 ft. west of
west edge of new unit.

10/17/77

270

Center 1/4 corner for Sec. 22

Found - BT's as recorded. Ren. #58
Reset corner from BT's with a: 5/8" x 30" Iron rod with alum. cap
mkd. "C 1/4 S22 P.L.S. 418 1978.

Burton W. Holt
For: Sun Studs Inc.
June 1978
C.S. 58/163

6/78

271

Section Corner for Secs. 17, 18, 19 and 20.

Found - A 20" Cedar, now 25" bears N.82°E., 104.0 ft. with visible
scribing " 7 T30S BT" in a partially healed single blaze.
A 20" Oak, now 24" bears N.28°W., 192.6 ft. (Rec. 186.4 ft.)
with well healed single blaze. Ren. #214

No monuments or orig. BTs found.

Set - At appropriate dist. and brg. from NE BT, and brg. from NW BT:
Set 1" x 36" iron pipw with brass cap 9" above ground and in
a mound of stone 6" x 16". Cap was stamped "Douglas Co. Surveyors"
T30S R-4W- 18 17 19 20 R 4 W 1978"

New BT's- A 6" Madrone bears S.81 1/2°E., 120.5 ft. scribed "S20 T30S R4W
CS BT" in a double blaze.

A 17" Red cedar, bears S.48 1/2°W., 173.4 ft. scribed "S19
T30S R4W CS BT" in a double blaze.

Corner located south approx. 530 ft. from SE cor. DLC No. 40, T30S R4W.

8/29/78

Karen Reed
F.C. Silagy
Doug. Co. Sur-
veyors Office
Aug. 29, 1978
C.S. 60/11

1-79