

Douglas County Surveyor's Record of
Government Corners Renewed

T 30

T. S. R 4

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 21881

William Ruppert
For: Tom & Larry
Michaels
Dec. 1980
M 79 - 65

1/4 Corner for Secs. 20 and 21 277
Found - Orig. BT, S.70°E., 171.6 ft. Scar & opened rotten face.
Markhan corner was destroyed by road construction. Ren. #100
Set - 1" x 16" iron pipe with 2 1/2" Brass cap marked T30S R4W
1/4 S20 S21 PLS 866 1980. Set 6" below ground on west
edge of road. Set 5 ft. steel fence post 0.5 ft. west.
Found - 30" B. Oak, N.70°E., 31.8 ft. Ren. #100
New BT - 22" W. Oak, N.13°30'W., 27.4 ft. scribed "1/4 S20 BT"
Fence corner bears N.56°W., 12.3 ft.

S.J. Flause
Deputy, Doug. Co.
Surveyors Office
Witness: T. Plouff
March 26, 1981
C.S. 61/19

12/80

Section corner for Secs. 25 and 36 only. (east) 278
Found - A 1963 2 1/2" brass cap on a 1" I.P. firmly set and protruding
15" from the ground. Cap is properly marked. Ren. #175
An orig. Red fir, 12" now a 24" DBH D. Fir snag approx. 45 ft.
tall bears S.48°W., 21.8 ft. Tree has blaze scars an "X": blaze
in the bark on the northeast side, and is bark scribed T30 R4W
S36 BT.
An orig. Red fir 8" now a 10" diam. 30" tall rotted Fir stump bears
N.46 1/2°W., 22.4 ft. Stump has old axe work, no scribing found.
A 14" R. Fir now a 14" DBH D. fir snag approx. 12 ft. tall bears
N.01°W., 40.8 ft. Tree has unhealed double blaze marked T30S
R4W S25 CS BT. (Rec. S25 T30S R4W CS BT)
Monument position is accepted.
New BT's-A 6" DBH D. Fir bears S.51 1/2°W., 31.0 ft. and is scribed T30S
R4W S36 CS BT on a double blaze.
A 7" DBH D. Fir bears S.65°W., 61.2 ft. and is scribed T30S R4W
S36 CS BT on a double blaze.
The tree from Ren. #175 and the new BTs are tagged with DCSO BT tags.

SEE GIS FILE
FOR 1981 BLM
ADMIN. SURVEY
INFO.

3/26/81

Southwest corner DLC #49 279
Found - 1" bolt with 1 3/4" hex head flush with pavement lying partially
on its side. Ren. #110
5" now 8 1/2" down partially rotten Oak with BT tag. Face & scribing
not visible because of condition of tree. Stump hole of BT
bears N.88°E., 24.3 ft. (rec. calls for S.88°W., but this falls
in road.)
Fence corner with yellow tag bears N.80°E., 18.2 ft. Fence runs
north, south and east.
New BT's- 42" white oak, bears N.32°E., 87.3 ft. scribed "SW CL 49 CS BT" in
double blaze.
5" white Oak, bears S.63°E., 18.6 ft. scribed "SW CL 49 CS BT"
in double blaze. Township and range were not scribed in order to
keep size of blaze smaller a land owners request.
5" oak bt is in R/W fence.

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
Debbie Stewart
May 7, 1981
C.S. 61/24

5/7/81

Sec. corner common to Sec's 14, 13, 23, & 24. 280
Found - 7/8"x18" I.R. per Ren #178, buried 1" below grnd.w/upper 6" bent to E.
BT's- 20" now 24" B. Oak per Resurvey bears N.4°E., 27.1-ft. Tree
shows good orig. scar plus good scar per Ren. #178. This
scar has been opened recently & has a scribed "O" visible.
Possible BT; 10" now 18" B. Oak with several small scars, bears
N.61°W., 20.0-ft. (Rec. N.61°W., 23.8-ft. per Resurvey). The scar
on this tree do not look like the scars on the other Oak BT.
This tree is being used as a fence cor., with wire on the side
that I would have opened to confirm if it is a BT or not.
Set - At the location of the 7/8" I.R., I set a B.C. protruding 8" out
of ground & marked: "Douglas Co. Surveyor T30S S14 S13 S23
S24 R4W 1981". 7/8" I.R. replaced along South side of cap.
New BT - 10" W. Oak scribed "T30S R4W S14 CS BT" in dble. blaze, bears
N.23°W., 52.6-ft.
Note - For sketch, see C.S. 61 / 29. 11/3/81

Gregory E. Quibell
Douglas County
Surveyors Office
Teresa Buley, witness
Nov. 3, 1981
C.S. 61 / 29