

Douglas County Surveyor's Record of
Government Corners Renewed

T 30

T. S.

R 4

R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 51851

287

Section corner for Secs. 1, 2, 11 and 12.
Found - 1976 County brass cap on 1 1/4" I.P. firmly set, protruding
5" from ground. Cap properly marked. Ren. #263
(Earlier monuments probed for, no evidence found.) (All original, 1854, BTs
searched for, no evidence found.)
Found- 1889, 1891 BT, 36" R. fir, now a decayed 38" DBH, 4 ft. tall
stump bearing S.06°E., 35.2 ft.; 33.7 ft. slope dist. to face
(Rec. S.6°E., 33.7 ft.) Tree has possible evidence of a
healed blaze. This is opened to reveal decayed interior of stump,
no evidence of face or scribing found.
8" R. Fir, now 20" DBH grand fir, bears N.15°E., 91.2 ft. Tree
has well healed double blaze. Ren. #108
16" W. fir, now 19" diam. 1 ft. tall decayed fir stump, bears
N.58°W., 41.6 ft. Tree has remains of lower blaze with scribing
"BT" visible. (brass plate found healed in lower blaze; now in
DCSO artifact display.) Ren. #108
12" R. fir, now 24" DBH D. fir bears S.67 1/2°E., 25.3 ft. (rec.
S.65°E., 25.3 ft.) Tree has well healed double blaze with no
scribing visible. Ren. #108
7" White fir, now a 9" diam. 12" tall white fir stump, bears
S.45°W., 39.7 ft. (39.7 ft. reduced from 40.6 slope dist.. Tag
on cut portion of tree with same date as Ren. #263 has dist.
mkd. as 40.6 ft.) Open portion of upper blaze has scribing "30
S 4" visible; there is also a lower healed blaze. Ren. #263
16" white fir, now a 17" DBH grand fir bears N.2 1/2°W., 59.6 ft.
Tree has marking "30SR4WS2 CS" visible in a partially healed
double blaze. Ren. #263
(No evidence found from Ren. #47 or new BT from Ren. #192)
New BT - 8" DBH douglas fir scribed T30S R4W S12 CS BT, on a double
blaze bears S.12°E., 17.0 ft.
Note - Monument lies approx. 100 ft. south of Days Creek Road #34.
Monument lies 3 ft. east of a north-south fence line.

11/15/84

288

1/4 Corner for Sections 25 and 26
Found - A 1981 BLM 3 1/4" dia. alum. disk firmly set flush with ground.
13" now 17" dia. I. Cedar partially healed single blaze with
illegible scribing visible, bears S.73°W., 202.6 ft. (agrees
well with record)
SE BT washed out by erosion of South Umpqua River.
No orig. evidence found.
New Accessories:
4" dia. yellow pine double blazed and scribed "X BT" bears
S.17 3/4°E., 43.0 ft.
NW stone foundation wall corner of wood framed house bears
S.6 1/2°W., 23.0 ft.
Corner lies in gravelled drive way 14 ft. west of river bank edge.

289

West SW Corner for DLC #47
Found - 1 1/2" I.D. iron pipe 9" below ground. Iron pipe leaning North
approx. 0.2 ft. from plumb. Probably set in Ren. #26 but not
found in Renewal report #245
DCSO brass cap on an I.P. set in Ren. #245 Not Found. Resident
(Jay Holms) believes cap was removed by road work.
Bearings and distances taken to plumb position of 1 1/2" iron pipe:
8" now 17" dia. W. oak with a previously opened lower blaze (no
scribing visible) and a fully healed upper blaze bears N.80°E.,
60.7 ft. Original BT. Agrees with record.
NW BT per Ren. #26 gone.
NE BT per Ren. #26 (N.86 1/2°E., 91.0 ft.) probably the same tree as
SE BT in Ren. #157 (S.86°40'E., 90.6 ft.) 18" now 33" dia. W.
Oak with a fully healed double blaze bears S.86 1/2°E., 92.2 ft.
(Rec. S.87°E., 91.0 ft. is a face measurement) Per Ren. #245
12" now 19" dia. W. oak with a fully healed double blaze bears
N.10 1/2°W., 54.9 ft. (Rec. N.8°W., 57.7 ft. taken to DCSO BC/IP.)
Per. Renewal No. 245
Set - None. Bearings and distances to the original BT and Renewal tree
per Ren. No. 157 fit well with record, therefore we believe 1 1/2"
I.P. to be at position of DLC corner as determined by G.G. Stewart
in Renewal #26.

3/29/88

S. J. Flause
R. W. Smith
Deputies, Douglas
County Surveyors
Office
November 15, 1984
C.S. 62/21

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
April 22, 1986
C.S. 62.34

FND. OK. 9/92
BY BROWN M115-57

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
March 29, 1988
C. S. 62/50