

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 5 R. W. W. M.

✓ $\frac{1}{2}$ CORNER ON WEST SIDE OF SECTION 7. 27
Set by proportional measurement. Drove 2" x 24" Pipe
24" underground with wooden plug. **SEE CORNER NO. 199**
An Apple 12" dia. bears N.15°E., 18 lks. scribed
 $\frac{1}{4}$ S.7 C.S.B.T.
A Black Oak 57" dia. bears S.45°W., 237 lks. scribed
 $\frac{1}{4}$ S.7 C.S.B.T.

✓ SECTION CORNER BETWEEN 6 and 7 on RANGE LINE. **SEE ALSO 39 28**
Set from Trees P. T. s as recorded on page 145 **204** renewed
Corners Book number 1. Bolt and Stone cone. Drove 1" x 36"
Pipe 26" in underground.

✓ $\frac{1}{2}$ CORNER BETWEEN 16 and 17. **SEE CORNER NO. 110 29**
White Oak 15" dia. bears N.42°E., 50 lks.
Black Oak 8" dia. bears N.25°W., 30 lks.

✓ INTERIOR "L" CORNER OF D.L.C. # 40, Isaac Bailey. 30
Set 8" x 8" Stone set in the ground. Standard Geological
Survey B.M. elevation 642 ft. set 1903 bears North 135.7 ft.
Center line of S.P.R.R. bears N.107.4 ft. point 19.9 ft.
from R.R. Station 1309+68.1 B.C. spiral No.1407

✓ N.E. CORNER OF COWLES D.L.C. NO. 41. 31
Set 1 $\frac{1}{2}$ " x 30" Steel bars 3 $\frac{1}{2}$ " Gear on end.
A 12" Seedling Apple tree bears N.77°E., 237.0 ft.
Bark blazed.
Set from W. $\frac{1}{2}$ Corner of Section 7, 30/5.

✓ S.E. CORNER OF D.L.C. NO. 41. - See LATER RENEWAL Cor. No. 145 by Byrn 32
Set 1" x 48" Square end steel bar driven in center of
old well on South side of Priner road, from **145**
A 40" Black Oak bears S.22°30'E., 82.0 ft.
Set from West $\frac{1}{2}$ Corner of Section 7, 30/5 and Bert Riddle's
testimony.

✓ S.W. CORNER OF ROBERTS D.L.C. 59. 33
Set hub for corner, (tacked) from stump of original.
Oak B.T. from hub marked
An 18" Fir N.32°W., 76.7 ft. - *fo. 5/1/78 c.s. 60/11*
No other tree in D.L.C. available.

✓ $\frac{1}{2}$ CORNER BETWEEN SECTIONS 22 and 23. **SEE CORNER NO. 155 34**
Found stumps of bearing trees, both trees were cut off
high and the tree to the N.W. shows the blazes for scribing
but is rotten in the heart. Someone drove a $\frac{3}{8}$ " Pipe in
center of a rock pile where corner is. Marked two new
trees
A 12" Fir N.29 $\frac{1}{2}$ °E., 42' marked $\frac{1}{4}$ S.35 C.S.B.T.
A 4" Laurel S.50°W., 18' marked $\frac{1}{4}$ S.32 C.S.B.T.

THE SOUTH $\frac{1}{2}$ CORNER OF SECTION 20. 35
I set a 4" squared Oak stake marked $\frac{1}{4}$ from the original
trees as described. The tree in the Northeast is standing but
dead and the tree to the Southwest is down and rotten, scab
shows scribing. **SEE CORNER NO. 202**
I marked two new trees
Fir 16" dia. bears S.58°20'E., 17.3 ft.
Fir 8" dia. bears S.22°30'W., 37.6 ft.

Ben B. Irving D.C.S. W.F. Byrnes
April 1919. It.
Wit. L. H. Smick
N.E. Richardson

June 27, 1885
E. B. Irving
Wit. N.E. Richardson
R. L. Irving
Dec. 13, 1884.

A. Boyer
Wit. N.E. Richardson
4/6/36
A. Boyer
Wit. N.E. Richardson
Bert Lane
4/6/36.

A. Boyer
Wit. Frank Hettner
J.P. Smick Geo. Bollenbeugh
Apr. 9, 1937. Mar. 9, 1939.

Geo. O. Baker
No. 77
Registered Land
Surveyor
c.s. 40/6