

County Surveyor's Record, Douglas County, Oregon

RENEWED GOV'T. CORNERS

T 30 S, R 5 W, WM.

CHAINS

1/4 COR. BET. SEC. 31 & 32. March 1946 54
 Set halfway bet. sec. corners, Set 3/4" iron pipe.
 Mark 12" W. Oak S 22°15' E 85.1 ft. SEE #99-96
 8" W. Oak N 47°15' W 97.5 ft.

1/4 COR. WEST SIDE SEC. 31 March 1946 55
 East side Sec. 36, T 30 S, R 6 W.
 Set 3/4" iron pipe.
 Mark 14" B. Oak N 53°00' E 54.4 ft. 222
 36" B. Oak S 49°05' W 38.8 ft.

1/4 COR. BET SEC. 27 & 28. Dec. 1945 56
 Find 16" Fir West 32.34 ft. (#17) SEE CORNER NO. 216
 Find Corner Stone
 Mark 18" Madrona N 70°56' E 47.6 ft.

S.W. COR DLC #51 Clark Dec 1945 57
 Find stump of Old B.T.
 Set 1 1/4" iron pipe.
 Mark 24" Fir N 71° E 27.4 ft. 127
 6" Madrona S 36° E 18.3 ft.

COR. 31-32-5-6- S. COR. 31&32 March 1946 58
 Set from Old B.T. stump.
 Set 3/4" Iron pipe. SEE
 Mark 12" Fir S 27°55' W 15.4 ft. Last CORNER
 12" Fir S 31°40' E 21.3 ft. ON PAGE
 30" Fir N 32°30' W 98.0 ft.
 7" Fir N 4°20' E 43.8 ft.

TOWNSHIP COR. SW Cor Sec 31 T 30 S, R 5 W March 1946 59
 SE Cor Sec 36 T 30 S, R 6 W
 NW Cor Sec 6 T 31 S, R 5 W
 NE Cor Sec 1 T 31 S, R 6 W
 Set by running West East and North
 Set 3/4" iron pipe. SEE CORNER NO. 221
 Mark 26" Fir N 81°28' E 16.0 ft.
 8" Cedar S 5°35' E 41.6 ft.
 18" Fir N 26°53' W 26.6 ft.
 26" Fir S 80°00' W 44.5 ft.

1/4 COR. SOUTH SIDE SEC. 31, ONLY. March 1946 60
 Set 40 chs. West from Sec Cor on line
 Set 1" iron pipe. SEE CORNER NO. 217
 Mark ~~#####~~ 8" Live Oak N.25°04'W.
 25.1 ft.
~~#####~~ 8" Live Oak S. 72°17'W.
 8.0 ft.

COR. 29-30-31-32 March 1946 61
 Found 2 old B.T. both dead. Set iron pipe.
 Mark 14" B Oak N 46°10' E 65.0 ft. SAME 209
 12" B. Oak. S 57°30' E 94.6 ft. #97
 30" B. Oak S 4°42' W 92.9 ft.
 38" B. Oak N 44°45' W 31.5 ft.

Closing CORNER SECTION 30 - 31. West side Sections. 62
 Drive 1 inch pipe for Corner.
 Find both old B.T.'s badly rotted, mark new B.T.'s. 223
 A 10" Fir N. 29° 00' E. 61.4 Ft.
 A 16" Fir S. 72° 22' E. 13.8 Ft.

1/4 COR. WEST SIDE SEC. 18 63
 Find 26" W. Oak N 80° E 115.5 ft. SEE C.S. 7/32(1923)
 Drive 5/8" axle shaft and mark new B. T.'s. - see M 20-23
 6" W. Oak S 87° 46' W 9.1 ft.
 6" W. Oak S 35° 43' E 14.6 ft.

Corner to Sections 31 and 32 only, T30S. R5W March 1946 Cor. No. 58
 Set from old B.T. Stump - Set 3/4" Iron Pipe.
 Mark 12" Fir S. 27°55' W. 15.4 ft. CORNER NO. 160
 12" Fir S. 31°40' E. 21.3 ft. REFER TO EVANS
 30" Fir N. 32°31' W. 98.0 ft. CORNER C.S. FILE
 7" Fir N. 4°20' E. 43.8 ft. No. 41/367-MARCH '55
 ALSO 1959 RENEWAL
 MAP M 1-9 C.S. 46/64

Geo. J. Wenderoth
 Dep. Co. Surv.

Geo. J. Wenderoth
 Dep. Co. Surv.

Geo. J. Wenderoth
 Dep. Co. Surv.

G. J. Wenderoth
 Dep. Co. Surv.
 October 1946.
 Witness.
 R. C. Head
 R. F. Pfaff.

G. J. Wenderoth
 Dep. Cnty Surv.
 C. L. Morley
 Witness
 April 1946