

Douglas County Surveyor's Record of
Government Corners Renewed

30

T. S.

5

R. W. W. M.

Northwest corner of J. Clark D. L. C. No. 51.
1 1/4 inch iron pipe, 1 BT.

108

Found Southeast corner Gazely D.L.C. No. 48:
Axle, 30 inch B. Oak, N.1°25'W.; 319.2 feet.
Map. Stub, N.51°54'E., 98.8 feet.

109

1/4 sec. corner to secs. 16 and 17.

110

Determined by O. B. T.s. - A 23 inch W. O. bears N.44°E., 33.0 feet dist.

O. B. T.
Found a 1 1/2 inch iron pipe at corner point, from which:
A 40 inch B. O. bears N.25°E., 65.0 feet dist, mkd. 1/4 S 165 B. T.
A 23 inch B. O. bears N.87°W., 33.0 feet dist, mkd. 1/4 S S 17 B. T.
A 22 inch B. O. bears S.42°E., 69.5 feet dist mkd. 1/4 S 16 BT.

Southeast corner D. L. C. No. 50.

111

Determined by O. B. T. - REN #4
At corner point set 1" X 30" Iron Pipe from which
A 17" B. O. windfall bears N.27°W., 9.2 feet dist. O. B. T.
A 6" La. bears N.75°W., 8.5 feet dist. fd scribe, O. B. T.
A 16" La. bears N.46°E., 3.5 feet dist. O. B. T. I rescribed Cl. 50.
A 10" Ced. bears S.36°E., 8.1 feet dist., mkd. D. L. C. 50 B. T.
Fence corner bears N.72°E., 8.0 feet dist. - fences run N - S - W - 1/4
corner to 27 & 28 bears North 377.0 feet.

1/4 corner to sections 11 and 12.

112

Found scribed Laurel post & Original B. T.
A 7" Fir (now 20") S.43 1/2°E., 8 lks. - (Good Condition).
Set 1/2" I. P., Fir stake alongside.

South 1/4 Section 12.

113

Found Laurel tree - blaze chopped out & rotted, no marks legible. Property
owners agreed to its use to fix South 1/4 corner of Section 12.
Set 5/8" Iron Rod for South 1/4 corner Sec. 12.
Blazed and scribed:
12" Laurel, N.5°E., 18.5 feet.
20" Laurel, N.85°E., 35.0 feet.
Both m'k'd. So. 1/4 S - 12 (Agr.) C. S. B. T.

1/4 corner sections 1, and 12.

114

Set a 5/8 inch iron rod from 10" Bl. Oak B. T.
Blazed and scribed New B. T.s:
30 inch Fir, N.8°W., 39.0 feet m'k'd 1/4 S - 1, C. S. B. T.
20 inch Fir, S.70°E., 56.3 feet m'k'd 1/4 S-12, C. S. B. T.

Section corner to secs. 12 & 13, T30S, R5W., and secs. 7 & 18, T30S, R4W.

115

Set 5/8 inch I. Rod from 2 original B. T.s.
Blazed and scribed new B. T.s:
30" Fir - N.34°E., 27.5 feet mkd. T30S, R4W., 5 - 7, C. S. B. T.
10" Pine - N.22°W., 18.1 feet m'k'd T30, R5, S-12, C. S. B. T.
20" Pine - S.15°E., 33.7 feet mkd. T 30, R 4, S - 18, C. S. B. T.

Closing corner to secs. 1 and 12.

116

Set a 5/8 inch Iron Rod from 2 original bearing trees:
A 7" Laurel (dead) - S.22°W., 35 lks.
A 40" Pine - N.66 1/2°E., 53 lks.
Blazed and scribed new B. T.s:
20" Fir, N.58°W., 25.4 feet, mkd. T 30 S, R 5 W., C. C. S - 1, C. S. B. T.
14" Fir, S.39 1/2°W., 25.2 feet mkd. T30S, R 5 W., C. C. S - 12, C. S. B. T.

Robt. M. Thompson
January, 1955.
File No. 41/339.

John H. Markham
Witness:
P. F. Willhoit
April 25, 1955.
C. S. File No. 41/387

John H. Markham Jr.
Work done for Canyon
Logging Co.
June 14, 1955.
C. S. File No. 42/19

A. R. Evans, Deputy County Surveyor
July, August, 1951.
C. S. File No. 45/69.

RENEWED, SEE CORNER NO. #267 (W.C.)
SEE #323 for COR.
SEE REN #130
CORNER NO. 189
CORNER NO. 236
CORNER NO. 176
CORNER NO. 179
CORNER NO. 174