

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 5 R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

(continued)

#150 Cont.

Original BT, 40" Fir, bark scribed, S.20°W. 37.0 ft.,
rescribed in bark, S 2 T 31 S R 5 W BT.
Set- 3" Square Dogwood Post.
4" Dogwood N.19°W. 7.3 ft. scribed S35 T 30 S R 5 W BT.
40" Fir, bark scribed, S 1 T 30 S R 5 W BT.
Rescribed in bark, 2 Original BT's, noted above.

151

1/4 Section Corner to Sections 9 & 10.
Found - Both Orig. BT's. & Corner Tree.
BT's. check bearings & distances, show good scars, I
do not open.
Corner Tree previously opened, shows good scribing "S".
Set Brass Cap alongside South edge of Corner Tree and Mark
Brass Cap County Surveyor's Office, 1959
1/4 S9/S10 T30S R5W.
New BT: 8" R. Fir bears N.46 1/2°E. 45.5 ft. scribed 1/4 S10 CS BT.

RE-RENEWED, SEE CORNER NO. 190

James W. Byron, Deputy
S. A. Bilow
April 24, 1959
C. S. File No. 49/107

SEE REN # 42

152

1/4 Section Corner to Sections 5 & 8.
Found - Axle under E. W. Fence and both BT's., bark scribed,
as recorded by Germond.
The N. W. BT., now Stump (distances to BT's. are on slope).
New BT: 10" W. Oak bears N.15 1/2°W. 75.8 ft. scribed 1/4 S5 CS BT.

FDOLPER WARE
3-87 CS58/272

153

Section Corner to ~~Secs. 22 & 21, T30S R5W~~, & Secs. 3 & 4, T31S R5W.
Found - Orig. 20", now 36" Fir S.38°W. 13.2 ft., previously
opened, shows good scribing "S 4 T".
Orig. 6", now 10" Fir Snag N.83°W. 11.9 ft., shows old
scar, face burned, no scribing found.
No evidence of other Original BT's.
Pointed Sandstone at Corner 12" x 12" x 18" above ground
marked 6 notches on South & 4 notches on East.
26" R. Fir, bark scribed, S 3 T31S R5W CC CS BT. bears
S.85°E. 28.8 ft.
R. Fir, bark scribed S 4 T31S R5W CC CS BT. S.35°W.34.0 ft.
Note - These last 2 trees scribed 10 yrs. or so ago.
New BT's: 15" R. Fir bears N.87°W. 17.2 ft. scribed S33 T30S R5W CS BT.
36" R. Fir bears S.38°W. 14.5 ft. scribed S4 CS (bark scribed BT)
80 ft. West to Creek.
55 ft. North to Creek.

CORNER
NOT COMMON
SEE 1966
DEPENDENT
RESURVEY

James W. Byron, Deputy County Surveyor
Milo Godfrey
C. Putnam
Surveyed For C. & D. Lumber Co.
July 23, 1959 - C. S. File No. 49/168

154

Section Corner to Sections 27, 28, 33, & 34.
Found - 2" Iron Pipe at Corner & Both Fir BT's. as recorded, 1937.
Now 30" B. Oak N.18°E. 17.2 ft., I do not open. (Ren. No. 72)
I rescribe 30" B. O. N.18°E. 16.7 ft., scribed S27 T30S R5W CS BT.
13" Cedar bears S.55°E. 54.5 ft. scribed S34 T30S R5W CS BT.

RE-RENEWED, SEE CORNER NO. 175

155

1/4 Section Corner to Sections 32 & 33.
Found - 1" Pipe. & 8" Laurel S.50°W. 18 ft., scribing all visible,
" 1/4 S32 CS BT".
Stump of Fir N.29 1/2°E. 42 ft., showing traces of scribing.
Remnants of Laurel Stumps N.25°W. 27.7 ft. & S.10°E. 19.1 ft.,
No scribing found. Stumps too far gone.
Blazed & scribed one New Bearing Tree:
8" B. Oak S.54 1/2°E. 31.4 ft. scribed "1/4 S33 CS BT."
Corner lies in Fence Corner - Fence runs North & West.

RE-RENEWED, SEE CORNER NO. 287

156

1/4 Corner to Sections 33 & 34 - Set by approximate measurement.
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1959
1/4 S33/S34 T30S R5W.
New BT's: 16" Cedar S.36°E. 54.0 ft. scribed 1/4 S34 CS BT.
18" Laurel North 2.0 ft. scribed 1/4 S33 CS BT.

RE-RENEWED, SEE CORNER NO. 331

COR.
INAPPROPRIATE
SET BY
BYRON
SEE FILE
4/11/59

Map M 15-33