

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 5 R. W. W. M.

KORE-CHAPMAN CO., EUGENE, ORE. 21881

157

Section Corner to Secs. 32 & 33, T30S R5W & Secs. 4 & 5, T31S R5W.
Found - All of Boyer's BT's. The S.W. BT, now snag only. All (SEE #7-T31-5)
show good scars and all check bearing & distance. 219
Also find 1/2" x 12" Iron Rod at Corner.
Set Brass Cap alongside Iron Rod & Mark Cap:

S32	S33	T30S
S 5	S 4	T31S R5W

New BT's: 16" R. Fir bears West 70.5 ft. scribed S32 T30S R5W CS BT.
9" Laurel " S.87°E. 79.2 ft. scribed S4 T31S R5W CS BT.
48" Cedar bears S.38°W.100.7 ft. scribed S5 T31S R5W CS BT.
Note: This area badly burned this year.

158

South 1/2 Corner to Section 32, T30S R5W.
Found - Brass Cap at Corner. - SEE COR. No. 10, T31-5W #106 IN T30.5
I obliterate the number 5 which refers to Sec. 5 & add
the word South. The cap now reads South 1/2 Corner Sec. 32.
I find both BT's. now dead.
Chisled 2" *(cross) & B. O. on South face of 5' x 5' dome outcrop,
bears N.48°E. 6.7 ft.
New BT: 10" R. Fir bears North 91.6 ft. scribed 1/2 S32 CS BT.
Note: This is in 1959 burned area, - SEE COR. #10, T31S, R5W
Bottom of draw 100' ± South of Corner.

159

S. W. Corner D. L. C. No. 45.
1" Iron Pipe from which :
32" Pine S.65°20'E. 411.5 ft.
18" Pine S.29°25'E. 350.6 ft. Surveyed for - Lee Kellor
Dec. 1954

160

Closing
Corner to Sections 31 & 32 only.
This area badly burned in 1959 forest fire. I find 1/2" Iron Pipe Ren #58
at corner. All BT's. now dead. No live trees in vicinity. #291
Set Brass Cap alongside Corner Iron Pipe & Mark: County Surveyor's
Office, 1959 S31/S32 T30S R5W
T31S
Blaze & Scribe 2 1/2" Fir Stump T30S R5W S32 CS BT. bears East 11.7 feet.
Note - Corner is 50 feet East of top of Ridge.
All Scribe Marks on both BT's. of 1954 renewal to South Cut off.
See Map File M 1 - 9, C. S. 46/64

161

1/2 Section Corner to Sections 19 and 20.
Found - 24", now 28" B.Oak N.69°E. 46.5 ft., previously opened, shows
scribe mkd. REN #11 + REN #36
Also find base of rotted Pine, now 16", that checks bearing &
distance for NE BT.
Also find, now 14" Laurel, bears N.62°E. 28.2 ft., shows good
scribing "1/2 S". I add "20 CS BT."
Set Brass Cap at Corner Mkd.: County Surveyor's Office, 1960
1/2 S19/S20 T30S R5W
New BT: 12" B.Oak bears N.25 1/2°W. 37.9 ft. scribed 1/2 S19 CS BT.

162

N. E. Corner J. Reynolds D.L.C. No. 58.
Falls 1' N. of centerline State Highway No. 42.
I scribe: 12" D. Fir N.82°10'W., 87.3 feet
14" Y. Pine N:25°50'W. 82.3 feet.

163

N. W. Corner Wm. Preston D. L. C. No. 62.
Found - 2 B.T's. per Wenderoth Survey, 1952. #92
1 1/2" Iron Pipe gone & B.T. to N. E. dead.
To renew I set 1" Iron Pipe from which:
I scribed: 24" Alder, N.64°30'E. 68.2 feet.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
Nov. 12, 1959
C. S. File No. 46/64
M 1 - 9

Geo. J.
Wenderoth
Map File
M 16 - 63

James W. Byron
Milo Godfrey
Clete Putnam
Dec. 28, 1959
C. S. File No. 46/64

James W. Byron
Milo Godfrey
Clete Putnam
Feb. 2, 1960
C.S. File No. 49/107

Done For Norman T.
Chappell
By Robert M. Thompson
Feb. 16, 1960
Map File M 17 - 18

FD. OK
4/9/64
Ca. Surveyor's
Office
C. S. 42/18