

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 5 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97401

$\frac{1}{4}$ Corner to Sections 25 and 36. 225
Found - Scribed Stake at Cor. & both BT's., See Ren. #141, except
24" Fir bears N.18°E. 30.0 ft., Not N.15°E. &
S. E. BT is now stump.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S25 T30S R5W
Office, 1963 S36
New BT: 7" Laurel bears S. 9°W. 32.7 ft. scribed $\frac{1}{4}$ S36 CS BT.

*see F.B. 103
Pg. 142
for B.T.'s*
 $\frac{1}{4}$ Corner to Sections 26 and 25. 226
Found - Orig. 24", now 36" Oak S.45°E. 82.5 ft., shows good reverse
scribing on section cut from tree.
Orig. N.W. BT. not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S26/S25 T30S R5W
Office, 1963
New BT: 9" W.Oak N.51°E. 45.9 ft. scribed $\frac{1}{4}$ S25 CS BT.
Note - We do not find Stake set at Corner, See Ren. #140.
We find 14" W.Oak N.59°W. 96.0 ft., not N.63°W. 97.0 ft.,
shows scribing.

RE-RENEWED. SEE CORNER NO. #304

N. E. Corner D.L.C. #58. 227
Found - 14" Pine N.26°W. 82.3 ft., shows good scribing.
Fir BT., not found, falls in area excavated for gas line.
Drove - PK Nails at Corner 1.0 ft. N. of Centerline of Hwy. #42 &
flush with surface, See Cor. No. 162.
New BT: 9" R.Fir bears S.69 $\frac{1}{2}$ °W. 105.0 ft. scribed NE DLC 58 CS BT.

*Fd PK NAIL
#1878. Russ
M 10-10*

Section Corner to Sections 25 - 26 - 35 - 36. 228
Found - 2 BT's., See Ren. #22. 22" Fir Stump S.65°E. 68.0 ft.,
we open & find good scribing.
N.W. BT., now stump, down & out of position, shows scribing.
No other BT's. found.
Note - Corner is under S.70°W. Fence Axle set at Cor., not found.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S26 | S25 T30S R5W
Office, 1963 S35 | S36
New BT's: 18" B.Oak bears N.23°W. 33.5 ft. scribed S26 T30S R5W CS BT.
16" W.Oak bears N.31°E. 68.0 ft. scribed S36 T30S R5W CS BT.
12" R.Fir bears S.13°W. 55.8 ft. scribed S35 T30S R5W CS BT.
6" Alder bears S.32°E. 18.4 ft. scribed S36 CS BT.

*for additional
B.T.'s
see F.B. 103
Pg. 142*

Section Corner to ~~Secs. 35 & 36, T30-5W.~~ & Secs. 1 & 2, T31-5W. 229
Found - 3" Sq. Stake at Corner & BT's. as recorded in Ren. #150.
Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S36 T30S R5W
Office, 1963 S2 | S1 T31S
No new Bearing Trees. (NOT COMMON - SEE 1966 DEPENDENT RESURVEY)

$\frac{1}{4}$ Sec. Cor. to ~~Sec. 36, T30-5W.~~ & Sec. 1, T31-5W. 230
Found - Both Orig. BT's. Orig. 6", now down 10" Laurel N.55°W. 13.9 ft.
We open & find good scribing "BT".
Orig. S. E. BT. shows old axe work. NOT COMMON
Corner Stone not found, Corner is on steep East Slope. SEE 1966 DEPENDENT RESURVEY
Set - $\frac{3}{4}$ " I. Rod at Corner & New BT's. as follows:
7" R.Fir bears N.20°W. 16.8 ft. scribed $\frac{1}{4}$ S36 CS BT.
8" R.Fir bears S.35°W. 17.2 ft. scribed $\frac{1}{4}$ S1 CSBT.

$\frac{1}{4}$ Sec. Cor. to ~~Sec. 35, T30-5W.~~ & Sec. 2, T31-5W. 231
Found - Orig. 12", now 20" Laurel, S.10°E. 21.0 ft.
Orig., now 20" Laurel Stump N.15°W. 17.8 ft.
We open S.E. BT. & find good scribing "T".
New BT's - 13" Cedar bears S.38°E. 28.0 ft. scribed $\frac{1}{4}$ S2 CS BT.
22" Laurel bears N.25°W. 20.0 ft. scribed $\frac{1}{4}$ S35 CS BT.
Note - Corner is on West slope, 100.0 ft. East of small stream.

James W. Byron, Deputy Co. Surv.
Mike Darby and Jim Halterman
November - December 1963
C. S. File No. 53/26