

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30 T. S. R 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Cont. from last page -

281

An 18" Fir now an 18" stump with scribing "5 CS S36 BT" visible on an open double blaze bears N.27°W., 26.6 ft. (Rec. N.26°53'W., 26.6 ft.)

A 26" now 28" D. Fir alive with well healed double blaze bears S.80°W., 44.5 ft. (Rec. S.80°00'W., 44.5 ft.)

Bearing trees marked by J.W. Byron, 1963, Ren. #221 referencing monument set by Wenderoth:

A 14" Maple alive with well healed single blaze bears North 37.6 ft

A 6" now 10" D. Fir alive with well healed double blaze bears N.70°E., 30.9 ft.

We chop out and destroy entirely all markings found on Wenderoth's 1946 bearing trees and on Byrons 1963 BT's. We leave the I.P. set by Wenderoth at its found location.

6/4/79

1/4 Corner for Secs. 29 and 32

282

Found - A 1" I.P. set by Markham as noted in the County Surveyors records C.S. 40/250 Ren. #81

From which:

An Orig. D. Fir, 30" now a low cut stump bears S.60°W., 55.4 ft. (Rec. N.60°W., 55.4 ft.) No scribing found

An 18" Fir, now a snag bears S.24°E., 10.2 ft. Open blaze to find scribe "1/4 S32 CS BT" Ren. #132.

A 13" Fir, now a 14" snag bears N.51°E., 8.2 ft. Open blaze and find scribing "1/4 S29 CS BT" Ren. #132.

A 14" Fir, now uprooted bears S.5°W., 33.0 ft. Open blaze and find "BT". Ren. #208.

Contacted J.H. Markham, Jr. about the brg. of S.60°W., to orig. BT. Received an unsatisfactory explanation for using such brg. Reposition the corner at proper brg. and dist. from orig. Fir, N.60°W., 55.4 ft.

Set - A 1" x 36" I.P. with brass cap stamped "Douglas County Surveyor" T30S R5W 1/4 S29 S32 1979.

New BT's- A 6" Madrone scribed "1/4 S29 CS BT" in double blaze bears N.1 1/2°E., 13.4 ft.

A 9" Madrone scribed "1/4 S32 CS BT" bears S.67 1/2°W., 29.1 ft.

A PK Nail set in Northerly face of conglomerate stone outcropping 3 ft. high bears S.28 3/4°E., 4.18 ft.

Note: Found 1" I.P. set by Markham bears N.0°1'05"W., 55.4 ft. dist. We leave the pipe set by Markham undisturbed. We obliterate the scribing on the trees which reference this position.

7/3/79

283

1/4 Corner for Sec. 31 only. (South)

A careful search of the area revealed no trace of the original corner (Ford 1854) or any remains of Pine or Black Oak trees. We therefore determine a corner location by single proportionate measurement along the south boundary fo T30S R5W. A corner established by Wenderoth in 1946 which purports to be the identical corner which we are now establishing bears S.86°48'15"E., 390.63 ft. from our 1979 corner location. Thorough examination of Wenderoth's narrative of survey indicates an improper use of proportionate measurement resulting in an incorrect corner location.

SET - At the true corner point as determined by our 1979 survey, WE SET a 1"x36" Iron pipe, 35 inches in the ground on a steep and rocky northwest slope, with brass cap attached marked: Douglas County Surveyor T30S R5W 1/4 S31 1979

AND MARK THE FOLLOWING BEARING TREES: T31S

A 6" Live Oak, scribed "1/4 S31 CS BT" on a double blaze bears N.41 3/4°E., 7.5 ft.

An 8" D. Fir, scribed "1/4 S31 CS BT" on a double blaze bears N.50 1/2°E., 46.4 ft.

An 18" D. Fir, scribed "S6 CS BT" on a double blaze bears S.27 3/4° E., 35.3 ft.

We now return to Wenderoth's 1946 corner location and find the following evidence - A 1" Iron pipe, firmly set and extending 18" above ground

From which: The remains of Wenderoths BT's Ren. #60 are located as follows:

An 8" now 8" Live Oak, alive and in poor condition with previously opened and obliterated blazes, no scribing found, bears N.25°04'W., 25.1 ft.

An 8" now 9" Live Oak, alive and in poor condition with previously opened and obliterated blazes, no scribing found bears S.72°17'W 8.0 ft.

CONT. NEXT PAGE

Doug. Co. Surveyors Off.  
Larry E. Monrean  
Karen Reed  
Vicki Woodral  
July 3, 1979  
RM 3 - 26  
C.S. 61/3

Fd 7/90  
M112-4