

Douglas County Surveyor's Record of  
Government Corners Renewed

T 30

T. S.

R 5

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

291

CONT - - - - -

- New BT's - A 14" D. Fir bears N.45°W., 39.7 ft. scribed "T30S R5W S31 CS BT" in a double blaze (face bears S.20°E.)  
 A 9" D. Fir bears N.8 1/2°W., 45.4 ft. dist. scribed "T30S R5W S31 CS BT" in a double blaze (face bears S.10°W.)  
 A 9" Live Oak bears N.30°E. 5.1 ft. dist. scribed "T30S R5W S32 CS BT" in a double blaze (face bears west)  
 A 14" D. Fir bears N.84 1/2°W., 38.8 ft. scribed "T30S R5W S31 CS BT" in a double blaze.

This corner which was proportioned in 5/24/79, had to be moved due to the finding of the original township corner, therefore the faces of the bearing trees face the proportioned corner site. New bearings and distances are herein recorded and bearings of faces are stated per bearing tree.

We return to Wenderoth's corner and find the following:

- A 3/4" I.P. (C.S. 39/118) bent, with 1" I.P. and brass cap alongside extending 14" above ground marked: County Surveyors Office T30S R5W S31 S32 T31S R5W

and the remains of Wenderoth's BTs:

- A 12" Fir, now a 14" diam., 10 foot high snag with open blazes, all scribing previously obliterated, bears S.26 1/2° W., 15.4 ft. (Rec. M20-24, S.27°55'W., 15.4 ft.)  
 A 12" Fir, now a 15" diam., 15 foot high snag with open blazes all scribing previously obliterated bears S.33°E., 22.0 ft. (Rec. M20-24, S.31°40'E., 21.3 ft.)  
 A 30" Fir, now a 26" stump with scribing "BT" visible on unhealed blaze bears N.32 1/2°W., 98.0 ft.  
 A 7" Fir now an 8" windfall broken off two feet above ground with well healed double blaze. We open and find scribing "RS S32 BT" bears N.4°20'E., 43.8 ft.

and Byrons BTs Ren. #160

- A 24" Fir stump with scribing "T30S R5W S32 CS BT" visible bears S.85°E., 11.7 ft. (Rec. East 11.7 ft.)

There is no trace of any black oak trees or stumps in the vicinity of Wenderoth's corner. We remove all found scribing from the bearing trees and obliterate the markings on Byron's brass cap at Wenderoth's corner location.

6/12/79

292

NE 1/16 Corner Sec. 31

Found - A 2" I.P. set by G. Wenderoth in 1946 as recorded on map # M 20-24 as filed in the records of the Douglas Co. Surveyors office. A review of the filed map indicates that an improper method of subdividing the section was used and that we cannot agree with this point as the proper NE 1/16 corner of Sec. 31.

Two bearing trees referencing the iron pipe set by Wenderoth were found as follows: A 14" W. Oak now 18", has a partially healed double blaze with some scribing visible bears N.3 3/4°E., 41.7 ft. to center and 41.0 ft. to face. (Rec. N.4°20'E., 41.0 ft.)

A 9" now 12" W. Oak has been cut down. the trunk has a well healed double blaze. The stump bears S.29°E., 55.2 ft. (Rec. S.28°15'E., 55.0 ft.)

Set - At position of the NE 1/16 S31 as properly determined by survey WE SET an iron pipe 1" x 36", 34" into the ground with attached brass cap marked "Douglas County Surveyors T30S R5W NE 1/16 + S31 1979". The 2" I.P. by Wenderoth bears S.81°30'30"E., 96.35 ft.

New BT's- A 20" W. Oak scribed "NE 1/16 S31 CS BT" on a double blaze bears S.58°W., 18.3 ft.

A 8" W. Oak scribed "NE 1/16 S31 CS BT" on a double blaze bears S.68 1/2°E., 38.8 ft.

Note: Monument is located 26 ft. north of an east west fence.

7/17/79

Douglas County Surveyors Office  
 Karen Reed - Gary Langlitz - Ed Monrean  
 P. Earle - Vicki Woodrall  
 June - July 1979  
 RM 3 - 26  
 C.S. 61/3

Fd 7/90  
 M112-8

(next page)