

Section corner to secs. 7, 8, 17 and 18.

97

Location of corner determined by O.B.T.s:

60 inch Fir, N.50°E., 34.0 feet, O. B. T. - fd scribe.

15 inch La. snag, S.59°E., 16.5 feet, O.B.T. - fd. scribe.

14 inch Fir, S.41°30'W., 7.2 feet, O. B. T. - fd. scribe. *SEE COR. #38*

At corner point fd. 4 inch x 4 inch scribed wood post. I set an iron pipe with brass cap in concrete mkd. T30S R6W, 7, 8, 17, 18, 2880 1957, from which:

6 inch Fir bears N.21°W., 25.2 feet mkd. S 7 R 6 W, B.T.

15 inch Cedar bears N.86°W., 32.0 feet mkd. S 18 R 6 W, B.T.

11 inch Fir, bears S.33°W., 18.0 feet mkd. S 18 B.T.

12 inch Fir, S.18°30'E., 43.6 feet mkd. S 17 B.T. *183*

98

1/4 corner to secs. 8 and 17.

Location of corner determined by O. B. T.s:

30 inch Fir bears N.52°W., 39.0 feet - O. B. T. - fd. scribe. *SEE COR.*

20 inch Fir bears S.61°W., 61.0 feet - O. B. T. - fd. scribe. *#39*

At corner point found 4 x 4 wood post scribed. I set an iron pipe with brass cap in concrete marked 1/4 S T30S R6W S8 S17 2880, 1957, from which:

10 inch Fir bears S.68°W., 30.3 feet mkd. 1/4 S 17 B.T.

10 inch Cedar bears S.17°30'W., 32.2 feet mkd. 1/4 S 17 B.T.

7 inch Cedar bears S.80°E., 27.4 feet mkd. 1/4 S 17 B.T.

12 inch Fir bears N.34°E., 48.6 feet mkd. 1/4 S 8 B.T. *182*

Corner lies on steep north slope - Road bears south 1010 feet on top of Mtn.

99

Section corner to secs. 8, 9, 16 and 17.

Location of corner determined by O. B. T.s::

40 inch Fir snag bears N.40°W., 11.0 feet, O. B. T. - fd. scribe.

44 inch Cedar, S.33°W., 118.0 feet, O. B. T. - fd. scribe. *REN. #40*

22 inch Pine, S.34°E., 62.0 feet, O. B. T. - fd. scribe.

45 inch Fir, N.35°E., 90.0 feet, O. B. T. - fd. scribe.

At corner point found 6 inch X 6 inch scribed post in large mound of stone. I set an iron pipe with brass cap in concrete mkd. T30S R6W, 8-9-16-17, 2880, 1957, from which:

13 inch Fir bears N.57°E., 48.3 feet mkd. S 9 B. T.

9 inch Fir bears S.12°E., 37.1 feet mkd. S 16 B. T.

15 inch Fir bears S.46°W., 41.4 feet mkd. S 17 B. T.

6 inch Fir bears N.73°W., 33.2 feet mkd. S 8 B. T.

100

Section corner to secs. 2, 3, 10 and 11.

Location of corner determined by O. B. T.s:

A 50 inch Fir bears N.67°W., 19.2 feet - O.B.T.

A 20 inch La. bears S.15°E., 14.2 feet - O. B. T.

I rescribed S 11 T30S R6W, B.T.

At corner point found 4 inch x 4 inch wood post and set 2 1/2 inch x 24 inch iron pipe, from which:

A 30 inch La. bears N.6°E., 36.3 feet distant mkd. S 2 T30S R6W, B.T.

An 18 inch La. bears N.61°30'W., 55.2 feet distant mkd. S 3 T30S R6W, B.T.

A 22 inch La. bears S.76°W., 58.0 feet distant mkd. S 10 T30S R6W, B.T.

A 25 inch B. O. bears S.10°E., 88.2 feet distant mkd. S 11 T30S R6W, B.T.

A fence bears South 154.0 feet at edge of large opening - fence runs NW & SE.

Corner lies on top of main ridge. *FD-H. NORTHCRAFT - 1974-M 54-13*

Witness corner to secs. 25, 26, 35 and 36.

Placed a stake 311 feet north of section corner to secs. 25, 26, 35 and 36 for witness corner. Later, I drove a 1/2 inch iron rod at the stake, from which:

A B. Oak, 29 inches in dia., bears S.58°W., 20.5 feet dist. marked WITNESS COR BT 1543.

ERROR - THIS CORNER IS IN T 32 S, R 6 W.

John H. Markham Jr.
Done for Hanna Coal & Ore. Co.
June 28, 1957
July 1, 1957
C. S. File No. 42/273.

John H. Markham Jr.
Done for Steamar Lbr. Co.
June 26, 1957
C. S. File No. 42/274.