

Douglas County Surveyor's Record of  
Government Corners Renewed

30

T. S.

6

R. W. W. M.

KOKS-CHAPMAN CO., EUGENE, ORE., 21881

James W. Byren  
M. G. & C. P.  
May 23, 1960  
C.S. 52/25

continued - - -

120A

Blazed & Scribed 2 New Trees;

9" Fir S. 2°E. 79.2 ft. Mkd: "T31S R6W S3 CS BT".

9" W. Oak S. 10°W. 97.4 ft. Mkd: "T31S R6W S4 CS BT."

No trace of Orig. BT's. except Stump Holes & a few remnants of charred wood.

Note - All trees in immediate vicinity, including B.T.'s.) are badly damaged by Fire in 1959.

Section Corner to Sections 25, 26, 35, and 36.

121

Found - 3 Orig. BT's. & all four of Markham's BT's. - See Cor. #51

Also N. S. Fence 2' East of Corner.

Orig. NW BT., now rotted Stump, but shows good reverse scribing "BT". Orig. SW BT., now 24" W. Oak, center rotted. Orig. SE BT. shows good scar.

Markham's BT's. are bark scribed and his NW BT now low cut Fir Stump.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

S26 | S25  
S35 | S36

T30S R6W

New BT's: Rescribe, now 8" Laurel S. 70°W. 9.5 ft. T20S R6W S35 CS BT.

28" B. Oak S. 42°E. 58.7 ft. (Orig.) scribed T30S R6W S36 CS BT.

9" W. Oak N. 52°W. 57.5 ft. scribed T30S R6W S26 CS BT.

10" W. Oak N. 3°E. 40.5 ft. scribed T30S R6W S25 CS BT.

Section Corner to Sections 35 and 36.

122

Found - Orig. 18" B. Oak S. 49°E. 38.9 ft. This tree is now 28".

It showed two good scars. I open to old faces which are now partly rotted, but I believe we found reverse scribing, parts of "BT". Call to North checks O.K.

No trace of S. E. Orig. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's Office, 1960

1/4 S35/S36 T30S R6W

New BT's: 8" W. Oak bears S. 28°E. 31.5 ft. scribed 1/4 S36 CS BT.

6" W. Oak bears N. 63°W. 6.2 ft. scribed P S35 CS BT.

FD 3/86  
By: D. Bantz  
M 101-1

Sec. Cor. to Secs. 7 & 18, T30S R6W & Secs. 12 & 13, T30S R7W.

123

Found - Orig. 20", now down 30" Laurel, N. 89°W. 36.3 ft., shows good reverse scribing "B" "2".

Orig. 20", now 30" Laurel S. 25°W. 49.5 ft., center rotted.

Orig. 7", now down & rotted 12" Laurel N. 79°E. 28.4 ft.

No trace of Orig. S. E. BT. found.

Set Brass Cap at Corner Mkd: County Surveyor's

S12 | S7

T30S.

New BT's: R7W S13 | S18 R6W

14" R. Fir bears N. 18°W. scribed S12 T30S R7W CS BT.

12" R. Fir bears N. 20°E. 15.5 ft. scribed S7 T30SR6W CS BT

8" R. Fir bears S. 23°W. 17.8 ft. scribed S13 T30S R7W CS BT.

8" R. Fir bears S. 29°E. 26.8 ft. scribed S18 T30S R6W CS BT.

FD. 1977  
BLM ADMIN. SURVEY  
SEE GIS FILE

S.W. Corner Section 31. - as determined by O.B.T's:

124

23" La. N. 45°W. 134.0 ft. O.B.T.

24" La Snag N. 38°E. 100.0 ft. O.B.T.

30" La. Snag S. 60°E. 18.0 ft. O.B.T.

At Corner Point Set 3/4" x 30" I. P. from which:

8" Fir bears South 53.4 ft. dist. mkd. S6X BT.

Large Rock 6'x6'x10' bears S. 18°W. 33.0 ft. dist. at North Face.

5" Fir S. 85°W. 13.8 ft. mkd. S1 BT.

6" Fir N. 15°W. 9.0 ft. mkd. S36 BT.

6" B.O. N. 72°E. 26.2 ft. mkd. S31 BT.

FD. OK BY SMALLEY  
7/92 M112-52

Corner to Sections 30 and 31. - as determined by O.B.T's:

125

38" Pine N. 70°W. 20.4 ft., fd. scribe, O.B.T.

At Corner Point Set 3/4" x 30" I. R. from which:

7" Pine bears N. 6°W. 9.0 ft. 1/4 S30 B.T.

18" Pine bears N. 52°E. 26.2 ft. 1/4 S30 B.T.

7" Cedar bears S. 14°E. 23.8 ft. 1/4 S31 B.T.

14" Pine bears S. 39°E. 60.6 ft. 1/4 S31 B.T.

FD. OK 7/92  
M. SMALLEY M112-52

for additional B.T.'s  
see FB. 103  
pg. 140

James W. Byron, Deputy  
Milo Godfrey  
Clete Putnam  
July 8, 1960  
C.S. File No. 52/25

John H. Markham  
Wit. J. R. Markham  
For Stomar Lumber Co.  
July & August, 1961  
C. S. File No. 42/288