

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

170

$\frac{1}{4}$  Section Corner to Sections 10 and 11.

Found - Orig. 18", now 40" Pine S.25°W. 108.2 ft., prev. opened,  
shows good scribing "S".

Orig. N. E. BT., not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

$\frac{1}{4}$  S10/S11 T30S R6W

New BT's: 14" Pine bears S.20°E. 24.4 ft. scribed  $\frac{1}{4}$  S11 CS BT.

15" Pine bears N.27°W. 56.5 ft. scribed  $\frac{1}{4}$  S10 CS BT.

171

Section Corner to Sections 1 - 2 - 11 - 12.

Found - I. P. & Rock Mound at Corner.

Find Bearing Trees as Recorded Ren. No. 17, except  
now 16" R.Fir bears N.75°W., not N.85°W. 25.7 ft.

S. E. Bearing Tree, now dead.

Note - 26" Pine to S.E. shows scribing on old face but by Ring  
Count was scribed about 60 years ago.

Corner agrees with Call to Stream (66 ft. West).

We find no Orig. BT's, but this is an area with right species.

New BT's: 14" R.Fir S.85°E. 17.6 ft. scribed S12 T30S R6W CS BT.

16" R.Fir bears N.41°E. 23.8 ft. scribed S1 T30S R6W CS BT.

172

$\frac{1}{4}$  Corner to Sections 11 and 12.

Found - Both Bearing Trees, see Ren. #18, except, now 14" Cedar  
bears S.46°E., not S.54°E. 54.1 ft.

S. W. Bearing Tree O.K. for bearing & distance.

Do not find I.P. set at Corner.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

$\frac{1}{4}$  S11/S12 T30S R6W

Note - Corner falls about 4 ft. south of old fence corner.

173

N. E. Corner D. L. C. No. 40.

Found - Boulder at Corner &  $1\frac{1}{2}$ " I.P. alongside Boulder & marked  
40 with small + on top.

44" Oak Stump with old axe work, center rotted, no

scribing, bears N.72 $\frac{1}{2}$ °E. 40.3 ft. See Ren. No. 5.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

N.E. DLC 40 T30S R6W

New BT's: 16" Triple Cedar S.21 $\frac{1}{2}$ °E. 57.0 ft. scribed NE DLC 40 CS BT.

30" Maple bears N.73°W. 56.6 ft. scribed NE DLC 40 CS BT.

174

N. W. Corner D. L. C. No. 37.

Found -  $\frac{3}{4}$ " I.P. at Corner & under old E. - W. Fence. REN. #20

Now 30" Fir Stump N.15°W. 13.2 ft., shows good bark

scribing "B". S.E. BT. down.

New BT's: 17" B.Oak bears S.34°E. 62.9 ft. scribed NW DLC 37 CS BT.

15" Maple bears N.60°E. 7.0 ft. scribed NW DLC 37 CS BT.

10" R.Fir bears N.82°E. 36.4 ft. scribed NW DLC 37 CS BT.

175

Section Corner to Sections 19 - 20 - 29 - 30.

Found - 15", now 34" Sugar Pine N.5°E. 28.4 ft., prev. opened,  
shows good scribing.

S.E. BT. prev. opned, shows good reverse scribing.

N. W. & S. W. BT's. not found.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R6W S19 | S20  
Office, 1964 S30 | S29

New BT's: 10" Laurel bears S.52 $\frac{1}{2}$ °W. 51.0 ft. scribed S30 T30S R6W CS BT.

22" R.Fir bears S.25°E. 10.5 ft. scribed S29 T30S R6W CS BT.

20" R.Fir bears N.11°W. 48.5 ft. scribed S19 T30S R6W CS BT.

176

S. E. Corner D. L. C. No. 40.

Found - Both BT's. as recorded in Cor. No. 73. Also  $\frac{1}{2}$ " I.P. at Corner.

Set - Brass Cap at Cor. Mkd: S.E. DLC 40 T30S R6W

County Surveyor's Office, 1964

No new Bearing Trees scribed.

James W. Byron, Deputy County Surveyor  
Mike Darby and Jim Halterman  
January 1964  
C. S. File No. 53/40