

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 91881

233

George Grubb
For: Ralph Huffman
March 1980
M 79 - 34

1/4 Corner for Secs. 34 and 35.
Set - Brass cap
BT's - A 20" Pine bears S.28°W., 46.9 ft. scribed "1/4 S34 BT" on a double face.
A 26" Cottonwood bears S.36°E., 68.1 ft. scribed "1/4 S35 BT" on a double face. See also Ren. #4

3/80

234

Larry E. Monrean
Deputy - Doug. Co.
Surveyors Office
Karen Reed, Deputy
Karen Mosley, witness
April 21, 1980
C.S. 61/6

Section corner for Secs. 21, 22, 28 and 27.
Found - 1963 County surveyors brass cap properly marked protruding 0.8 ft. above ground. See Ren. #157
An orig. 26" W. Oak, now a 36", bears N.43°W., 36.6 ft. (Rec. N.48°W., 36.3 ft.) (Ren. #157, N.43°W., 37.0 ft.). The orig. blaze has been previously chopped, the 1963 blaze is partially healed with visible scribing.
An orig. 16" W. Oak, now 24" bears N.39°E., 12.8 ft. (Rec. N.39°E. 12.5 ft.) with rotted out orig. blaze and partially healed re-scribe blaze.
A 6" Madrone bears S.16°E., 23.7 ft. measured to DBH of trunk (22.2 ft. DBH to the center of base with partially healed blaze.
A 10" W. Oak, now 11", bears S.59°W., 27.5 ft. with well healed double blaze.
Left cap in position.
New BT - A 12" incense cedar, scribed "T30S R6W S21 CS BT" in a double blaze bears N.48°W., 51.8 ft. dist.

235

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
Debbie Stewart
C.S. 61/19
April 23, 1981

Section corner for Secs. 35, 34, and Secs. 3 & 2 of T.31-6
Found - 1969 County brass cap properly marked. Ren. #200
22" now 23" Oak, S.36°30'E., 70.0 ft. with visible "31S 6W S2 CS BT" showing in rotted face. This tree has been cut into in a search for old scribing and will probably not live.
7" now 12" cedar with well healed double blaze bears N.81°W., 37.6 ft.
23" now 25" Fir with "30 S R6W S34 CS BT" visible in partially healed blaze bears N.15°W., 10.7 ft.
14" now 16" Fir with "31S 6W S3 CS" visible in partially healed blaze bears S.25°W., 40.5 ft.
New BT - 9" Fir bears S.11 1/2°E., 33.8 ft. scribed T31S R6W S2 CS BT in double blaze.

fd. OK 2-94 1994-0012

4/23/81

236

Wm. J Ruppert
OLS 866
June, 1981
See M 87 - 79

Section corner common to Sec's. 11, 12, 13, & 14.
Found - 1 1/2" Pipe with top 12" broken off. Ren.# 205. FOUND at 11-93 BY R.BROWN 1993-0088
24" Maple bears N.34°30'E., 137.0-ft.
24" W. Oak bears S.17°30'W., 58.1-ft.
24" W. Oak bears N.75°W., 205.4-ft.
38" Maple bears S.75°30'E., 133.8-ft.
Set - 7/8" x 26" Iron Rod alongside old pipe.

237

Gregory Quibell,
Deputy, Doug. Co.
Surveyors Office
John Powell, Randy
Smith
Jan. 28, 1983
C.S. 62/7

Township corner, Sec. 6; and Sec. 31, T.29-6; Sec. 36, T.29-7; Sec. 1 T.30-7
Found - 1962 Douglas Co. Surveyors Office brass cap properly marked and firmly set. Ren. #126
1968 BLM brass cap per resurvey properly marked and firmly set with what appears to be the orig. corner stone buried alongside.
DCSO brass cap bears S.23 1/2°E., 1.65 ft. from BLM cap.
Found all accessories as described in 1968 resurvey and 1982 Lloyd Smith survey. (M 93-45)
My measurements to the two remaining original bearing trees from each of the brass caps, plus faint notches on all four edges of the found stone, cause me to accept the position of the BLM brass cap as the proper corner location. I then cut the DCSO brass cap off and drive a yellow nylon cap inside the remaining 1" iron pipe. Cap marked Doug. Co. Surveyor.

1/28/83