

Douglas County Surveyor's Record of
Government Corners Renewed

T 30 T. S. R 6 R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 91981

241

1/4 Corner for Section 25 only. (East)
Found - 1 1/4" O.D. iron pipe, protruding 1" above ground, top is bent 0.4 ft. southwest of a plumb position. Brass cap was mowed off. It is found loose on top of ground along side iron pipe. Ren. #195, 219
12" now 13" dia. W. oak with a fully healed single blaze bears S.24°W., 127.4 ft. (Rec. S.26°W, 127.4 ft.) Ren. No. 195
10" now 15" dia. W. oak with a fully healed single blaze bears S.80°W., 262.6 ft. (Rec. S.82°W, 262.6 ft.) Ren. No. 195
A 1969 DCSO 1 1/4" I.P. (1/4 Cor Sec. 30, T.30S, R5W only) bears South 99.4 ft. (agrees with record) (A new DCSO BC/IP is now at position of found 1 1/4" I.P.)
Set - Previously described 1 1/4" O.D. iron pipe per Ren. No. 195 is referenced to plumb position and removed, iron pipe measures 36" long. A new DCSO 2 3/8" dia. brass cap on a 30 1/2" long 1 1/4" O.D. iron pipe is set and protrudes 1 ft. above ground. BC/IP is set at referenced position. Cap is mkd. "Douglas County Surveyors Office T30S 1/4 S25 R6W | R5W 1989"
New Accessory:
A white metal witness post is set 1 ft north of BC/IP.
Corner lies in open field.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
Jan. 6, 1989
C.S. 62/61

1/6/89

242

1/4 Corner for Sections 10 and 11
Found - 1 1/4" iron pipe found firmly set projecting 12" above ground. Cap stamped: S

T30S
C S12 | S11 O
R6W
1963

Wayne L. Rogers
For: BLM
May 25, 1988
C.S. 63/87

Should be for Section 10 and 11.
Found - Orig. BT. A pine 40" bears S.25°W., 164 lks.. Scribe mark S visible on opened blaze.
A Pine 16" bears S.20°E., 36 1/2 lks. fragmentary scribe marks visible on partially healed double blaze. Ren. #170
A roothole bears N.26°W., 85 lks. with down pine alongside. Scribe marks "1/4 S10 CS BT" visible on open double blaze. Ren.170
New BT - A Pine, 10" bears N.59°W., 46 lks. dist., mkd. 1/4 S10 BT.
Corner located in fence.

RE-RENEWED, SEE CORNER NO. # 243

5/25/88

243

1/4 Cor. for Sections 10 and 11.
Found - A 2 1/2" dia. DCSO brass cap on a 1 1/4" O.D. iron pipe, surrounded by three rocks; I.P. protrudes 17" above ground. Ren. #170
Note: Brass cap is not properly marked - "12" should be a 10.
18" now 40" dia. ponderosa pine with a previously opened blaze, scribe marks visible "S" bears S.23°W., 108.2 ft. (Rec. S.25°W 108.2 ft.) Orig. BT.
14" now 18" dia. Ponderosa Pine with illegible scribe marks visible on a partially healed double blaze, bears S.22°E., 24.4 ft. (Rec. S.20°E., 24.4 ft.) Ren. #170
15" Pine now down and rotted with scribe marks visible on open double blaze "1/4 S10 CS BT" bears N.31°W., 56.5 ft. to root hole. (Rec. N.26°W., 56.5 ft.) Ren. No. 170
10" Ponderosa pine with a single blaze, scribing visible "1/4 S10 BT" bears N.59°W., 30.4 ft. (agrees well with record) Ren. #242
Set - The "2" from the improper 1963 stamping "S12" is stamped out and A "0" and "1989" are added to brass cap.
New BT - 17" dia. Ponderosa Pine fence corner, single blazed and scribed 4 1/2 ft. above ground "1/4 S11 CS BT" bears N.3 1/2°E., 5.6 ft.
Corner lies on a NE-SW ridge that slopes southwest.

Douglas County
Surveyors Office
Randall Smith
Stephen Flause
June 16, 1989
C.S. 62/63

244

1/4 Corner for Sections 21 and 28.
Found - NO MONUMENT IN CAT TRAIL. See Ren #202
12" Madrone dead, with scribe visible bears N35°E, 13.5 ft.
16" Madrone with healed blaze, bears S43°W, 17.2 ft.
New BT's - 19" madrone bears S80°E, 66.0 ft.

Howard Johnstone
LS# 498
September 26, 1989
M 109 - 2