

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 7 R. W. W. M.

The corner for Sections: 13, 24, 19, and 18. *Ps 6 + 7W* 8

I found two original Black Oak BT's; one bearing, South 60° West for 327 Links, which is now a 44" tree. The other bears North 70° East for 70 Links and is now as 38" Black Oak.

I set 3"X3" X 4' Cedar Stake for the corner from the original Bearing Trees, marking it S 13, S24, S7, and S18.

Quarter corner for Sections 24 and 19 on township line. *R6W+ RTW* 9

Found the original Incense Cedar BT, bearing North 20° East for 126 Links. Chopped in and found old scribe markings. This is now a 24" Cedar.

Set a Cedar stake for the $\frac{1}{4}$ corner and marked it $\frac{1}{4}$ S24 and $\frac{1}{4}$ 19.

Quarter corner for Section 23 and 24. 10

Started at the established corner for 13, 14, 23, and 24. Chained South on random for 2640 feet, using a variation of 30° 30' East, and looked thoroughly for the old BTs for this $\frac{1}{4}$ corner, but did not find them; continued on the random line to the South boundary of Section 24, hitting 578' East of the corner for Section 23, 24, 25, and 26.

The correct variation was found to be 14° 18' East. The West side of Section 24 is 5263.0 feet. I set a stake for the $\frac{1}{4}$ corner on correct line at the halfway point or 2681.5 feet south of the NW corner.

Two BTs were marked:

A 9" Fir, bearing North 3° East for 8.0 feet, marked $\frac{1}{4}$ S 24.

A 13" Fir, bearing South 24° West for 39.8 feet, marked $\frac{1}{4}$ S 23.

Quarter corner for Secs. 13 and 24. *#31* 11

I found the original 60" Laurel BT, bearing N 65° E. for 39 lks. Set a 4" X 4" Cedar Stake for $\frac{1}{4}$ corner stake marking it $\frac{1}{4}$ S13 and $\frac{1}{4}$ S24. The other BT has been destroyed.

$\frac{1}{4}$ sec. corner for secs. 35 and 36. 12

Determined by Orig. bearing trees.

A 16" W. O. bears N. 85° W., 15.5' dist. O. B. T.

A 14" B. O. windfall bears N. 70° E., 40.0' dist. O. B. T.

At corner point set 1" X 30" Iron pipe from which

A 14" laurel bears S. 43° E., 46.5' dist. mkd. $\frac{1}{4}$ S 36, B. T.

A 6" W. O. bears N. 67° 30' W., 33.3' dist. mkd. $\frac{1}{4}$ S, B. T.

S.P.R.R. mile post No. 536.53 bears S. 36° W., 13.8' dist.

Section corner 25-26-35-36. 13

A 30" Fir Stump bears S. 67° W., 51.0' dist. O. B. T.

A 40" Fir bears N. 74° W., 47.5'.

A L. O. Stump bears N. 27° E., 8.8'.

A L. O. Stump bears S. 63° E., 9.0'.

At corner point found large pile of stones & scribed post. from which

A 6 inch L. O. bears S. 60° W., 11.1' dist. mkd. T30S, R7W., S36 B. T.

A 9 inch L. O. bears N. 24° E., 9.7' dist. mkd. T30S, R7W., S. 25 B. T.

A 6 inch L. O. bears S. 3° W., 16.0 feet dist. Mkd. T30S, R5W., S35BT.

Claude Kerr - Registered Professional Engineer - June 6, 1953 -
O.S. File # 11/160
John H. Markham Jr.
Witness - W. J. Guse and work done for
Mr. M. J. Guse, Nov. 7, 1953.
Filed in Drawer 41, Div. 254

RE-RENEWED SEE CORNER NO. #31

RE-RENEWED SEE CORNER NO. #113

SEE #15

#84

188'