

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Section Corner to Sections 10 - 11 - 14 - 15.

76

Found - Original BT's. as follows:

- 12", now 11" Laurel N.40°E. 23.2 ft., face rotted, never healed over, now snag.
- 14", now 15" Laurel S.10°E. 10.6 ft., shows faint scribe.
- 14", now 16" Laurel S.60°W. 37.0 ft., shows faint scar.
- 40", now 48" D.Fir N. 65°W. 21.8 ft., recorded as Laurel, shows good scars.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R7W S10 | S11
Office, 1964 S15 | S14

- New BT's: 6" W.Fir N.45°E. 10.4 ft. Mkd: T30S R7W S11 CS BT.
9" D.Fir S.35°E. 9.5 ft., prev. scribed "T30S R7W S14 BT".
16" Laurel S.60°W. 37.0 ft. Mkd: T30S R7W S15 CS BT. (Orig. BT)
8" W.Fir N.27°W. 27.4 ft. Mkd: T30S R7W S10 CS BT.

Also there is a 39" Cedar N.13°E. 38.0 ft., bark scribed previously,
Mkd: S11 T30S R7W BT.

Section Corner to Sections 11 - 12 - 13 - 14

77

Found - Orig. BT's. as follows:

- 48", now 42" Pine Snag S.70°W. 9.2 ft., shows good scribe.
- 36", now 48" Pine, down, N. 85°E. 64.7 ft., shows scribe.
- Bother Oaks gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R7W S11 | S12
Office, 1964 S14 | S13

- New BT's: 7" D.Fir S.15°W. 6.9 ft. Mkd: T30S R7W S14 CS BT.
12" D.Fir S.21°E. 16.8 ft. Mkd: T30S R7W S13 CS BT.
7" D.Fir N.87°E. 20.8 ft. Mkd: T30S R7W S12 CS BT.
No tree close in Section 11.

Fence Corner bears S. 31° E. 5.0 feet with fence going S. and E.

Wit. Corner

78

1/4 Corner to Sections 11 and 14.

Found - Both BT's. & Corner Tree, See Ren. #2, by Briggs, 1892.

- 5" R. Fir Corner Tree, now 16", shows very faint scar, has been used as fence corner.
- 4" D.Fir, now 7" Stump, North 4.6 ft., Cut open & found scribe.
- 5" D.Fir, now 16" Snag S.5°W. 3.3 ft. Cut upen & fd. "B" scribe.
- Fell snag to prevent possible damage to corner.

Set - Brass Cap Wit. Cor. Mkd: County Surveyor's Office, 1964
T30S R7W 1/4 S11 W.C. 4 ft. E.

This Monument is 4.0 ft. W. of Corner S14 Tree.

- New BT's: 20" D.Fir N.51°E. 14.2 ft. Mkd: W. C. 1/4 S11 CS BT.
22" D.Fir S.15°W. 15.7 ft.

1/4 Corner to Sections 11 and 12.

79

Found - 22" Oak Snag S.25°E. 19.8 ft., opened & face rotted off.

- 14" Fir Snag S.25°W. 24.5 ft., Ren. No. 18.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T30S R7W 1/4 S11 | S12

- New BT's: 25" Cedar N.43°W. 39.7 ft. Mkd: 1/4 S11 CS BT.
16" W.Oak N.51°E. 101.7 ft. Mkd: 1/4 S12 CS BT.

1/4 Corner to Sections 2 and 11.

80

Found - Squared Post & BT's. Stumps, as follows:

- 36" D.Fir S.60°W. 4.0 ft., shows good scribe 1/4 S11 & BT scar.
- 8" Fir (rotted remnants) N.15°E. 17.7 ft. Dug "BT" out.

Set - Brass Cap at Cor. Mkd: County Surveyor's T30S R7W 1/4 S 2
Office, 1964 S11

- New BT's: 12" D.Fir N.52°E. 25.6 ft. Mkd: 1/4 S2 CS BT.
9" Live Oak S.30°E. 15.5 ft. Mkd: 1/4 S11 CS BT.

Note - This corner lies on N. slope approximately 150 ft. south
of creek in bottom.

Vernon R. Tracy
Mike Darby and Jack Barnett
August and Sept. 1964
C. S. File No. 53/40

RE-RENEWED, SEE CORNER NO. 114

RE-RENEWED, SEE CORNER NO. #150