

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 30 S. T. S. R. 7 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner to Sections 31 and 32.

109

Found - 1918 GLO Brass Cap, in place, mkd: "1/4 S31/S32".
 Orig. 40" Fir, now Snag, S.15°E. 13.2 ft., scribe visible on log
 on ground.
 Orig. (7)16", now 14" Live Oak, Alive, N.52°W. 10.6 ft., shows scar
 at base of tree.
 New BT"s: 8" D.Fir N.18°W. 10.6 ft. mkd: "1/4 S31 CS BT".
 6" D.Fir S.46°E. 3.5 ft. mkd: "1/4 S32 CS BT".
 This corner lies on westerly edge of top of spur, sloping south.

C.
S.
File
No. 53/46

Witness cor. to E. 1/16 Secs. 21 and 28.

110

Found - 1965 Cadastral brass cap at wit. cor. 13.2 ft. west of true
 cor. point.
 Now 12" W. Fir, S.20°E., 20.5 ft., now dead. Scribe visible.
 Now 21" W. Fir, S.79°E., 27.1 ft., alive "BT" scribe visible
 on unhealed blaze.
 New BT - 10" W. Fir, S.31°W., 72.5 ft. mkd. "WC E 1/16 S28 CS BT"
 Note - Corner lies 5.0 ft. north of small creek.

MARCH 21

Vernon "Ray" Tre
J. Heritage
C.S. File 56/34
July 27, 1973

1/4 Corner, Sections 17 & 16.

7/27/73

111

Found - Orig. Corner tree, now 14" diam. with blaze on west
 12" D. Fir stump 4' high scribed "1/4S S.58°W. (Rec.
 S.46°W.) 4.8 ft. (center to center) Ren. No. 50
 16" (now 20"), fir, S.60°E., 9.6 ft. shows faint blaze.
 12" (now 12") Fir, bears S.44 1/2°W., 23.5 ft.
 Set - Brass cap, set S.40°E., 1.5 ft. from center of
 corner tree mkd. COUNTY SURVEYORS T 30 S. R 7 W

L. E. Monrean
Pete Earle
C.S. 56/39
10/24/73

OFFICE 1/4
1973 S 17 S 16

10/24/73

1/4 Corner for Secs. 1 and 2.

112

Found - 5/8" Iron rod. S.12 1/2°W., 44.6ft. (Not of Record)
 A blazed 12" Alder mkd. with blue keel "26", bears
 N.24°E., 27.4 ft.
 A blazed 16" Alder markings unreadable, bears S.60°W.,
 87.5 ft.
 Set - 5/8" Iron rod by single proportion.

Bruce Rogers
for Strout Realty
M 49 - 53
1/74

1/74

1/4 Corner for Secs. 23 and 24.

113

Found - Unrecorded 1" iron pipe, approx. 5 ft. long driven in the
 ground at the corner point, pipe has been bent by logging
 operations.

I remove pipe and set Brass cap mkd.:

COUNTY SURVEYORS

OFFICE

1974

1/4
S 23 | S 24
T30S | R7W

From which:

9" now 12" Fir, now dead, bears N.3°E., 8.0 ft. with scribing
 "1/4 S24 BT" visible in previously opened face. (Kerr's BT)
 We find no trace of Kerr's SW BT. Ren. #10

This corner lies in recent burn area and all timber has been salvaged.
 There are no living trees near.

New Bearing Objects:

- A boat spike, marked "24" driven in the top of a 24" fir stump
 bears S.16°E., 64.2 ft.
- A boat spike, marked with an "x" driven in the top of a 26"
 fir stump bears S.37 1/2°W., 37.2 ft.
- A boat spike, marked "23" driven in the top of a 14" fir stump
 bears N.74 1/2°W., 33.8 ft.

I also set a steel fence post with survey marker witness sign 1.0 ft.
 north of the corner. Declination 20°E.

2/26/74

Gary Langlitz, County Surveyors office
Peter Earle
Feb. 26, 1974
C.S. 56/43