

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30 T. S. R 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97101

Section corner for Secs. 5 and 4; and Secs. 32 & 33 of T.29 1/2-7 128
 Found - PK nail hole in sandstone scribed "CS +".
 18" cedar, N.71°E., 8.3 ft. (N.54°E., 9.9ft.) down - scribe
 visible.
 21" fir, N.65°E., 21.7 ft. healed. Ren. #34
 36" madrone, S.15°E., 21.1 ft. Rotted face.
 20" pine, S.36°W., 29.7 ft. Healed.
 17" pine, N.20°W., 53.5 ft. Healed.
 Set - 2" brass tablet in concrete grout at PK nail location marked
 "LS 498".

Howard Johnstone
 L.S. \$498
 For: Roseburg
 Lumber Company
 June 29, 1984
 M 97 - 14

1/4 Corner for Sections 4; and Sec. 33 of T.29 1/2-7 129
 Found - Rock, 8" x 6" x 4" exposed marked "1/4".
 24" madrone, N.51°W., 42.2 ft. Rotted face.
 19" madrone, S.19°E., 43.6 ft. Healed
 9" fir, S.35°E., 8.0 ft. Healed
 10" madrone, N.17°E., 16.4 ft. scribe visible. Ren. #40
 Set - 5/8" x 48" Iron rod and alum. cap alongside of rock.

Section corner for Secs. 5, 4, 8 and 9 130
 CORNER REPORT ONLY
 Found - 1975 Cadastral brass cap
 8" fir, N.51°W., (N.53 3/4°W.) 19.1 ft. healed.
 6" fir, N.80°W., (S.81 1/4°W.) 21.9 ft. scribe visible.
 9" fir, N.76°E., (N.83 3/4°E.) 29.4 ft. healed.
 8" fir, S.84°E., (S.81 1/4°E.) 20.5 ft. healed.
 Compass declination 21° east.

Howard Johnstone,
 L.S. #498
 For: Roseburg Lbr.
 Company
 July 26, 1984
 M 97 - 28

1/4 Corner for Sections 30 and 31. 131
 Found - 1918 GLO brass cap and iron pipe.
 50" Pine, N.10°E., 118.8 ft. staub with visible scribe.
 14" Pine, N.17°W., 10.3 scribe visible. See Ren. #99
 11" Fir, S.11°E., 11.4 ft. Snag.
 New BT - 10" fir, S.20°W., 30.3 ft.

Section corner for Secs. 30 and 31; and 25 & 36 of T.30-8 132
 Found - 1918 GLO brass cap iron pipe in mound of stones.
 11" madrone, S.14 1/2°E., 17.2 ft. healed. Ren. #66
 All cedars down and rotten- Slip area
 44" fir, S.75°E., 27.7 ft. staub
 New BTs- 7" fir, N.25°E., 45.8 ft.
 11" fir, S.85°E., 26.4 ft.
 8" fir, S.82°W., 18.2 ft.

1/4 Corner for Secs. 29 and 32 133
 Found - 1918 GLO brass cap and iron pipe.
 23" fir, tall stump, N.54°E., 15.2 ft. healed.
 30" pine snag, S.19°W., 17.2 ft. scribe visible.
 New BT - 8" cedar, S.64°W., 30.5 ft.

Howard Johnstone
 L.S. #498
 For: Roseburg Lbr.
 Company
 Sept. 24, 1984
 M 97 - 50

Center 1/4 Corner for Sec. 32- 134
 Set - 5/8" x 42" iron rod and alum. cap marked "LS 498".
 BTs - 7" fir, N.36°W., 23.5 ft.
 6" fir, S.44°W., 27.8 ft.

1/4 Corner for Section 5 only. (North) (T.31-7) 135 Ren. #102
 Found - 1918 GLO brass cap and iron pipe.
 26" oak, S.66°W., 26.4 ft. face scar.
 14" oak, S.5°W., 26.2 ft. broken stump.
 10" oak, S.38°E., 5.9 ft. down.
 16" fir, S.24°E., 20.6 ft. down.
 No good trees to the south.
 New BT - 8" fir, N.38°E., 14.7 ft.