

Douglas County Surveyor's Record of  
Government Corners Renewed

30 T. S. 8 R. W. W. M.

XXXXXX CHAINED TO TUBES ONE BLOOD

Section corner to sections 25, 26, 35 and 36.  
Set 5/8 inch pipe for section corner from existing bearing trees which are  
in good condition, 6

From which: 59  
A fir, 24 inches, N.36°E., 49.5 feet, Old bearing tree.  
A fir, 20 inches, bears S.60°E., 28.4 feet, Old bearing tree. B.L.M. tag.  
A white fir, 8 inches, bears S.57°15'E., 41.5 feet scribed " S 35 BT ",  
New bearing tree.

R. H. Gee  
Oct. 29, 1956  
C. S. File No.  
42/181.

1/4 corner to section 36, T30S, R8W., and section 1, T31S, R8W.  
Found 2 O. B. T.s:

24 inch Pine, S.25°E., 18 lks. - Rotten snag.  
30 inch Pine, N.60°E., down and rotten. 97  
Set 4 inch x 4 inch x 48 inch D. Fir post.  
Blaze and scribe 2 new B. T.s:  
6 inch W. Fir, N.36°E., 33 lks. mkd. 1/4 S 36 R. E. 2741 B. T.  
16 inch D. Fir, S.24W., 27.5 lks. mkd. 1/4 S 1 R. E. 2741 B. T.

Arthur R. Evans  
Work done for Martin Bros. Box Co.  
April 18 & 19, 1956  
C. S. File No. 42/197.

Section corner to secs. 35 & 36, T30S, R8W., and secs. 1 & 2, T31S, R8W. 8  
Point for corner established by Proportionate measurement, between 1/4 corners.  
Set a 3 inch x 3 inch x 36 inch D. Fir stake.

Blaze and Scribe B. T.s: 80  
10 inch Madrone, S.78 1/2°E., 13.2 feet mkd. T31, R8, S - 1 - R. E. 2741 B.T.  
3 inch D. Fir, S.72°W., 6.2 feet mkd. "X" - B. T.  
8 inch Madrone, N.51°E., 17.9 feet mkd. T30, R8W., S-36, R.E. 2741 B.T.  
7 inch Madrone, N.6°W., 17.2 feet mkd. T30, R8, S-35, R.E. 2741 B.T.

1/4 Section Corner between Sections 23 & 26. 9

The 12" diam. Fir scribed 1/4 S on North face for the 1/4 Corner was  
found but is now a snag. 22  
The 46" diam. Fir BT. is a snag & scribe near obliteration due to fire.  
The 8" diam. Fir BT. is gone.  
Using the 12" diam. Fir Snag scribed 1/4 S on North face as corner, I  
scribe, in the wood, two new B.T.'s. as below:  
27" diam. D. Fir that lies N.01°30'E., 49.7 ft. from the Corner,  
marked 1/4 S BT S23.  
23" diam. D. Fir that lies S.50°00'W. 96.1 ft. from the Corner,  
marked 1/4 S BT S26.

Clifford M. Bryden  
May 7, 1958  
C.S. File No. 42/357

Section Corner to Sections 9, 10, 15, & 16. 10  
Found - All Orig. BT'S: SAME AS # 14

Orig. 16", now 36" Cedar shows faint scribe marks N.28°W. 31.7 ft.  
Orig. 15", now 36" Fir stump, shows good scar at base, I do not  
open. N.28°E. 15.2 ft.  
Orig. 46", now 48" Fir S.36°W. 34.9 ft. shows good bark scribing.  
Orig. 16", now 36" Fir S.76°E. 11.2 ft. shows good bark scribing.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958 S9 S10  
T30S R8W. S16 S15  
New BT's: 10"W. Fir bears S.88 1/2°W. 35.1 ft. scribed S16 T30S R8W CS BT.  
Rescribed Orig., now 36" Cedar N.28°W. 31.7 ft. S9 T30S  
R8W CS BT.  
10"R. Fir bears S.18 1/2°E. 49.5 ft. scribed S15 T30S R8W CS BT.  
8"R, Fir bears N.13°E. 32.8 ft. scribed S10 T30S R8W CS BT.

James W. Byron, Deputy  
M. Godfrey  
S. A. Blouw  
August, 1958  
C.S. File No. 49/108

1/4 Section Corner to Sections 15 & 22. 11  
Found - Orig. 48", now 50" R. Fir Snag N.44°E. 26.4 ft. Shows old  
bark scribing "1/4" & recent bark scribe 1/4 S.  
No Trace of Orig. S. E. BT.

Set Brass Cap at Corner Mkd: 1/4 S15 T30S R8W County Surveyor's  
S22 Office, 1958  
New BT's: 7" R. Fir bears S.16°W. 27.5 ft. scribed 1/4 S22 CS BT.  
8" R. Fir bears N.22 1/2°E. 30.8 ft. scribed 1/4 S15 CS BT.

EO OK - 9/19/6 - DeGroot - M125 - 51