

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 8 W. R.W.W.M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

James W. Byron, Deputy  
Mike Darby & Jim Halterman  
February 20, 1964  
C. S. File No. 53/40

Vernon R. Tracy  
Mike Darby & J. Barnett  
August 1964  
C. S. File No. 53/53

Vernon R. Tracy  
Mike Darby and Jack Barnett  
September 1964  
C. S. File No. 53/67

Section Corner

T30S  
R8W 

B 36	S 31
S 1	S 6

 R7W  
T31S

39

Found - Brass Cap at Cor. & all BT's. as recorded, GLO notes, 1918.  
S. W. Bearing Tree, now rotted stump.  
New BT: 6" R. Fir bears S.29°W. 4.5 feet scribed S1 T31S R8W CS BT.

Find. O.K.  
by H. JOHNSTONE  
DEC. 1981  
M89-79

1/4 Corner to Sec. 36, T30-8W. & Sec. 31, T30-7W.

Found - Brass Cap at Corner 66 ft. south of Table Creek.  
Now 18" Fir S.86 1/2°W. 23.1 ft., shows scars.  
Now 20" Yewwood S.31°E. 33.0 ft., all as recorded, GLO notes, 1918.  
New BT: 22" Fir bears N.71°E. 15.0 ft. scribed 1/4 S31 CS BT.

Find. OK  
by H. JOHNSTONE  
DEC. 1981  
M89-79

40

Section Corner to Secs. 18 & 19, T30-8W. & Secs. 13 & 24, T30-9W.

Found - Squared Post & BT: 15", now 34" D. Fir N.35°E. 39.6 ft., faint  
bark scribe "BT" & other not readable.  
24", now down & rotted D. Fir, S.26°E., 101.6 ft., part of  
old face & axe marks in rotten remnants.  
No trace of Laurel or Chinq. to S.W. & N. W.

41

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964

New BT's: 8" D. Fir N.87°E. 8.8 ft. Mkd: T30S R8W S18 CS BT.  
8" D. Fir N.43°W. 10.0 ft. Mkd: T30S R9W S13 CS BT.  
8" D. Fir S.52°W. 12.4 ft. Mkd: T30S R9W S24 CS BT.  
13" D. Fir S.19°E. 26.7 ft. Mkd: T30S R8W S19 CS BT.

S13	S18
R9W S24	S19 R8W

 T30S

Sec. Cor. to Secs. 7 & 18, T30-8W. & Secs. 12 & 13, T30-9W.

Found - Co. Surv. Brass Cap, 1958, and 3 BT's. as recorded in  
Ren. #6, T30-9W. N. W. BT., down.  
New BT: 12" W. Fir N.71°W. 54.6 ft. Mkd: T30S R9W S12 CS BT.

42

1/4 Corner to Sections 27 and 28.

Found - 9" Cedar Snag (Orig. BT.) N.76°W. 13.2 ft., open & shows "1/4 S" scribe.  
Other BT's. gone completely.

43

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964  
T30S R8W 1/4 S28/S27

New BT's: 26" D. Fir N.68°W. 43.9 ft. Mkd: 1/4 S28 CS BT.  
36" D. Fir S.13°E. 44.4 ft. Mkd: 1/4 S27 CS BT.

Note - This corner lies on steep, west slope with small draw approximately  
100 ft. north & larger draw approx. 175 ft. south.

1/4 Corner to Sections 22 and 27.

Found - Brass Cap & BT's. as recorded in Ren. #16, in 1958.  
Orig. BT. chopped open & appears to be starting to rot.  
New BT: 1/8" D. Fir N. 3° W. 34.2 ft. Mkd: 1/4 S22 CS BT.

44

FD OK - 9/9/66 = DeGroot - M125-51

1/4 Corner to Sections 33 and 34.

Found - Scribed Stone 14" x 12" x 7", no marks of any kind.  
24", now 34" D. Fir (Orig. BT.) S.76°W. 14.5 ft., bark scribe "4S BT".  
11", now 20" Laurel (Orig. BT.) S.67°E. 25.7 ft., out & laying over

45

Set - Brass Cap at Cor. Mkd: County Surveyor's Off. 1964 rock ledge.  
T30S R8W 1/4 S33/S34 #156

New BT's: 25" D. Fir N.44°E. 62.9 ft. Mkd: 1/4 S34 CS BT.  
25" D. Fir S.34°W. 35.8 ft. Mkd: 1/4 S33 CS BT.

Note - This corner lies at top of rock bluff approx. 30 ft. high.  
Brass Cap set in a mound of stone.

1/4 Corner to Sections 9 and 16.

Found - Cedar Stub N.28°W. 11.9 ft., no scribe.  
40", now 36" Cedar, laying in creek bottom, shows partial scribe  
& axe marks on what is left of overgrowth. This tree fell  
& slid into creek, hole S.68°W. approx. 30 ft.

46

(continued over)