

Douglas County Surveyor's Record of
Government Corners Renewed

T. 30 S. T. S. R. 8 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

70

Sec. Corner to Sections 17 - 18 - 19 - 20.

Found - Orig. 10" Oak N.74°E. 20.5 ft., no scribe found. Tree down & out of position.

Orig. 12", now 22" Laurel S.11°E. 38.9 ft., alive. We open & find "O T" scribe.

Orig. 12", now 16" Laurel S.44°W. 38.9 ft., down, open & find old face & fragmentary reverse scribing.

Orig. 15", Oak N.10°W. 42.9 ft., down & badly rotted, out of position, no scribing.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

S 18	S 17	T30S
S 19	S 20	R8W

New BT's: 15" W.Fir N.59°W. 9.6 ft. Mkd: T30S R8W S18 CS BT.

20" Cedar N.11°E. 31.5 ft. Mkd: T30S R8W S17 CS BT.

15" W.Fir S. 1°E. 19.0 ft. Mkd: T30S R8W S20 CS BT.

9" D.Fir S.31°W. 23.0 ft. Mkd: T30S R8W S19 CS BT.

V. "Ray
Tracy
&
M. Darby
T. Connell
July
1965
C.S.
File
No. 53/67

71

Section Corner to Sections 16 - 17 - 20 - 21.

Found - Orig. 16", now 26" Laurel N. 14° E. 61.4 ft., open & shows "BT" scribe in very poor condition.

Orig. 14", now 19" Pine S. 37° E. 66.0 ft., shows scar. (This tree down and out of place.)

Find rotted remains of N. W. & S. W. BT's.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

S 17	S 16	T30S R8W
S 20	S 21	

New BT's: 11" D.Fir N.71°E. 13.6 ft. Mkd: T30S R8W S16 CS BT.

6" D.Fir N.76°W. 8.7 ft. Mkd: S17 CS BT.

21" Pine S.67°W. 13.5 ft. Mkd: T30S R8W S20 CS BT.

6" W.Fir S.81°E. 29.3 ft. Mkd: S21 CS BT.

Fd 8224 BTs
1976 - BLM ADMIN
SURVEY - SEE
GIS FILE

Vernon "Ray" Tracy
Mike Stone
September 1965
C. S. File No. 53/67

72

1/4 Corner to Sections 22 and 23.

Found - Orig. 12", now 26" Chinq. N.56°W. 2917 ft. to face. Open & found "4" reverse scribe, face rotted, BT is alive.

Orig. 20", now 27" Fir N.25°E. 22.4 ft. to face. Bark scribe "1/4 BT", now Snag 15.0 ft. high, badly rotted.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

T30S R8W 1/4	S 22/S 23
--------------	-----------

New BT's: 14" D.Fir East 12.5 ft. Mkd: 1/4 S23 CS BT.

12" D.Fir S.68°W. 14.3 ft. Mkd: 1/4 S22 CS BT.

Note - This corner lies on top of rolling ridge top.

73

1/4 Corner to Sections 7 and 18.

Found - Orig. 13", now 20" Fir N.10°W. 9.2 ft. to face, shows old bark scribe "1/4 BT" in very poor condition.

Orig. 12", now 32" Fir S.38°W. 19.8 ft. to face, shows fragmentary bark scribe "1/4 S".

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

T30S R8W 1/4	S 7
	S 18

New BT's: 36" D.Fir N.61°E. 13.9 ft. Mkd: 1/4 S7 CS BT.

13" D.Fir S.24°W. 32.9 ft. Mkd: 1/4 S18 CS BT.

Note - This corner lies on a N. E. slope of spur, course N. W.

74

Section Corner to Sections 7 - 8 - 17 - 18.

Found - Orig. 15", now 30" Fir N.15°E. 14.5 ft., shows frag. bark scribe, BT is alive.

Orig. 12", now 15" Fir S.58°E. 48.2 ft., shows bark scribe in poor condition. BT is alive.

Orig. 16", now 26" Fir S.25°W. 38.3 ft., shown as S.35°W., shows bark scribe in fair condition. BT Alive.

Orig. 46", now 46" Fir Snag N.50°W. 25.1 ft., no scribe found, bark gone.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965

T30S R8W	S 7	S 8
	S 18	S 17

New BT's: 9" Chinq. S. 70° W. 5.3 Mkd: T30S R8W S18 CS BT.

7" Chinq. N. 2° W. 31.7 ft. Mkd: T30S R8W S7 CS BT.

6" W.Fir N. 71° E. 40.7 ft. Mkd: S8 CS BT.

11" Hemlock S. 78° E. 37.5 ft. Mkd: T30S R8W S17 CS BT.

RE-NEWED

75