

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 30 S. T. S. R. 8 W. R. W. W. M.

1/4 Corner to Sections 20 and 21.  
Found - Orig. 8", now 12" Oak, alive, S. 80°W. 9.7 ft., blaze open & axe marks, no scribe.  
Orig. 8", now 16" Oak, down, S. 54°E. 8.6 ft., open & scribe visible.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1969 T 30 S R 8 W S 20 S 21  
New BT's: 6" D. Fir S. 72°E. 23.5 ft. mkd: "1/4 S21 CS BT".  
12" D. Fir S. 50°W. 21.8 ft. mkd: "1/4 S20 CSBT".

This corner lies on moderate southerly slope, spring bears S. 20°W. 62'  
9/17/69

93

Section cor. of sec. 34 and 35 only, T29S R8W.  
Found - 40" D. Fir, now down, rotten, N. 80°E. 13.9 ft.  
20" D. Fir, now 27", S. 43°E. 30.4 ft. Bark scribe visible "8W2".  
30" D. Fir, now down, rotten, S. 55°W. 4 ft.  
15" Cedar, now down, N. 30°W. 8.6 ft.

Set - Brass cap at cor. mkd: County Surveyor's Office 1970 T29S R8W S 34/S 35 T30S S 2

New BT's - 26" D. Fir N. 25°W. 20.2 ft. Scribed: T29S R8W S34 CS BT.  
8" W. Fir N. 39°E. 21 ft. Scribed: T29S R8W S35 CS BT.

Reblazed and Rescribed:  
27" D. Fir S. 43°E. 30.4 ft. scribed: T30S R8W S2 CS BT.

Note - This cor. lies approx. 230 ft. East of 34/213 2/9/70

94

Section cor. of sec. 3 and 2 only, T30S R8W.  
Found - 40" D. Fir, Now 47", N. 42°E. 21.1 ft. Bark scribe visible "T, W, B."  
10" Laurel, now down, S. 54°E. 15.8 ft. This probable BT has very old "X" on it, however, out of ground & down hill from where it should be. No trace of SW BT.

Set - Brass cap at cor. mkd: County Surveyor's Office 1970 T29S R8W S 34 T30S S 3/S 2

New BT's - 6" Cedar N. 4°E. 32.8 ft. Scribed T29S R8W S34 CS BT.  
13" Cedar S. 75°E. 31.7 ft. Scribed T30S R8W S2 CS BT.  
35" D. Fir S. 2°W. 11.5 ft. Scribed T30S R8W S3 CS BT.

Note - This cor lies approx. 230 ft. West of 34/35. 2 2/9/70

95

Section Corner to Sections 7 - 8 - 17 - 18.  
Found - 1965 County Surveyor Brass Cap, properly marked, See Ren. #74.  
9" Chinquapin, now stob, S. 70°W. 5.3 ft., no scribe, tree gone.  
7", now 9" Chinquapin, N. 2°W. 31.7 ft., scribe visible.  
6", now 6" W. Fir, N. 71°E. 40.7 ft., scribe visible.  
11", now 11" Hemlock, S. 78°E. 37.5 ft., scribe visible, "T30S R8W S18 CS BT". (This tree is in Section 17)

Renewal, Reblzd. & Rescribed:  
11" Hemlock S. 78°E. 37.5 ft. scribed T30S R8W S17 CS BT.  
New BT: 22" Hemlock S. 70°W. 22.9 ft. scribed T30S R8W S18 CS BT.

9/10/70

96

Sec. Cor. to Secs. 35 & 36, T30-SW. & Secs. 1 & 2, T31-SW.  
Found - 5", now 5" D. Fir, S. 14 1/2°W. 19.8 ft., pitched over scribe. Ren. #80.  
8", now 8" Laurel N. 6°W. 17.2 ft., scribe visible.  
12", now 12" Laurel, S. 78 1/2°E. 13.2 ft., scribe visible.  
9", now 9" Laurel, N. 51°E. 17.9 ft., scribe visible.

Also found Brass Cap, out of ground.  
Reset - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 T30S R8W S35/S 36 T31S R8W S 2/S 1

New BT's: 7" D. Fir S. 83 1/2°E. 23.4 ft. scribed "T31S R8W S1CSBT".  
6" D. Fir N. 19°E. 17.0 ft. scribed "T30S R8W S36 CS BT".

3/31/71

*Fd. BC #4 BTs  
1976 - BLK  
ADMIN. SURVEY  
SEE GIS FILE*

John M. Powell  
Frank Jones & W. Penley  
C.S. File No. 54/38

*FD. OK  
1-10-80  
M79-15  
N. JOHNSTONE*

John M. Powell  
Penley & Heritage  
C.S. File No. 53/67

*Fd. O.K. by  
H. JOHNSTONE  
DEC-1981  
M 89-79*

J.M. Powell  
& Crew  
C.S. File  
No. 53/67