

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 30 S. T.S. R. 8 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Howard Johnstone
L.S. 498
For: Rsbg.Lbr.Co.
June 30, 1982
M 92 - 52

Center 1/4 of Sec. 26.
Set - 5/8" x 24" I.R. & alum. cap, mkd: LS 498.
New BTs- 8" fir bears S.20°W., 17.6-ft. (scribed).
5" fir bears S.59°E., 26.3-ft. (scribed).

133

Gregory Quibell
Deputy, Doug. Co.
Surveyors Office
John Powell
Randy Smith
Dec. 13, 1982
C.S. 62/1

Section corner for Secs. 30 and 31; and Secs. 25 & 36 of T.30-9
Found - 1" x 30" Iron pipe with properly marked 1968 County brass cap attached, standing loosely approx. 4" in the ground. Ren. #89
Orig. 15" now 28" fir bears N.43°W., 24.4 ft. (Rec. N.47°W.) with pitched over previously opened blaze.
Orig. 30" now 54" fir with scribed "BT" in previously opened blaze. Alive. Did not take bearing & dist. Since it would have required cutting many trees out of line of sight and I had 6 other BTs close to corner.
Orig. 15" now 32" pine with pitched over previously opened blaze bears N.28°E., 57.4 ft. (Rec. N.25°E.)
9" fir now 10" with well healed single blaze bears S.52°E., 16.2 ft
11" W. oak with scribed "S R8W S30 CS BT" in partially healed blaze bears N.65°E., 33.6 ft. (Rec. 34.2 ft.) Ren. #89
8" now 9" W. oak with scribed "T30S R9W S25 CS BT" bears N.10°W. 30.0 ft. Ren. #89
8" now 10" fir with well healed single blaze bears S.82°W., 26.6 ft
Root hole and rotted remains of possible orig. 5" oak with no scribing or face visible. Root hole bears S.22°E., 6.4 ft. (Rec. S.10°E., 5.9 ft.)
Set - Since the location I found the brass cap at, fit all the trees well I reference its location and reset the pipe 24" into the ground and add the marks "Reset 1982" to the cap.
Blaze line runs north from corner to road 30-9-24.1

134

12/13/82

Randall W. Smith, Deputy
Douglas County Surveyors Office
Stephen J. Flause
February 27, 1984
C.S. 62/16

*FDOK D. Edwards
2/2005
CS 65/55-1
Set 6' post
2' North*

Sec. Corner for Secs. 26, 27, 34, & 35. Ren.#60.
Fnd. -- I.P. w/County B.C. as per Ren.#60.
BTs - 46" D.Fir N.84°E, is down w/a visible blaze showing.
30" D.Fir, now a 30" diam. 12-ft.high snag bears N.46°W.(Rec. is N.43-1/4°W.) 20.6-ft. (Rec. 19.5-ft. is to face). A healed single blaze has a partial scribing visible.
24" D.Fir, now a 24" diam. 8-ft. high stump bears S.19°W., 20.1-ft. (Rec. 19.6-ft.) partially healed blaze has some scribing visible: "S R R E 2 7 4 BT".
33" D.Fir, now a 33" diam. 24" high stump, bears S.42-1/2°E., 81.9-ft. (Rec. 80.7-ft. is to face).
New BTs- 11" W.Fir dbl.blazed & scribed: "T30S R8W S26 CS BT" bears N.42-1/2°E., 5.9-ft.
6" W.Fir, dbl.blazed & scribed: "T30S R8W S27 CS BT" bears N.42°W., 29.0-ft.
10" W.Fir, dbl.blazed & scribed: "T30S R8W S34 CS BT" bears S.88°W., 55.0-ft.
New BO - Set a 1/2" x 8" spike in a 33" D.Fir stump, which bears S.42-1/2°E. 81.9-ft. Spike is set through a DCSO bearing tree tag in top of stump.(stump is a BT per Ren.#5) Spike is stamped BO 1.
See sketch in file.

135

2/84

Howard Johnstone
L.S. #498
For: Roseburg Lumber Co.
July 26, 1984
M 97 - 28

Section corner for Secs. 25 and 36; and Secs. 30 & 31 of T.30-7.
Found - 1918 GLO brass cap and iron pipe in mound of stones.
11" madrone, S.14 1/2°E., 17.2 ft. Healed. Ren. #35
All cedars down and rotten - Slip area.
44" Fir, S.75°E., 27.7 ft. Staub.
New BTs- 7" fir, N.25°E., 45.8 ft.
11" fir, S.85°E., 26.4 ft.
8" fir, S.82°W., 18.2 ft.

136

7/26/84

Howard Johnstone
For: Roseburg
Resources
November, 1988
M 101 - 44

1/4 Corner for Section 7; and Sec. 12 of T.30-9
CORNER REPORT ONLY. (1988 BLM survey, not filed yet)
Found - 1988 CAD BCIP mkd. 1/4 S12/7
10" fir, N.12°W., 5.6 ft. scribe visible
12" fir, N.60°E., 20.8 ft. scribe visible.

137

11/88