

Douglas County Surveyor's Record of  
Government Corners Renewed

30

T. S.

8

R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 31881

1/4 Cor. Secs. 7 & 18

154

Douglas Co.  
Surveyors Office  
Stephen J. Flause  
John Pike  
4/16/2007  
C.S. 67/21-26

Found - 2½" dia. brass cap, properly mkd on 1¼" O.D. IP projects 14" above ground, firmly set.  
13" now 18" dia., D.Fir fully haled single blaze visible bears S.15½°W., 32.9 ft (rec S.24°W., 32.9 ft) 1965 BT REN #73- Appears 1965 crew read wrong side of compass needle?  
36" now 42" dia. D.Fir snag, fully healed single blaze visible bears N.61°E. 13.1 ft (Rec. N.61°E., 13.9 ft.) 1965 BT  
Both orig. trees have blown down years ago. Root holes check well for rec. bearing & dist.

WC 1/4 Corner Secs. 18 & 19

155

Douglas Co.  
Surveyors Office  
Stephen Flause  
John Pike  
4/24/2007  
C.S. 67/21-31

Found - 44" dia. Cedar corner tree now 46" dia. x 2 ft tall hollowed out stump.  
2½" dia., brass cap (properly mkd) on 1¼" O.D. IP, projects 12" above ground & bears East 10.0 from center of tree stump. Firmly set  
11" now 12" dia., x 6" tall very rotted Hemlock stump, bears S.5°E., 19.8 ft. (Agrees w/rec; 1965 BT referencing witness corner)  
8" Hemlock now gone, 1965 BT. *Ren # 69*  
46" now 46" dia., x 3 ft. tall rotted fir stump bark gone from face shows burl wood, bears N.19°W., 30.4 ft. center to center. We meas. 28.4 ft from edge of corner tree to center of BT, from face to face we meas. 27.0 ft. (Rec. N.26°W., 28.4 ft.)  
27" cedar (OBT) now down & rotted, bark gone, no marks visible. Root hole agrees ok w/rec. (S.40°E., 17.8')

New - To reference WC  
15" dia., G.Fir double blazed & scribed "WC ¼ S18 CS BT" bears N.43°E., 7.3 ft.  
7" dia., D.Fir double blazed & scribed "WC ¼ CS BT" bears N.68½°W., 19.3 ft.  
9" dia., G.Fir double blazed & scribed "WC ¼ CS BT" bears S.8½°E., 17.6 ft.  
8" dia., D.Fir double blazed & scribed "WC ¼ CS BT" bears S.24½°W., 36.6 ft.

Note - Lies on gentle N facing slope of young trees. Compass decl. 16¼°E.