

Douglas County Surveyor's Record of
Government Corners Renewed

30 T. S. 9 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

1/4 Corner common to Sections 13 and 14. 52 18
Found - 18" D. F. S.87°E. 36.3 ft., now 40". Scribe visible.
Set - Corner falls in area of proposed road reconstruction
therefor an iron pipe was not set at this time.
7" D. Fir N.73°W. 94.3 ft.
20" Cedar N.73°E. 113.7 ft.

Howard W. Johnstone
For Roseburg Lumber Co.
Jan. 7, 1961
C. S. File No. 51/163

Section Corner common to Sections 13, 14, 23 and 24. 19
Found - 15" Fir N.52°W. 38.4 ft., now 25", bark scribe.
6" Cedar N.77°E. 15.8 ft., now 23". 101
Set - 1" x 24" Iron Pipe
16" W. Fir S.73 1/2°E. 46.8 ft.
6" W. Fir S.15°W. 47.3 ft.

1/4 Corner common to Sections 14 and 23. 20
Found - 6" Chinquapin N.60°W. 29.0 ft. (dead) #168
38" D. Fir S.66°W. 7.9 ft. (now stump, scribe in good
condition)
Set - 1" x 30" Iron Pipe
17" Doug. Fir N.10°E. 93.5 ft.

Howard W.
Johnstone
For Roseburg
Lumber
C.S. 51/163

September 15, 1961

1/4 Corner between Sections 3 and 2. 21
Found - 14" Fir N.70°E. 33 lks. (now a 26" High Stump)
8" Fir N.70°W. 7 lks. (down, scribe visible)
Scribed New BT's:
12" Fir S.87°E. 29.5 ft.
8" Cedar N.23°W. 13.0 ft.
Set - 1" x 30" Iron Pipe 24" in ground. 36

Howard W.
Johnstone
For Rsborg.
Lumber
C. S. File No.
51/163

October 12, 1961

1/4 Corner between Sec. 13, T30-9W. & Sec. 18, T30-8W. 22
Found - W. Oak S.35°W. 45.5 ft. (down, no visible scribing)
12" W. Oak N.42°E. 23.8 ft. (down, scribe visible)
Set - 1" by 36" Iron Pipe
Scribed - 16" D. Fir S.43°W. 40.0 ft.
6" D. Fir N.55°E. 9.7 ft.

Howard W.
Johnstone
For Roseburg
Lumber Co.
C.S. File
No. 51/163

May 28, 1962

FD. OK 6/88
M 106-51
H. Johnson

Section Corner to Secs. 21 - 22 - 27 - 28. 23
Found - 3 Orig. BT's: Orig. 11", now 14" Hemlock N.26°W. 48.8 ft.,
now snag, shows good scribing.
Orig. 20", now down 36" Hemlock N.32°E. 14.0 ft. #160
Orig. S.W. BT. not found. FD. OK 7/27/93
Orig. 22" W. Fir, now 16" Snag, shows good scribing.
Rock as recorded at corner.

Set - Brass Cap alongside Cor. Stone Mkd: County Surveyor's S21/S22
Office, 1962 S28/S27
New BT's: 20" R. Fir bears S.17°E. 26.4 ft. scribed S27 T30SR9W CS BT.
7" Hemlock bears N.67°W. 87.2 ft. scribed S2 CS BT.
48" Fir bears S.54°W. 27.7 ft. bark scribe T30SR9WS28CS BT.
5" Hemlock bears N.74°E. 67.3 ft. scribed S22 CS BT.

James W. Byron, Deputy Co. Surv.
Mike Darby, Wm. Stoffel & Jim Combs
Dec. 4, 1962
C.S. 49/100

1/4 Corner to Sections 21 and 22. 24
Found - Orig. 16", now 30" Fir S.60°W. 56.1 ft., shows good scar.
Orig. 38", now 48" Fir Stump, shows good scribing "1/2 S" on old face.
Do not find stone at cor. which is in toe of rock road fill.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
1/4 S21/S22 T30S R9W

New BT's: 16" R. Fir bears S.82 1/2°W. 102.8 ft. scribed 1/4 S21 CS BT.
24" R. Fir bears S.38°E. 90.5 ft. scribed 1/4 S22 CS BT.
Note - Corner is on steep West Slope and 40 ft. West of logging Road.

(C. & D. Lumber Co.)